

AIRCO WELDING PRODUCTS -- GMAW WIRE,TYPE A5356 -- 3439-00-803-9491

=====
Product Identification
=====

Product ID:GMAW WIRE,TYPE A5356

MSDS Date:01/01/1987

FSC:3439

NIIN:00-803-9491

MSDS Number: BFQCR

=== Responsible Party ===

Company Name:AIRCO WELDING PRODUCTS

Emergency Phone Num:(201)464-8100

CAGE:83923

=== Contractor Identification ===

Company Name:AIRCO WELDING PRODUCTS DIV OF THE BOC GROUP I
NC.

Address:4437 E 49TH STRRET

City:CLEVELAND

State:OH

ZIP:44125-1005

Country:US

Phone:216-641-8790

CAGE:83923

Company Name:KEEN MFG INC

Address:243 N LINCOLN AVE

Box:1006

City:SALEM

State:OH

ZIP:44460

Country:US

Phone:216-332-4509

CAGE:65493

=====
Composition/Information on Ingredients
=====

Ingred Name:ALUMINUM (SARA III)

CAS:7429-90-5

RTECS #:BD0330000

Fraction by Wt: 94%

OSHA PEL:15MG/M3 DUST/5 FUME

ACGIH TLV:10MG/M3 DUST; 9192

Ingred Name:MAGNESIUM

CAS:7439-95-4

RTECS

#:OM2100000
Fraction by Wt: 5%

Ingred Name:CHROMIUM (SARA III)
CAS:7440-47-3
RTECS #:GB4200000
Fraction by Wt: 0.1%
OSHA PEL:1 MG/M3
ACGIH TLV:0.5 MG/M3; 9192
EPA Rpt Qty:1 LB
DOT Rpt Qty:1 LB

Ingred Name:MANGANESE (SARA III)
CAS:7439-96-5
RTECS #:OO9275000
Fraction by Wt: 0.1%
OSHA PEL:(C) 5 MG/M3 DUST
ACGIH TLV:5 MG/M3 DUST 9293

=====
Hazards Identification
=====

Effects of Overexposure:DIZZINESS,NAUSEA,OR DRYNESS OR IRRITATION OF
NOSE,THROAT,OR EYES

=====
First Aid Measures
=====

First Aid:INHALE:REMOVE TO FRESH AIR, GIVE CPR/O*2 IF NEED;EYES:FLUSH W
LG AMTS H*20 FOR 15 MIN;SKIN:FLUSH W LG AMTS H*20;INGEST:RINSE
MOUTH.

=====
Fire Fighting Measures
=====

Extinguishing Media:EXTINGUISH WITH AGENT SUITABLE FOR SURROUNDING FIRE
Unusual Fire/Explosion Hazard:WELDING ARC AND SPARKS CAN IGNITE
COMBUSTIBLE PRODUCTS

=====
Accidental Release Measu
res
=====

Spill Release Procedures:CLEAN UP ANY GRINDING DUST OR WASTE RESIDUE
AND PLACE IN SUITABLE DOT APPVD DISPOSAL CONTAINER.

=====
Handling and Storage
=====

Other Precautions:WELD IN WELL VENTILATED AREA.AVOID INHALATION OF
WELDING FUMES.AVOID ELECTRICAL SHOCK BY MAINTAINING DRY WORK AREA.

=====
Exposure Controls/Personal Protection
=====

Respiratory Protection:FUME RESP.OR AIR SUPPLIED RESP.IN CONFINED
SP

ACES.
Ventilation:MECHANICAL (GENERAL) ACCEPTABLE LOCAL EXHAUST IF NEEDED.
Protective Gloves:WELDER'S GLOVES
Eye Protection:FACE SHLD W.FILTER LENS.
Other Protective Equipment:APRON,LEGGINGS,BOOTS,CAPES,SHOULDR
COVERS-SEE SUPPL.DATA-
Supplemental Safety and Health
MSDS DATED 11-15-79/HAZ.DECOMP:IN ARC WELDING SLIGHT NO*2,AND
OZONE/OTHER PROTECTIVE EQUIPMENT;HARD HAT,SCREENS,LOW REFLECTIVITY
WALLS OR BOOTHS/

===== Physical/Chemical Properties =====

HCC:N1

Appearance and Odor:ELECTRODE,WELDING

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES
NONE

Hazardous Decomposition Products:FUME OF METALS&METAL OXIDES
INCLUD.BASE MTL&COATNG-SEE SUPPL

===== Disposal Considerations =====

Waste Disposal Methods:DISPOSE IAW LOCAL,STATE & FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated
for use by elements of the Department
of Defense. The United States of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document should seek competent professional advice to verify and
assume responsibility for the suitability of this information to their
particular situation.