View NSN Online: https://aerobasegroup.com/nsn/7930-01-014-5066

DOALL COMPANY -- GAGE BLOCK CLEANER, AEROSOL -- 7930-01-014-5066
========== Product Identification ==========

Product ID:GAGE BLOCK CLEANER, AEROSOL
MSDS Date:05/04/1990
FSC:7930
NIIN:01-014-5066
MSDS Number: BMCDV
=== Responsible Party ===
Company Name:DOALL COMPANY
Address:254 N LAUREL AVE
City:DES PLAINES
State:IL
ZIP:60016
Country:US
Info Phone Num:708-803-7331
Emergency Phone Num:708-803-7262
CAGE:026
37
=== Contractor Identification ===
Company Name:DOALL CO
Address:254 NO LAUREL AVE
Box:City:DES PLAINES
State:IL
ZIP:60016
Country:US
Phone:847-803-7366
CAGE:18056
Company Name:DOALL COMPANY
Address:254 N LAUREL AVE
City:DES PLAINES
State:IL
ZIP:60016-4321
Country:US
CAGE:02637

========== Composition/Information on Ingredients ==========

Ingred Name:TRICHLOROETHANE
CAS:71-55-6
RTECS #:KJ2975000
Fraction by Wt: 70.0%
Other REC Limits:NONE SPECIFIED
OSHA PEL:350 PPM
ACGIH TLV:350 PPM
E

PA Rpt Qty:1000 LBS
DOT Rpt Qty:1000 LBS
Ozone Depleting Chemical:1

Ingred Name:PROPANE
CAS:74-98-6
RTECS #:TX2275000
Fraction by Wt: 15.0%
Other REC Limits:NONE SPECIFIED
OSHA PEL:1000 PPM
ACGIH TLV:ASPHYXIANT

Ingred Name:ISOBUTANE
CAS:75-28-5
RTECS #:TZ4300000
Fraction by Wt: 14.0%
Other REC Limits:NONE SPECIFIED
OSHA PEL:1000 PPM
ACGIH TLV:ASPHYXIANT

Ingred Name:METHYL OLEATE
CAS:112-62-9
RTECS #:RK0895000
Fraction by Wt: 1.0%
Other REC Limits:NONE SPECIFIED
OSHA PEL:15 MG/M3 TDUST
ACGIH T
LV:10 MG/M3 TDUST; 9293

========== Hazards Identification ==========

LD50 LC50 Mixture:ORAL LD50 RAT 10 G/KG
Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:INHALATION: BREATHING DIFFICULTY. EYE CONTACT: IRRITATION. SKIN CONTACT: DEFATTING AND/OR IRRITATION. SKIN ABSORPTION: NOT EXPECTED TO OCCUR. INGESTION: NAUSEA AND/OR DIARRHEA.

========== First A

id Measures ==========

First Aid:INHALATION: REMOVE PERSON TO FRESH AIR. IF NECESSARY, SUPPORT BREATHING. GET MEDICAL ATTENTION. EYE CONTACT: FLUSH WITH WATER FOR 15 MINUTES. IF IRRITATION PERSISTS, GET MEDICAL ATTENTION. WASH EXPOSE D AREA WITH MILD SOAP AND WARM WATER ONLY. DO NOT USE HARSH SOAP OR SOLVENT. GET MEDICAL ATTENTION. SKIN ABSORPTION: GET MEDICAL ATTENTION. INGESTION:KEEP PERSON WARM AND QUIET. GET MEDICAL ATTENTION.

========== Fi
re Fighting Measures ==========

Flash Point:ND
Lower Limits:1.9
Upper Limits:9.5
Extinguishing Media:CARBON DIOXIDE, FOAM OR DRY CHEMICAL.
Fire Fighting Procedures:WATER STREAM OR SPRAY TO COOL CONTAINERS TO PREVENT VAPOR FORMATION AND IGNITION MAY SPREAD FIRE. FOG NOZZLES ARE PREFERRED IF WATER IS USED. WEAR SCBA
Unusual Fire/Explosion Hazard:AEROSOL CANS WILL RUPTURE EXPLOSIVELY ON OVERHEATING.

========== Accidental Release Measures ==========

Spill
Release Procedures:SMALL SPILLS: USE ABSORBENT MATERIAL. LARGE SPILLS: REMOVE IGNITION SOURCES. VENTILATE & LEAVE AREA. RE-ENTER WITH SCBA GEAR & MOP WITH SOAP & WATER. ALLOW RESIDUE TO EVAPORATE.

========== Handling and Storage ==========

Handling and Storage Precautions:STORE DRY IN A CLOSED CONTAINER IN A COOL PLACE AWAY FROM ANY FIRE SOURCE. DO NOT INGEST. AVOID BREATHING VAPOR.
Other Precautions:DO NOT SMOKE WHILE USING OR USE NEAR AN OPEN FLAME.

========== Exposure Controls/Personal Protection ==========

Ventilation:GENERAL MECHANICAL VENTILATION SHOULD BE ADEQUATE. PROVIDE LOCAL VENTILATION IF VAPOR BUILDUP BECOMES EXCESSIVE.
Protective Gloves:NEOPRENE GLOVES IMPERMEABLE TO OIL
Eye Protection:SAFETY GOGGLES OR FACE SHIELD
Other Protective Equipment:AN EMERGENCY SHOWER AND EYEWASH SHOULD BE AVAILABLE IN WORK AREA.
Work Hygienic Practices:PRACTICE REASONABLE PERSONAL HYGIENE. WASH EXPOSED SKIN WITH MILD SOAP AND WAR

M WATER ONLY. OIL-SOAKED
CLOTHING SHOULD**
Supplemental Safety and Health
**BE CHANGED PROMPTLY AND WASHED BEFORE RE-WEARING.

RCRA DEF
INITION: AS RECEIVED, THIS PRODUCT DOESNOT MEET THE RCRA DEFINITION
OF A HAZARDOUS WASTE MATERIAL.

========== Physical/Chemical Properties ==========

Vapor Pres:80.0 @140F
Vapor Density:>1
Spec Gravity:0.950
Evaporation Rate & Reference:>1 (BU AC=1)
Solubility in Water:INSOLUBLE
Appearance and Od
or:COLORLESS LIQUID, SOLVENT ODOR.

========== Stability and Reactivity Data ==========

Stability Indicator/Materials to Avoid:YES
STRONG OXIDIZERS.
Stability Condition to Avoid:AVOID OPEN FLAMES AND HOT SURFACES.
Hazardous Decomposition Products:OXIDES OF CARBON, AND CHLORINE
COMPOUNDS.

========== Disposal Considerations ==========

Waste Disposal Methods:TREAT AS AN OILY WASTE AND DISPOSE OF IN
ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS
.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department
of Defense. The United States of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document should seek competent professional advice to verify and
assume responsibility for the suitability of this information to their
particular situ

ation.