

DEXTER HYSOL AEROSPACE INC DIV OF EXTER CORP -- EA 934 NA PART B -- 8040-00-016-8662
===== Product Identification =====

Product ID:EA 934 NA PART B

MSDS Date:05/01/1993

FSC:8040

NIIN:00-016-8662

Kit Part:Y

MSDS Number: BCVKB

=== Responsible Party ===

Company Name:DEXTER HYSOL AEROSPACE INC DIV OF EXTER CORP

Address:2850 WILLOW PASS ROAD

Box:312

City:PITTSBURG

State:CA

ZIP:94565-3237

Country:US

In

fo Phone Num:510-458-8000

Emergency Phone Num:510-458-8000

Preparer's Name:MSDS DEPARTMENT

CAGE:33564

=== Contractor Identification ===

Company Name:DEXTER CORPORATION ADHESIVE & COATING SYSTEMS

Address:2850 WILLOW PASS ROAD

Box:312

City:BAY POINT

State:CA

ZIP:94565-3299

Country:US

Phone:202-483-7616

CAGE:33564

===== Composition/Information on Ingredients =====

Ingred Name:NO INGREDIENT FOR THIS FORMULATION_INGREDIENT

===== Hazards Identification =====

=====

LD50 LC50 Mixture:ORAL, RAT LD50= >1080 MG/KG DET
Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:ACUTE- MATERIAL IS CORROSIVE TO EYES
AND SKIN. BRIEF CONTACT MAY CAUSE CHEMICAL BURNS. VAPORS AND MISTS
WILL IRRITATE NOSE AND THROAT. CHRONIC-SKIN ALLERGY.
Effects of Overexposure:CORROSIVE TO SKIN AND EYES, CHEMICAL BURS,
CHEST DISCOMFORT AND BRONCHITIS.
Medical Cond Aggravated b
y Exposure:SKIN DISEASES.

===== First Aid Measures =====

First Aid:INHALATION:REMOVE TO FRESH AIR, PROVIDE CPR/OXYGEN IF NEEDED.
EYE CONTACT:FLUSH WITH WATER FOR 15 MINUTES. GET MEDICAL HELP. SKIN
CONTACT:WASH WITH SOAP AND WATER. GET MED ATTENTION IF SYMPTOMS
PERSIS T. INGESTION:DO NOT INDUCE VOMITING, DRINK 1-2 GLASSES OF
WATER. GET MEDICAL HELP IMMEDIATELY.

===== Fire Fighting Measures =====

Extinguish
ing Media:DRY CHEMICAL, HALON, WATER SPRAY, FOAM OR FOG.
Fire Fighting Procedures:FIRE FIGHTERS SHOULD WEAR PROTECTIVE CLOTHING
AND SELF-CONTAINED BREATHING APPARATUS.
Unusual Fire/Explosion Hazard:DENSE SMOKE AND TOXIC GASES MAY BE
LIBERATED.

===== Accidental Release Measures =====

Spill Release Procedures:USE PROPER PERSONAL PROTECTION; USE SUITABLE
ABSORBENT MATERIAL AND RECOVER FOR PROPER DISPOSAL.

===== Handling and Storage =====

Handling and Storage Precautions:STORE IN COOL, DRY AND WELL VENTILATED
AREA. KEEP AWAY FROM HEAT, OPEN FLAMES.
Other Precautions:EMPTY CONTAINERS RETAIN RESIDUE. DO NOT PRESSURIZE,
CUT, WELD OR EXPOSE TO HEAT, FLAME, STATIC ELECTRICITY, OR OTHER
SOURCES OF IGNITION; THEY MAY EXPLODE AND CAUSE INJURY.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:USE NIOSH APPROVED RESPIRATOR FOR ORG VAPORS/
MIST IF ABOVE TLV.

Ventila

tion:PROVIDE LOCAL EXHAUST TO MAINTN 1.0 LB TOTAL

===== Disposal Considerations =====

Waste Disposal Methods:DISPOSE OF COLLECTED MATERIAL IN ACCORDANCE WITH LOCAL,STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.