View NSN Online: https://aerobasegroup.de/nsn/5910-00-238-2479 CORNELL-DUBILIER ELEC. DIV. OF FED. PAC. ELEC. CO. -- TJU20040 -- 5910-00-238-2479 Product ID:TJU20040 MSDS Date:01/01/1985 FSC:5910 NIIN:00-238-2479 MSDS Number: BDMBQ === Responsible Party === Company Name: CORNELL-DUBILIER ELEC. DIV. OF FED. PAC. ELEC. CO. Address: ONE INTERCHANGE PLZ City:WAYNE State:NJ ZIP:07470 Country:US **Emergency Phone Num:NONE** CAGE:14655

== Contractor Identification ===

Company Name: CORNELL-DUBILIER ELECTRONICS

Address: ONE INTERCHANGE PLZ

Box:City:WAYNE

State:NJ ZIP:07470 Country:US

Phone:201-694-8600

CAGE:14655

======= Composition/Information on Ingredients ========

Ingred Name: POLYCHLORINATED BIPHENYLS (PCBS) (SARA III)

CAS:1336-36-3

RTECS #:TQ1350000 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Effects of Overexposure: ABSORBED THRU SKIN, LUNGS, INTESTIN

CANCER,LIVER,KIDNEY,STOMACH,EYE,HEARING DISORDER(SUP DATA)
======================================
First Aid:EYES:FLUSH W/WATER IMMED.SKIN:WASH W/SOAP IMMED.INHAL:REMOVE TO FRESH AIR.GIVE ART.RESPIR. AS NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE QTY OF SALT WATER,INDUCE VOMITING BUT DO NOT MAKE UNCONSCIOUS PE RSON VOMIT.
======== Accidental Release Measures ==========
Spill Release Procedures:USE ABSORBENT & DIKES TO PR
EVENT RUNOFF.ISOLATE & NOTIFY PROPER AUTHORITIES.
=========== Handling and Storage =============
Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENTS.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOOD Ventilation:LOCAL EXHAUST Protective Gloves:RUBBER-IMPERV Eye Protection:GOGGLES.FACESHIELD Other Protective Equipment:FULL CLOTHING TO PREVENT SKIN CONTACT Supplemen tal Safety and Health OVEREXPOS:CAN CAUSE FORMATION OF CYSTS.CAUSES STILLBIRHTS.IRRITATES EYES,NOSE THROAT.
========= Physical/Chemical Properties =========
HCC:V1 Appearance and Odor:LIGHT STRAW COLORED LIQUID,AROMATIC ODOR.
========== Stability and Reactivity Data ==========
STRONG OXIDIZERS
======== Disposal Considerations ===========
Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED GENERALLY HIGH

E.CAUSES

Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED.GENERALLY HIGH TEMP. INCINERATION.O

## NLY APPROVED DISPOSAL OPERATOR PERMITTED.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of th is information to their particular situation.