

CALIFORNIA CHEMICAL COMPANY (HOCKING INTL CHEM CO) -- CORROSION REMOVING AND METAL CONDITION COMP -- 6850-00-656-1291

===== Product Identification =====

Product ID:CORROSION REMOVING AND METAL CONDITION COMP

MSDS Date:01/01/1987

FSC:6850

NIIN:00-656-1291

MSDS Number: BFKBW

=== Responsible Party ===

Company Name:CALIFORNIA CHEMICAL COMPANY (HOCKING INTL CHEM CO)

Address:2121 HOOVER AVE

City:NATION

AL CITY

State:CA

ZIP:92050-6529

Country:US

Info Phone Num:206-447-5911

Emergency Phone Num:206-447-5911

CAGE:6W517

=== Contractor Identification ===

Company Name:CALIFORNIA CHEMICAL & SUPPLY CO.

Address:SEE SUP DATA

Box:City:OAKLAND

State:CA

ZIP:94623

Phone:415-459-3400

CAGE:6W517

Company Name:HOCKING INTERNATIONAL CHEMICAL CORP

Address:2121 HOOVER AVE

Box:City:NATIONAL CITY

State:CA

ZIP:92050

Country:US

Phone:619-474-8457

CAGE:60930

===== Composition/Information on Ingredients =====

=====

Ingred Name:PHOSPHORIC ACID (SARA III)
CAS:7664-38-2
RTECS #:TB6300000
Fraction by Wt: 53.0%
OSHA PEL:1 MG/M3/3 STEL
ACGIH TLV:1 MG/M3/3 STEL; 9192
EPA Rpt Qty:5000 LBS
DOT Rpt Qty:5000 LBS

Ingred Name:2-BUTOXYETHANOL
CAS:111-76-2
RTECS #:KJ8575000
Fraction by Wt: 10.0%
OSHA PEL:S, 50 PPM
ACGIH TLV:S, 25 PPM; 9293

Ingred Name:DETERGENT
Fraction by Wt: 1.0%

===== Hazards Identification =====

Effects of Overexposure:SKIN AND EYES:IRRITATION AND/OR
BURNS.RESPIRATORY TRACT IRRITATION.

===== First Aid Measures =====

First Aid:INHALE:REMOVE TO FRESH AIR, GIVE CPR/O*2 IF
NEED;EYES/SKIN:FLUSH W LG AMTS H*2O FOR 15 MIN;INGEST:RINSE MOUTH;
GET MEDICAL ATTENTION FOR EYES, BREATHING DIFFICULTY, OR OTHER
SYMPTOMS OF OVEREXPOSURE.

===== Fire Fighting Measures =====

Flash Point:NON-FLAMMABLE
Lower Limits:U/K
Upper Limits:U/K
Fire Fighting Procedures:USE NIOSH APP

ROVED SCBA IN FIRES AND IN
CONFINED AREA.

Unusual Fire/Explosion Hazard:NO UNUSUAL FIRE AND EXPLOSION HAZARDS.

===== Accidental Release Measures =====

Spill Release Procedures:USE PROPER PERSONAL PROTECTIVE EQUIPMENT.USE
ABSORBENT MATERIAL AND RECOVER FOR DISPOSAL

===== Handling and Storage =====

Handling and Storage Precautions:STORE IN COOL,DRY AND WELL VENTILATED
AREA.KEEP AWAY FROM ALKALININE MATERIALS.KEEP CONTAI
NERS TIGHTLY
CLOSED WHEN NOT IN USE.

Other Precautions:AVOID CONTACT WITH SKIN AND EYES.AVOID USING
CONTAMINATED CLOTHES.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:USE NIOSH APPROVED RESPIRATOR FOR ACID MIST OR
SCBA.

Ventilation:PROVIDE MECHAN(GEN/LOCAL EXHAUST)VENT TO MAINTN