View NSN Online: https://aerobasegroup.de/nsn/5910-01-014-0260

CORNELL DUBILIER ELEC DIF OF FED PAC ELEC CO -- KNX44P206QAX -- 5910-01-014-0260

Product ID:KNX44P206QAX MSDS Date:01/01/1985 FSC:5910 NIIN:01-014-0260 MSDS Number: BGDKJ === Responsible Party === Company Name: CORNELL DUBILIER ELEC DIF OF FED PAC ELEC CO Address: ONE INTERCHANGE PLZ City:WAYNE State:NJ ZIP:07470 Country:US Emergency Phone Num:NONE CAGE:09023 === C ontractor Identification === Company Name: CORNELL DUBILIER ELEC DIV FED PAC ELEC Address: ONE INTERCHANGE PLZ Box:B-967 **City:WAYNE** State:NJ ZIP:07470 Country:US Phone:201-694-8600 CAGE:09023 Company Name: CORNELL-DUBILIER ELECTRONICS Address: ONE INTERCHANGE PLZ Box:City:WAYNE State:NJ ZIP:07470 Country:US Phone:201-694-8600 CAGE:14655

Ingred Name:POLYCHLORINATED BIPHENYLS (PCBS) (SARA III) CAS:1336-36-3 RTECS #:TQ1350000 EPA R

======================================
Effects of Overexposure:ABSORBED THRU SKIN,LUNGS,INTESTINE.CAUSES CANCER,LIVER,KIDNEY,STOMACH,EYE,HEARING DISORDER(SUP DATA)
======================================
First Aid:EYES:FLUSH W/WATER IMMEDIATELY.SKIN:WASH W/SOAP IMMEDIATELY.INHAL:REMOVE TO FRESH AIR,GIVE ART.RESPIR.AS NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE QTY OF SALT WATER,INDUCE VOMITI
NG,BUT DO NOT MAKE UNC ONSCIOUS PERSON VOMIT.
======================================
Spill Release Procedures: USE ABSORBENT & DIKES TO PREVENT RUNOFF. ISOLATE & NOTIFY PROPER AUTHORITIES.
======================================
Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENTS.
======================================
Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOO
Ventilation:LOCAL EXHAUST
Protective Gloves:RUBBER-IMPERV Eye Protection:GOGGLES,FACE SHIELD
Other Protective Equipment:FULL CLOTHING TO PREVENT SKIN CONTACT Supplemental Safety and Health
OVEREXPOS:CAN CAUSE FORMATION OF CYSTS,CAUSES STILLBIRTHS.IRRITATES EYES,NOSE THROAT.
======================================
HCC:Z3 Appearance and Odor:LIGHT STRAW-COLORED LIQUID,AROMATIC ODOR
======================================

STRONG OXI

DIZERS

Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED-GENERALLY HIGH TEMPERATURE INCINERATION.ONLY APPROVED DISPOSAL OPERATOR PERMITTED.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disc

laims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.