View NSN Online: https://aerobasegroup.com/nsn/8010-00-181-8079

Product ID: THINNER AIRCRAFT COATING MSDS Date:09/01/1990 FSC:8010 NIIN:00-181-8079 **MSDS Number: BJZSK** === Responsible Party === Company Name: CSD INC. (OBSOLETE ADDRESS; USE 4N760) Address:420 SEABOARD DRIVE **City:MATTHEWS** State:NC ZIP:28105-5073 Country:US Info Phone Num:704-82 1-9822 Emergency Phone Num:704-821-9822 Preparer's Name: DAVID SHIPP CAGE:5W216 === Contractor Identification === Company Name: CSD INC. (PRE 1985 NAME: MATHEWS, INC) Address:420 SEABOARD DRIVE Box:City:MATTHEWS State:NC ZIP:28105-5073 Country:US Phone:704-821-9822 CAGE:5W216 Ingred Name: METHYL ETHYL KETONE (2-BUTANONE) (MEK) (SARA III) CAS:78-93-3

RTECS #:EL6475000 Fraction by Wt: 30.5% Other REC Limits:NONE SPECIFIED OSHA PE L:200 PPM/300 STEL ACGIH TLV:200 PPM/300STEL 9192 EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name:HEXYL ACETATE MIXED ISOMERS CAS:88230-35-7 Fraction by Wt: 41.0% Other REC Limits:50 PPM 8 HOUR TWA

Ingred Name:TOLUENE (SARA III) CAS:108-88-3 RTECS #:XS5250000 Fraction by Wt: 10.5% Other REC Limits:NONE SPECIFIED OSHA PEL:200 PPM/150 STEL ACGIH TLV:50 PPM; 9293 EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Ingred Name:N-BUTYL ACETATE (SARA III) CAS:123-86-4 RTECS #:AF7350000 Fraction by Wt : 11.0% Other REC Limits:NONE SPECIFIED OSHA PEL:150 PPM/200 STEL ACGIH TLV:150 PPM/200STEL;9192 EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name:XYLENES (O-,M-,P- ISOMERS) (SARA III) CAS:1330-20-7 RTECS #:ZE2100000 Fraction by Wt: 7.0% Other REC Limits:NOT SPECIFIED OSHA PEL:100 PPM/150 STEL ACGIH TLV:100 PPM/150STEL;9192 EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO

Health Hazards Acute and Chronic:OVEREXPOSURE MAY CAUSE CARDIAC ABNORMALITY & LIVER ABNORMALITY. ASPIRATION OF MATERIAL INTO THE LUNGS DUE TO VOMITING CAN CAUSE CHEMICAL PNEUMONITIS WHICH CAN BE FATAL.

Effects of Overexposure:EYES:IRRIT, REDNESS, TEARING. SKIN: PROLONGED/REPEATED CONTACT CAN CAUSE MODERATE IRRIT, DEFATT, DERMATITIS. EXCESSIVE INHALE:NASAL & RESPIRATORY IRRIT, CENTRAL NERVOUS SYSTEM, DIZZINESS, WEAKNESS, FA TIGUE, NAUSEA, HEADACHE & POSSIBLE UNCONSCIOU

SNESS & EVEN DEATH. SWALLOW:GASTROINTESTINAL IRRIT, NAUSEA, VOMIT & DIARRHE

First Aid:SKIN:THOROUGHLY WASH AREA W/SOAP & WATER. REMOVE CONTAM CLOTHES. LAUNDER CONTAM CLOTHES BEFORE REUSE. EYES:FLUSH WITH LARGE AMOUNTS OF WATER, LIFTING UPPER & LOWER LIDS, GET MED ATTN. SWALLOWED:DO NOT INDUCE VOMITING, KEEP PERSON WARM, QUIET & GET MEDICAL ATTENTION. BREATH:REMOVE PERSON TO FRESH AIR. IF BREATH IS DIF

F ADMIN OXYGEN. BREATH HAS STOPPED GIVE CPR. KEEP PERSON WARM, QUIET, GET MED ATTN

Flash Point:20 F/-6.7 C Lower Limits:1.0 Extinguishing Media:REGULAR FOAM OR CARBON DIOXIDE OR DRY CHEMICAL Fire Fighting Procedures:WEAR SELF CONTAINED BREATHING APPARATUS W/ FULL FACEPIECE OPERATED IN POSITIVE PRESS DEMAND MODE. VAPOR MAY TRAVEL TO IGNITE SOURCES DISTANT FROM HANDLING POINT Unusual Fire/Explosion Hazard:NEVER WELD , USE CUTTING TORCH ON OR NEAR DRUM(EVEN EMPTY)CAN IGNITE EXPLOSIVELY. ALL 5 GAL PAIL & LARGE

METAL CONTAINERS GROUND/BOND WHEN TRANSFERING MATERIAL.

Spill Release Procedures:SM:ABSORB LIQ ON PAPER,VERMICULITE,FLOOR ABSORBENT. LG:ELIM ALL IGNITE SOURCES. NO PERSONS W/OUT WEARING PROTECTIVE EQUIP. STOP AT SOURCE. DIKE AREA TO PREVENT SPREAD, PUMP LIQ TO SALVAGE TANK. TAKE U P REST W/SAND,CLAY,ETC. SHOVEL INT CONTAINERS.

Handling and Storage Precautions: CONTAINERS MAY BE HAZARDOUS WHEN EMPTIED. SINCE EMPTIES RETAIN PRODUCT RESIDUES(VAPOR, LIQUID, SOLID) ALL HAZARD PRECAUTIONS GIVEN MUST BE OBSERVED. Respiratory Protection: NIOSH/MSHA APPROVED AIR SUPPLIED RESPIRATOR IS ADVISED IN ABSENCE OF PROPER ENVIRONMENTAL CONTROL. OSHA REGS ALSO PERMIT OTHER NIOSH/MSHA RESPIRATORS (NEGATIVE PRESSURE TYPE) UNDER SPECIFIED CONDITION S. SEE YOUR SAFETY EQUIPMENT SUPPLIER. Ventilation: PROVIDE SUFFICIENT MECHANICAL (GENERAL &/OR LOCAL EXHAUST) VENTILATION Protective Gloves:WEAR RESISTANT GLOVES:POLYETHYLENE Eye Protection: CHEM SPLASH GOGGLES OR SAFETY GLASSES Other Protective Equipment: TO PREVENT REPEATED OR PROLONGED SKIN CONTACT, WEAR IMPERVIOUS CLOTHING & BOOTS Work Hygienic Practices: REMOVE CONTAMINATED CLOTHING. LAUNDER CONTAM INATED CLOTHING BEFORE RE-USE. Supplemental Safety and Health HCC:F2 Boiling Pt:B.P. Text:179F,82C Melt/Freeze Pt:M.P/F.P Text:-20F,-29C Vapor Pres:35.1 MMHG Vapor Density:3.4 Spec Gravity:0.850 Evaporation Rate & amp; Reference: SLOWER THAN ETHER Solubility in Water:MODERATE Appearance and Odor: CLEAR, LITTLE IF ANY COLOR; CHARACTERISTIC ODOR Percent Volatiles by Volume:100 Corrosion Rate:NONE

======== Stability and

Reactivity Data ==========

Stability Indicator/Materials to Avoid:YES AVOID CONTACT WITH STRONG OXIDIZING AGENTS Hazardous Decomposition Products:MAY FORM TOXIC MATERIALS. CARBON DIOXIDE & CARBON MONOXIDE, VARIOUS HYDROCARBONS, ETC.

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH ALL LOCAL, STATE AND FEDERAL REGULATIONS. PREVENT RUN-OFF TO SEWERS, STREAMS OR OTHER BODIES OF WATER. IF RUN-OFF OCCURS, NOTIFY PROPER AUTHORITIES AS REQUIRED, THAT A S PILL HAS OCCURRED.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibil

ity for the suitability of this information to their particular situation.