MSDS Number: BMGQM
=== Responsible Party ===

Company Name: WESTINGHOUSE ELECTRIC CORP, MARINE DIV MLS

Address: 401 E HENDY AVE BLDG 71-40

Box:3499

City:SUNNYVALE

State :CA

ZIP:94088-3499 Country:US

Info Phone Num:408-735-2210

Emergency Phone Num:408-735-2210 Preparer's Name:DOD HMIS/DGSC-SSH

CAGE:90099

=== Contractor Identification ===

Company Name: WESTINGHOUSE ELECTRIC CORP. ELECTRONIC SYS. GROUP

Address: 401 E HENDY AVENUE BLDG 71-40

Box:3499

City:SUNNYVALE

State:CA

ZIP:94088-3499 Country:US

Phone:408-735-2210

CAGE:90099

======= Composition/Information on Ingredients ========

Ingred Name: ASBESTOS, WHITE (CHRYSOTILE), (OSHA PEL FROM 29CFR 19

10.1001).

CAS:12001-29-5

RTECS #:CI6478500

OSHA PEL:0.2 FIBERS/CC

ACGIH TLV:2 FIBERS/CC 9192

Ingred Name: POLYTETRAFLUOROETHYLENE (TFE) IMPREGNATED ASBESTOS

RTECS #:9999999ZZ Fraction by Wt: 18% TFE

Ingred Name:GENERIC "MSDS". SPECIFIC ASBESTOS TYPE NOT KNOWN. ONE CITED IS ASSUMED. INFORMATION BASED ON MILITARY SPEC. MIL-A-24058. RTECS #:9999992Z

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO

Reports of Carcino

| genicity:NTP:YES   | IARC:YES   | OSHA:YES  |
|--------------------|------------|-----------|
| UCHILIUN, NIF. IES | IANC. I ES | USHA. I E |

Health Hazards Acute and Chronic:ACUTE: NO ACUTE EFFECTS ARE KNOWN; CHRONIC: DUST FROM ABRASIVE ACTIONS (EG. CUTTING, MACHINING, FILING, ETC.) MAY CONTAIN ASBESTOS FIBERS. CHRONIC OVEREXPOSURE TO AIRBORNE FIBERS MAY LEAD TO ASBESTOSI S & MESOTHELIOMA. SMOKING COMBINED W/FIBER INHALATION GREATLY INCREASES LUNG CANCER RISK.

Explanation of Carcinogenicity:OVEREXPOSURE TO AIRBORNE CONCENTRATIONS OF ASBESTOS MAY LEAD TO ASBESTOSIS AND MESOTH ELIOMA.

Effects of Overexposure:INHALATION: INHALATION OF AIRBORNE DUST CONTAINING ASBESTOS FIBERS ON REPEATED EXPOSURE MAY CAUSE OR CAN LEAD TO ASBESTOSIS / MESOTHELIOMA. SKIN: NONE KNOWN. EYE: POTENTIAL IRRITATION FROM AIRBORNE DU ST; INGEST: NONE KNOWN.

Medical Cond Aggravated by Exposure:PERSON WITH PRE-EXISTING DISEASE INVOLVING THE EYES, SKIN OR RESPIRATORY TRACT MAY BE AT INCREASED RISK FROM EXPOSURE TO ASBESTOS DUST.

|   | First Aid Measures | ===== |
|---|--------------------|-------|
| ======================================= |                    |       |

First Aid:INHALATION: REMOVE TO FRESH AIR. OBTAIN MEDICAL ADVICE. SKIN: WASH EXPOSED AREA WITH SOAP & WATER. EYE: FLUSH WITH LARGE AMOUNT OF WATER. IF IRRITATION PERSISTS, GET MEDICAL ATTENTION. INGESTION: GET MEDICAL ATTENTION. OTHER: CHANGE CLOTHING AS REQUIRED TO AVOID CARRYING DUST PARTICLES INTO OTHER AREAS.

| ======================================= | Fire | Fighting | Measures | ======================================= |
|---|------|----------|----------|---|
|---|------|----------|----------|---|

Flash Point:NONE

Extinguishing Media:MATERIAL IS NOT FLAMMABLE. USE MEDIA APP ROPRIATE

FOR SURROUNDING FIRE.

Fire Fighting Procedures: COMBUSTION PRODUCTS OF THIS MATERIAL MAY BE TOXIC. USE A SELF-CONTAINED BREATHING APPARATUS WHEN FIGHTING FIRES INVOLVING CHEMICAL PRODUCTS.

Unusual Fire/Explosion Hazard: NONE KNOWN

|  | Accidental Release Measures |  |
|--|-----------------------------|--|
|--|-----------------------------|--|

Spill Release Procedures:USE PROPER PERSONAL PROTECTION. VACUUM OR WET CLEAN IF DUST IS INVOLVED. ANY VACUUM SYSTEM SHOULD BE EQUIPPED WITH AN OUTLET "HEPA" FILTER TO PREVE

| FIBERS TO THE ATMOSPHERE.  |
|--|
| ======================================   |
| Handling and Storage Precautions:HANDLE IN A MANNER TO MINIMIZE FORMATION OR RETENTION OF AIRBORNE DUST. USE PROPER PERSONAL PROTECTION FOR TASK AT HAND. CHECK W/YOUR SAFETY OFFICE!!! Other Precautions:AS MANUFACTURED, LOCKED-IN ASBESTOS DOES NOT PRESENT A HAZARD. ONLY WHEN THE ITEM IS SUBJECTED TO ABRASIVE ACTIONS AND DUST IS GENERATED, THEN ASBESTOS FIBE RS MAY BE RELEASED AND BECOME AIRBORNE.   |
| ====== Exposure Controls/Personal Protection ========  |
| Respiratory Protection:IF EXPOSURES EXCEED ESTABLISHED LIMITS, A NIOSH/ MSHA APPROVED RESPIRATOR FOR ASBESTOS SHOULD BE USED. CONSULT YOUR SAFETY OFFICE/IH PERSONNEL FOR GUIDANCE FOR THE TASK AT HAND. Ventilation:LOCAL EXHAUST IS RECOMMENDED IN SITUATIONS WHERE DUST IS GENERATED BY ABRASIVE ACTIONS, ABRASION OR OTHER MEANS. Protective Gloves:AS REQUIRED FOR TASK AT HAND. Eye Protection:SAFETY GLASSES W/SIDE SHIELDS OR GOGGLES Other Protective Equipment:AS REQUIRED FOR TASK AT HAND, AND THE GUIDANCE SET FORTH BY YOUR SAFETY OFFICE OR IH PERSONNEL Work Hygienic Practices:DO NOT INHALE DUST CREATED BY ABRADING ACTIONS.USE FULL PROTECTION AGAINST AIRBORNE FIBERS.AVOID AIRBORNE DUST CREATION. Supplemental Safety and Health THIS GENERIC "MSDS" WAS GENERATED FOR THIS "NSN" BASED ON MILITARY SPECIFICATION MIL-G-21032E FOR A METALLIC-ASBESTOS, SPIRAL WOUN D GASKET. WHEN A MANUFACTURER'S SPECIFIC "MSDS" IS PROVIDED FOR MATERI AL PROCURED UNDER THIS NSN, THIS GENERIC "MSDS" WILL BE REMOVED.   |
| ======================================   |
| HCC:T6 Evaporation Rate & Evapor |
| ========= Stability and Reactivity Data =========  |
| Stability Indicato   |

NT REINTRODUCING ASBESTOS

r/Materials to Avoid:YES NONE KNOWN Stability Condition to Avoid:NONE KNOWN

======= Disposal Considerations ===========

Waste Disposal Methods:CONTACT YOUR LOCAL ENVIRONMENTAL OFFICER.
DISPOSE OF ASBESTOS WASTE IN ACCORDANCE WITH LOCAL, STATE AND
FEDERAL REGULATIONS. DUST SHOULD BE HANDLED AS A HAZARDOUS AIR
POLLUTANT I/A/W 40CFR61 SUBPART " M" PERTAINING TO ASBESTOS. USE
APPROVEDLANDFILLS.

Disclaimer (provided with this information by the compiling ag encies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.