

Product ID:STYLE 64 MSDS Date:01/15/1991 FSC:5330 NIIN:00-996-4825 MSDS Number: BMWKD === Responsible Party === Company Name: A W CHESTERTON CO Address:225 FALLON RD City:STONEHAM State:MA ZIP:02180-2999 Country:US Info Phone Num:617-438-7000 Emergency Phone Num:617-438-7000;617-438-7013 CAGE:71431 === Contractor I dentification === Company Name: CHESTERTON A W CO Address:225 FALLON RD Box:City:STONEHAM State:MA ZIP:02180-9101 Country:US Phone:781-438-7000/800-535-5053 CAGE:71431

Ingred Name:ASBESTOS CAS:1332-21-4 RTECS #:CI6425000 Fraction by Wt: 45-55% OSHA PEL:0.2 F/CC (MFR) ACGIH TLV:0.2 FIBERS/CC EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name:GRAPHITE CAS:7782-42-5 RTECS #:MD9659600 Fraction by Wt: 1-5% OSHA PEL:15 MPPCF RDUST ACGIH LD50 LC50 Mixture: NONE SPECIFIED BY MANUFACTURER. Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:YES Health Hazards Acute and Chronic:(ACUTE) GRAPHITE DUST MAY CAUSE MECHANICAL IRRITATION TO THE SKIN, EYES, AND NASAL PASSAGES. (CHRONIC) EXPOSURE TO HIGH CONCENTRATIONS OF ASBESTOS DUST INCREASES RISK OF DEVELOPING LUNG DISEASES. SMOK ERS HAVE A GREATER RISK. Explanation of Carcinogenicity: ASBESTOS: GROUP 1 (NTP, IARC), OSHA REGULATED. Effects of Overexposure: SEE HEALTH HAZARDS. Medical Cond Aggravated by Exposure:NONE SPECIFIED BY MANUFACTURER. First Aid:INHAL: REMOVE TO FRESH AIR. IF BREATHING HAS STOPPED, PERFORM ARTF RESP. CONTACT MD. SKIN: WASH SKIN WITH SOAP AND WATER. EYES: FLUSH EYES FOR AT LEAST 15 MINUTES WITH LARGE AMOUNTS OF WATER. CONSULT MD IF IRRITATION PERSISTS. INGEST: CALLMD IMMEDIATELY . Extinguishing Media:CO*2, DRY CHEMICAL OR FOAM. Fire Fighting Procedures:WEAR NIOSH/MSHA APPROVED SCBA & FULL PROTECTIVE EQUIPMENT. **Unusual Fire/Explosion Hazard:NONE** Spill Release Procedures: IF PRODUCT IS DRIED OUT, WET WITH WATER, SWEEP UP OR HEPA VACUUM AND PLACE IN IMP ERMEABLE BAGS FOR DISPOSAL. Neutralizing Agent:NONE SPECIFIED BY MANUFACTURER. Handling and Storage Precautions: KEEP IN DRY & VENT AREA. USE KNIFE-TYPE ACTION TO CUT PACKING. NEVER USE A SAW-TYPE ACTION OR CUT IN AN ABRASIVE MANNER.

Other Precautions:DURING REMOVAL, ENSURE MATL IS ADEQ WET, CONTAIN & CAPTURE THE MATL TO ENSURE NO RELS OF ASBESTOS EMISSIONS, ENSURE MATL REMAINS WET UNTIL & AFTER IT IS SEALED INT

O LEAK TIGHT CNTNR FOR DISP.NOTIFICAT ION MAY BE REQ PRIOR TO (SUPP DATA)

Respiratory Protection:NOT NORMALLY REQUIRED. USE NIOSH/MSHA ASBESTOS APPROVED RESPIRATOR IF PEL/TLV IS EXCEEDED. Ventilation:IF PEL/TLV IS EXCEEDED, PROVIDE ADEQUATE VENTILATION. Protective Gloves:NOT NORMALLY NEEDED. Eye Protection:CHEMICAL WORKERS GOGGLES . Other Protective Equipment:NONE Work Hygienic Practices:NONE SPECIFIED BY MANUFACTURER.

Supplemental Safety and Health OTHER PREC: REMOVAL, CHECK LOCAL, STATE AND FEDERAL REGULATIONS.

Appearance and Odor:NONE SPECIFIED BY MANUFACTURER.

Stability Indicator/Materials to Avoid:YES STRONG OXIDIZING AGENTS. Stability Condition to Avoid:NONE Hazardous Decomposition Products:TRACE AMOUNTS OF CO, CO*2, SO*2.

====== Disposal Considerat

Waste Disposal Methods:PUT WASTE IN SEALED IMPERMEABLE BAG OR CONTAINER, PROPERLY LABEL ACCORDING TO LOCAL, STATE AND FEDERAL REGULATIONS AND DISPOSE IN AN ASBESTOS APPROVED LANDFILL. CHECK LOCAL, STATE AND FEDERAL REGULATI ONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implie

d, warrants this information to be accurate and

disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.