

GENERAL ELECTRIC CO., SILICONE PRODUCT DIV. -- RTV 8111 SILICONE RUBBER --
8030-00-142-9128

=====
===== Product Identification =====

Product ID:RTV 8111 SILICONE RUBBER

MSDS Date:03/23/1988

FSC:8030

NIIN:00-142-9128

Kit Part:Y

MSDS Number: BNSYM

=== Responsible Party ===

Company Name:GENERAL ELECTRIC CO., SILICONE PRODUCT DIV.

City:WATERFORD

State:NY

ZIP:12188

Country:US

Info Phone Num:518-237-3330

Eme

rgency Phone Num:518-237-3330

Preparer's Name:DA POLSINELLI

CAGE:01139

=== Contractor Identification ===

Company Name:GENERAL ELECTRIC CO, SILICONE PRODUCTS BUSINESS DEPT

Address:260 HUDSON RIVER RD

Box:City:WATERFORD

State:NY

ZIP:12188

Country:US

Phone:518-237-3330/800-332-3390

CAGE:01139

Company Name:R.H.CARLSON COMPANY,INC.

Address:41-CHESTNUT STREET

Box:1687

City:GREENWICH

State:CT

ZIP:06830-5921

Country:US

Phone:203-531-5500

CAGE:33530

=====
===== Composition/Information on Ingredients

=====

Ingred Name:ETHYL SILICATE (BOILING POINT 334F) (VAPOR PRESSURE 2.0 MM HG @ 20 C) (VAPOR DENISTY 7.2 [AIR=1])
CAS:110990-60-2
Fraction by Wt: 1000 PPM 4HR (RAT).
Medical Cond Aggravated by Exposure:NONE KNOWN.

===== First Aid Measures =====

First Aid:INGESTION: IF SWALLOWED DO NOT INDUCE VOMITING. GIVE LARGE QUANTITIES OF WATER TO DRINK AND GET MEDICAL ATTENTION. NEVER GIVE ANYTHING BY MOUTH TO AN UNCONSCIOUS PERSON. SKIN: WASH WITH SOAP AND WATER . EYES: IN CASE OF CONTACT, IMMEDIATELY FLUSH EYES WITH PLENTY OF WATER FOR AT LEAST 15 MINUTES AND GET MEDICAL ATTENTION IF IRRITATION PERSISTS.

===== Fire Fighting Measures =====

Flash Point Method:COC
Flash Point:570F,299C
Extinguishing Media:ALL STANDARD FIREFIGHTING MEDIA.
Fire Fighting Procedures:NONE KNOWN.

===== Accidental Release Measures =====

Spill Release Procedures:WIPE, SCRAPE OR SOAK UP IN AN INERT MATERIAL AND PUT IN A CONTAINER FOR DISPOSAL. WASH WALKING SURFACES WITH DETERGENT AND WATER TO REDUCE SLIPPING HAZARD. WEAR PROPER PROTECTIVE EQUIPMENT AS SPECIFIED IN THE PROTECTIVE EQUIPMENT SECTION.

===== Handling and Storage =====

Handling and Storage Precautions:AVOID CONTACT WITH SKIN AND EYES. USE ONLY IN A WELL VENTILATED AREA. CAUTION!
Other Precautions:ENGINEERING CONTROLS: EYEWASH STATIONS. USE IN A WELL VENT

ILATED AREA.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:USE IN A WELL VENTILATED AREA.

Ventilation:USE ONLY IN WELL VENTILATED AREA.

Protective Gloves:RUBBER GLOVES.

Eye Protection:SAFETY GLASSES.

Other Protective Equipment:NONE KNOWN.

Work Hygienic Practices:REMOVE CONTAMINATED CLOTHING AND LAUNDER BEFORE REUSE.

Supplemental Safety and Health

KEY1=N1.

===== Physical/Chemical Properties =====

HCC:F2

Spec Gravity:

1.16 (WATER=1)

Viscosity:12,000 CPS

Evaporation Rate & Reference: