View NSN Online: https://aerobasegroup.de/nsn/5340-01-005-8205

GENERAL ELECTRIC CO GE AIRCRAFT ENGINES -- J664G08 -- 5340-01-005-8205

Product ID:J664G08 MSDS Date:10/05/1992

FSC:5340

NIIN:01-005-8205

MSDS Number: BNWQV === Responsible Party ===

Company Name: GENERAL ELECTRIC CO GE AIRCRAFT ENGINES

Address: MAIL DROP W48 OR W49, 1 NEUMANN WAY

Box:156301 City:CINCINNATI

State:OH

ZIP:45215-6301

Country:US

Info Phone Num:513-243-0

794

Emergency Phone Num:513-243-0794 Preparer's Name:HMIS TECHNICIAN

CAGE:07482

=== Contractor Identification ===

Company Name: GENERAL ELECTRIC CO GE AIRCRAFT ENGINES

Address: MAIL DROP W48 OR W49, 1 NEUMANN WAY

Box:156301 City:CINCINNATI

State:OH

ZIP:45215-6301

Country:US Phone:513-243-0794

CAGE:07482

======= Composition/Information on Ingredients ========

Ingred Name: ASBESTOS, CHRYSOTILE

CAS:12001-29-5 RTECS #:CI6478500

Other REC Limits: NONE RECOMMENDED

OSHA PEL:0.2 FIBERS/CC

ACG

IH TLV:2 FIBERS/CC; A1;9192 Ingred Name:STEEL Other REC Limits: NONE RECOMMENDED Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO Health Hazards Acute and Chronic:ACUTE:MINOR EYS/SKIN IRRITATION. INGESTION- IRRITATION OF GI TRACT. INHALATION-IRRITATION OF RESPIRATORY TRACT. CHRONIC: ASBESTOSIS, LUNG CANCER, & MESOTHELIOMA, ALL OF WHICH ARE DISABLING A ND FATAL D ISEASES OF THE LUNG. INHALATION AND INGESTION OF ASBESTOS FIBERS MAY CAUSE CANCER OF THE BOWEL. Explanation of Carcinogenicity: ASBESTOS IS A KNOWN HUMAN CARCINOGEN. Effects of Overexposure: INHALATION: FATIGUE AND SHORTNESS OF BREATH THAT GETS WORSE WITH TIME AND EVENTUALLY BECOMES DISABLING, EYES: IRRITATION. SKIN: IRRITATION. INGESTION: MILD STOMACH DISTRESS. DIARRHEA, VOMITING, AND NA USEA. Medical Cond Aggravated by Exposure: ASTHMA, EMPHYSEMA, AND TUBERCULOSIS ARE ALL GENERALLY AGGRAVATED BY EXPOSURE TO ASBESTOS FIBERS. First Aid:INHALATION: REMOVE TO FRESH AIR. SEE DOCTOR. EYES: RINSE THOROUGHLY WITH WATER FOR 15 MINUTES. SEE DOCTOR. SKIN: WASH THOROUGHLY WITH SOAP AND WATER. IF IRRITATION PERSISTS, SEE DOCTOR. INGESTION: DIL UTE WITH WATER. DO NOT INDUCE VOMITING. SEE DOCTOR. Flash Point: NOT REQU Extinguishing Media: USE WATER FOG, CARBON DIOXIDE, FOAM, OR DRY CHEMICAL. Fire Fighting Procedures: WEAR FIRE FIGHTING PROTECTIVE EQUIPMENT AND A FULL FACED SELF CONTAINED BREATHING APPARATUS. Unusual Fire/Explosion Hazard: COMBUSTION OR HEAT OF FIRE MAY PRODUCE HAZARDOUS DECOMPOSITION PRODUCTS AND VAPORS. ======== Accidental Release Measures ============

Spill Release Procedures: VACUUM THE MATERIAL WITH A HEPA FILTERED

VACUUM. THE EQUIPMENT SHALL BE USED &

CONTAMINATION.
======================================
Handling and Storage Precautions:CLAMP IS NONFRIABLE & WILL NOT SHED FIBERS IN NORMAL USE AND STORAGE. USED CLAMPS SHALL BE WETTED BEFORE, DURING & AFTER DISASSEMBLY FROM AN ENGINE. Other Precautions:IF IT IS NECESSARY TO CUT OR IMPACT THE CLAM P WHILE
INSTALLING IT, WEAR A RESPIRATOR AND PROTECTIVE CLOTHING. USED CLAMPS SHALL BE IDENTIFIED AND DISPOSED OF IN ACCORDANCE WITH ALL LOCAL, STATE AND FE DERAL REGULATIONS.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:WEAR A NIOSH/MSHA APPROVED HEPA RESPIRATOR IF REQUIRED. WEAR SELF-CONTAINED BREATHING APPARATUS IF REQUIRED FOR HIGH LEVELS OF CONTAMINATES. Ventilation:LOCAL EXHAUST SUFFICIENT TO ENTRAIN ALL PARTICULATE
EM ISSIONS. HEPA FILTER REQUIRED. NO LEAKS ON PRESSURE SIDE OF FAN. Protective Gloves:COTTON OR LEATHER Eye Protection:SAFETY GLASSES OR GOGGLES Other Protective Equipment:USE COVERALLS OR DISPOSABLE CLOTHING. Work Hygienic Practices:WET WORK TO THE DEGREE POSSIBLE. WASH HANDS AFTER HANDLING CLAMP. LAUNDER CONTAMINATED CLOTHING BEFORE REUSE. Supplemental Safety and Health MSDS GENERATED BY HMIS TECHNICIAN.
========== Physical/Chemical Properties =============
HCC:T6 Solubility in Water:INSOLUBLE Appearance and Odor:BAND COMPOSED OF STEEL AND ASBESTOS Percent Volatiles by Volume:0
======================================
Stability Indicator/Materials to Avoid:YES STRONG OXIDIZING AGENTS, STRONG MINERAL ACIDS, AND STRONG ALKALIS Stability Condition to Avoid:ACCUMULATIONS OF DUST Hazardous Decomposition Products:ASBESTOS DUST
========= Disposal Considerations =============
Waste Disposal Methods:WET THE MATERIAL WITH WAT

RE-ENTRY OF ASBESTOS INTO THE WORKPLACE. OTHERWISE, WET THE MATERIAL WITH WATER & SURFACTAN T AND THEN SHOVEL OR MOP UP

EMPTIED SO AS TO MINIMIZE THE

ER AND SURFACTANT.

PLACE IN 6 MIL THICK POLYETHYLENE PLASTIC BAG. PLACE THESE BAGS INTO ANOTHER POLY BAG OR A SAFE PLACE UNTIL IT CAN BE SHIPPED TO AN APPROVED DISPOSAL SITE. IDENTIFY WITH ASBESTOS CANCER WARNING LABEL.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.