

CANTEX CORP -- CANTEX ASBESTOS-FREE WOVEN LINING -- 3950-01-286-8648

===== Product Identification =====

Product ID:CANTEX ASBESTOS-FREE WOVEN LINING

MSDS Date:09/01/1991

FSC:3950

NIIN:01-286-8648

MSDS Number: BPPHB

=== Responsible Party ===

Company Name:CANTEX CORP

Address:ROTTERDAM INDUSTRIAL PK BLDG NO 1

City:SCHENECTADY

State:NY

ZIP:12306

Country:US

Info Phone Num:800-833-6146

Emergency Phone N

um:800-833-6146

CAGE:5K616

=== Contractor Identification ===

Company Name:CANTEX CORP

Address:ROTTERDAM INDUSTRIAL PK BLDG NO 1

Box:City:SCHENECTADY

State:NY

ZIP:12306

Country:US

Phone:800-833-6146

CAGE:5K616

===== Composition/Information on Ingredients =====

Ingred Name:FIBERGLASS

Fraction by Wt: 50%

Other REC Limits:NONE RECOMMENDED

OSHA PEL:15 MG/M3(TOTAL DUST)

ACGIH TLV:10 MG/M3 (DUST)

Ingred Name:AROMATIC HYDROCARBONS

Fraction by Wt: 50%

Other REC Limits:NONE RECOMMENDE

D

===== Hazards Identification =====

Routes of Entry: Inhalation:NO Skin:YES Ingestion:NO
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:POSSIBLE DERMATITIS EFFECT ON SKIN.
Explanation of Carcinogenicity:THIS COMPOUND CONTAINS NO INGREDIENTS AT
CONCENTRATIONS OF 0.1% OR GREATER THAT ARE CARCINOGENS OR SUSPECT
CARCINOGENS.
Effects of Overexposure:NONE SPECIFIED BY MANUFACTURER.
Medical Cond Aggravated by Exposure:
NONE SPECIFIED BY MANUFACTURER.

===== First Aid Measures =====

First Aid:WASH SKIN FREELY WITH SOAP AND WATER. USE APPROVED CREAMS.

===== Fire Fighting Measures =====

Extinguishing Media:"NO FIRE HAZARD"

===== Accidental Release Measures =====

Spill Release Procedures:NONE SPECIFIED BY MANUFACTURER.

===== Handling and Storage =====

Handling and Storage Precautions:CONTACT WITH BARE SKIN MAY CAUSE SOME
FORM OF CONTACT DERMATITIS WITH SENSITIVE SKIN. USE ADEQUATE
PROTECTION, SUCH AS GLOVES OR CREAMS WHEN HANDLING.
Other Precautions:AVOID BREATHING DUSTS.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:USE APPROVED RESPIRATORY MASK TO PROTECT FROM
DUST WHEN CUTTING OR MACHINING.
Ventilation:MACHINERY SHOULD BE EQUIPPED WITH DUST REMOVAL HOODS.
Protective Gloves:AVOID CONTACT. USE HAND PROTECT

ION.
Eye Protection:SAFETY GLASSES SHOULD BE WORN.
Other Protective Equipment:NONE SPECIFIED BY MANUFACTURER.
Work Hygienic Practices:WASH THOROUGHLY AFTER HANDLING AND BEFORE
EATING, DRINKING OR SMOKING.
Supplemental Safety and Health
AVOID PROLONGED OR REPEATED DUST EXPOSURE.

===== Physical/Chemical Properties =====

HCC:N1

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES
NONE IN DESIGNED USE.
Stab
ility Condition to Avoid:NONE SPECIFIED BY MANUFACTURER.
Hazardous Decomposition Products:NONE SPECIFIED BY MANUFACTURER.

===== Disposal Considerations =====

Waste Disposal Methods:PLACE IN SEALED CONTAINER AND DISPOSE OF IN
APPROVED LANDFILL.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department
of Defense. The United States of America in no manner whatsoever,
expres
sly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document should seek competent professional advice to verify and
assume responsibility for the suitability of this information to their
particular situation.