

BECTON-DICKINSON MICROBIOLOGY SYSTEMS INC -- PREPARED TUBED AND MYCOFLASK MEDIA
-- 6550-01-302-1015

===== Product Identification =====

Product ID:PREPARED TUBED AND MYCOFLASK MEDIA

MSDS Date:12/16/1993

FSC:6550

NIIN:01-302-1015

MSDS Number: BWSPK

=== Responsible Party ===

Company Name:BECTON-DICKINSON MICROBIOLOGY SYSTEMS INC

Address:250 SCHILLING CIR

Box:243

City:COCKEYSVILLE

State:MD

ZIP:21030

C

Country:US

Info Phone Num:410-771-0100, 410-584-7169

Emergency Phone Num:301-584-7169/ 410-584-7169

CAGE:05545

=== Contractor Identification ===

Company Name:BECTON DICKINSON AND CO MICROBIOLOGY SYSTEMS DIV

Address:250 SCHILLING CIRCLE

Box:City:HUNT VALLEY

State:MD

ZIP:21030-1103

Country:US

Phone:410-771-0101

CAGE:05545

Company Name:CURTIN MATHESON SCIENTIFIC INC

Address:9999 VETERANS MEMORIAL DR

Box:1546

City:HOUSTON

State:TX

ZIP:77038-2499

Country:US

Phone:713-820-9898

CAGE:15481

=====

Composition/Information on Ingredients =====

Ingred Name:SUCROSE (BEET SUGAR)
CAS:57-50-1
RTECS #:WN6500000
Fraction by Wt: 3.00%
Other REC Limits:NONE RECOMMENDED
OSHA PEL:15 MG/M3 TDUST
ACGIH TLV:10 MG/M3; 9394

===== Hazards Identification =====

LD50 LC50 Mixture:ORAL LD50, RAT: 29700MG/KG.
Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:INHAL:MAY CAUSE IRRITATION. SKIN:MAY
CAUSE IRRITATION. EYES:MAY CAUSE IRRITATION. INGEST:NOT DETERMINED.
Explanation of Carcinogenicity:PER MSDS:CARCINOGENICITY:NOT APPLICABLE;
NTP/IARC/OSHA:NO.
Effects of Overexposure:IRRITATION OF EYES, SKIN, INHALATION AND
INGESTION.
Medical Cond Aggravated by Exposure:NOT DETERMINED.

===== First Aid Measures =====

First Aid:INHAL:REMOVE TO FRESH AIR. SKIN:WASH W/SOAP & WATER.
EYES:FLUSH WITH WATER FOR 15MINS.

===== Fire Fighting Measures =====

Extinguishing Media:WATERSPRAY.
Unusual Fire/Explosion Hazard:PRODUCT WILL NOT BURN. IF PRODUCT BECOMES
INVOLVED IN A FIRE SITUATION EXTINGUISHING MEDIA FOR SURROUNDING
MATERIAL SHOULD BE APPROPRIATE.

===== Accidental Release Measures =====

Spill Release Procedures:USE PAPER TOWELS TO PICK UP LIQUID &/OR GELLED
MATERIAL. WASH AREA WITH SOAP & WATER AFTER CLEANUP IS COMPLETE.
SEE WASTE DI

ith this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.