View NSN Online: https://aerobasegroup.com/nsn/8010-01-068-7723

Product ID:LAM X500 OFF WHITE SURFACER, 8W5 MSDS Date:01/17/1992 FSC:8010 NIIN:01-068-7723 **MSDS Number: BXBNX** === Responsible Party === Company Name: DEXTER CROWN METRO AEROSPACE COATINGS Address:31500 HAYMAN City:HAYWARD State:CA ZIP:94544 Country:US Info Phone Num:415-471-7171 Emergency Phone Num:415-791-1961 Preparer's Name:MCQUINN CAGE:0S4B8 === Contractor Identification === Company Name: CROWN METRO AEROSPACE COATINGS INC SUB OF DEXTER CORP THE Address:315 ECHELON RD Box:5695 City:GREENVILLE State:SC ZIP:29606 Country:US Phone:803-277-1870 CAGE:0S4B8 Company Name: DEXTER CORP THE DEXTER CROWN METRO AEROSPACE DIV Address:31500 HAYMAN ST Box:City:HAYWARD State:CA ZIP:94544-7120 Country:US Phone:510-471-7171 CAGE:98795

======== Composition/Information on

Ingredients ========

Ingred Name:SILICA, CRYSTALLINE - QUARTZ CAS:14808-60-7 RTECS #:VV7330000 Fraction by Wt: 10-20% OSHA PEL:SEE TABLE Z-3 ACGIH TLV:0.1 MG/M3 RDUST

Ingred Name:ACETIC ACID, BUTYL ESTER; (BUTYL ACETATE) (CERCLA). VP:8.0 @ 20C CAS:123-86-4 RTECS #:AF7350000 Fraction by Wt: 259F,>126C Vapor Pres:SEE INGS Vapor Density:HVR/AIR Spec Gravity:1.62 Evaporation Rate & amp; Reference:NOT KNOWN Solubility in Water:NOT KNOWN Appearance and Odor:NONE SPECIFIED BY MANUFACTURER.

Stability Indicator/Materials to Avoid:YES NONE SPECIFIED BY MANUFACTURER. Stability Condition to Avoid:NONE SPECIFIED BY MANUFACTURER. Hazardous Decomposition Products:FUMES MAY CONTAIN CARBON MONOXIDE & OXIDES OF NITROGEN. MAY PRODUCE HAZ FUMES WHEN HEATED TO DECOMP AS IN WELDING.

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE, AND

FEDERAL REGUALTIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this informatio n to their particular situation.