Product ID:CADMIUM OXIDE, TECHNICAL MSDS Date:03/01/1996 FSC:6810 NIIN:00-281-8804 **MSDS Number: BZNRJ** === Responsible Party === Company Name: CITY CHEMICAL CORPORATION Address:232 W.22ND STREET **City:NEW YORK** State:NY ZIP:10011-2418 Country:US Info Phone Num:201-653-6900/FAX -4468 Emergency P hone Num:201-653-6900/800-424-9300(CHEMTREC) CAGE:83628 === Contractor Identification === Company Name: CITY CHEMICAL CORPORATION Address:100 HOBOKEN AVE City: JERSEY CITY State:NJ ZIP:07310 Country:US Phone:201-653-6900/800-248-2436 CAGE:83628

Ingred Name:CADMIUM OXIDE (SARA 302/313) (CERCLA) CAS:1306-19-0 RTECS #:EV1925000 Fraction by Wt: NEAR100% Other REC Limits:NONE RECOMMENDED OSHA PEL:0.2 MG (CD)/M3 DUST ACGIH TLV:0.01 M LD50 LC50 Mixture:LD50 (ORAL RAT) = 72 MG/KG Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:YES Health Hazards Acute and Chronic:ACUTE-MAY BE FATAL IF INHALED, SWALLOWED, OR ABSORBED THROUGH THE SKIN. CAUSES EYE & SKIN IRRITATION. IRRITATING TO RESPIRATORY TRACT. MAY CAUSE HEADACHE, NAUSEA, VOMITING. CHRONIC-DAMAGES RO KIDNEYS, LUNGS. CARCINOGEN. Explanation of Carcinogenicity:CONTAINS C [7440-43-9] WHICH IS LISTED BY NTP AND IARC AND REGULATED BY OSHA AS A CARCINOGEN.

Effects of Overexposure:NAUSEA, VOMITING, HEADACHE. Medical Cond Aggravated by Exposure:MFR GAVE NO INFORMATION OF MSDS.

First Aid:IF ANY IRRITATION PERSISTS OR SEVERE, GET MEDICAL ATTENTION. EYE:FLUSH W/WATER FOR 15 MIN. SKIN:WASH W/SOAP & WATER. REMOVE CONTAMINATED CLOTHING & L

AUNDER BEFORE REUSE. INHALED:REMOVE FROM CONTAMINAT ED AREA. AID OR RESTORE BREATHING AS NEEDED. INGESTED:WASH OUT MOUTH W/WATER & GET IMMEDIATE MEDICAL ATTENTION.

Flash Point:NONE

Autoignition Temp:Autoignition Temp Text:NONE

Lower Limits:NONE

Upper Limits:NONE

Extinguishing Media:USE EXTINGUISHING MEDIA APPROPRIATE FOR SURROUNDING FIRE.

Fire Fighting Procedures: WEAR SELF-CONTAINED BREATHING APPARATUS & FULL

PROTECTIVE CLOTHING TO PREVENT CONTACT W/SKIN & EYES. Unusual Fire/Explosion Hazard:THIS MATERIAL LIKE MOST MATERIAL IN POWDER FORM, IS CAPABLE OF CREATING A DUST EXPLOSION.

Spill Release Procedures: EVACUATE AREA. WEAR SELF-CONTAINED BREATHING APPARATUS, RUBBER BOOTS, & RUBBER GLOVES. WEAR DISPOSALBLE COVERALLS & DISCARD AFTER USE. SWEEP UP, PLACE IN BAG & HOLD FOR WASTE DISPOSAL. AVOID RAISING D UST. VENTILATE

AREA & WASH SITE	
AFTER COMPLETION.	
Neutralizing Agent:MFR GAVE NO INFORMATION OF MSDS	3.

=================== Handling and Storage =	
--	--

Handling and Storage Precautions:CAUTION:REACTS VIOLENTLY W/MAGNESIUM. KEEP TIGHTLY CLOSED. STORE IN A COOL, DRY PLACE. Other Precautions:NONE

======= Exposure Controls/Personal Protection ==========

Respiratory Protection:WEAR APPROPRIATE NIOSH/MSHA APPROVED RESPIRATOR. DO NOT BREATHE DUST. Ventilation:USE ONLY IN A CHEMICAL FUME HOOD. Protective Gloves:CHEMICAL RESISTANT GLOVES Eye Protection:SAFETY GOGGLES Other Protective Equipment:OTHER PROTECTIVE CLOTHING, SAFETY SHOWER & EYE BATH. Work Hygienic Practices:WASH THOROUGHLY AFTER HANDLING. Supplemental Safety and Health AVOID PROLONGED &/OR REPEATED EXPOSURE. DO NOT GET IN EYES, ON SKIN OR

ON CLOTHING.

HCC:N1 NRC/State Lic Num:NONE Spec Gravity:8.150 Appearance and Odor:RED -BROWN POWDER

Stability Indicator/Materials to Avoid:YES ACIDS, OXIDIZING AGENTS Stability Condition to Avoid:MFR GAVE NO INFORMATION OF MSDS. Hazardous Decomposition Products:NATURE OF DECOMPOSITION PRODUCTS NOT KNOWN.

Conditions to Avoid Polymerization: MFR GAVE NO INFORMATION OF MSDS.

Waste Disposal Methods:CONTACT A LICENSED PROFISSIONAL WASTE DISPOSA

SERVICE TO DISPOSE OF THIS MATERIAL I/A/W FEDERAL, STATE & LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and a

ssume responsibility for the suitability of this information to their particular situation.

L