View NSN Online: https://aerobasegroup.com/nsn/8040-00-664-4946

TACC INTERNATIONAL CORP. -- LIQUID TENT PATCHING ADHESIVE #MA602 MIL-C-2399B

8040-00-664-4946

============= Product Identification ==================

Product ID:LIQUID TENT PATCHING ADHESIVE #MA602 MIL-C-2399B

MSDS Date:06/10/1994

FSC:8040

NIIN:00-664-4946

MSDS Number: CCJWM === Responsible Party ===

Company Name: TACC INTERNATIONAL CORP.

Address: AIR STATION INDUSTRIAL PARK

Box:390

City:ROCKLAND

State:MA ZIP:02370 Country:US

Info Phone Num:617-878-7015

Emergency Phone Num:617-878-7015

CAGE:0HZU1

=== Contractor Identification ===

Company Name: TACC INTERNATIONAL CORP Address:AIR STATION INDUSTRIAL PARK

Box:City:ROCKLAND

State:MA ZIP:02370 Country:US

Phone:781-878-7015

CAGE:0HZU1

======= Composition/Information on Ingredients ========

Ingred Name:TOLUENE (SARA 313) (CERCLA) (VP = 22.0)

CAS:108-88-3

RTECS #:XS5250000 Fraction by Wt: 5-20%

Other REC Limits:300 PPM CEILING

OSHA PEL:100 PPM/STEL 1

00

ACGIH TLV:100 PPM/STEL 100

EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Ingred Name: ACETONE (SARA 313) (CERCLA) (VP = 182.0)

CAS:67-64-1

RTECS #:AL3150000 Fraction by Wt: 50-75%

Other REC Limits: NONE RECOMMENDED

OSHA PEL:750 PPM/STEL 1000 ACGIH TLV:750 PPM/STEL 1000

EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

========== Hazards Identification ================

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Ha

zards Acute and Chronic:INHALATION: ACUTE SIGNS OF

OVEREXPOSURE COULD BE HEADACHE, DIZZINESS, NAUSEA, UPPER RESPIRATORY DRYNESS OR IRRITATION, DROWSINESS, MENTAL DEPRESSION OR NARCOSIS, DIFFICULTY IN BREATHING. CHRONIC EFFEC TS OF OVEREXPOSURE TO SOLVENT VAPORS COULD LEAD TO PERMONENT NERVOUS SYSTEM/BODY ORGANS/BRAIN EFFECTS. USE **

Effects of Overexposure:**WITH ADEQUATE VENTILATION. EYES: IRRITATION. INGESTION: MAY BE HARMFUL OR FATAL IF SWALLOWED. SKIN: REMOVAL OF

SKIN OILS, IRRITATION, DERMATITIS, EVEN SENSITIZATION WITH OVEREXPOSURE.

First Aid:INHALATION: GET FRESH AIR. EYES: IF NECESSARY CALL A PHYSICIAN. FLUSH WITH WATER FOR AT LEAST 15 MINUTES, IF NECESSARY, CALL A PHYSICIAN. SKIN: WASH WITH MILD SOAP AND WATER APPLY A MILD CREAM. INGEST ION: CALL POISON CENTER IMMEDIATELY.

============ Fire Fighting Measures =========================

Flash Point Method:TC

C Flash Point: