

BF GOODRICH THE ADHESIVE PRODUCTS DIV -- A1177B2 -- 8040-00-152-0028

=====  
Product Identification  
=====

Product ID:A1177B2

MSDS Date:09/25/1991

FSC:8040

NIIN:00-152-0028

Kit Part:Y

MSDS Number: CCMNY

=== Responsible Party ===

Company Name:BF GOODRICH THE ADHESIVE PRODUCTS DIV

Address:500 MAIN ST

City:AKRON

State:OH

ZIP:44318

Country:US

Info Phone Num:216-374-3000 / FAX 216-374-2333

Emergency Phon

e Num:216-374-3000

Preparer's Name:C. PEARSON

CAGE:1HS43

=== Contractor Identification ===

Company Name:PIEDMONT ADHESIVE & SEALANT SYSTEMS, INC

Box:UNKNOW

CAGE:0CGS8

Company Name:SIA ADHESIVES INC

Address:123 W BARTGES ST

Box:City:AKRON

State:OH

ZIP:44311-1081

Country:US

Phone:330-374-2786 / 330-374-2900

CAGE:1HS43

=====  
Composition/Information on Ingredients  
=====

Ingred Name:POLYAMIDE

CAS:68410-23-1

Fraction by Wt: 50.0%

Other REC Limits:NONE RECOMMENDED

Ingred Name:CALCI

UM CARBONATE  
CAS:1317-65-3  
RTECS #:EV9580000  
Fraction by Wt: 50.0%  
Other REC Limits:NONE RECOMMENDED  
OSHA PEL:10 MG/M3  
ACGIH TLV:10 MG/M3

=====  
===== Hazards Identification =====

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO  
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO  
Health Hazards Acute and Chronic:SOME PEOPLE MAY DEVELOP ALLERGIC REACTION.  
Effects of Overexposure:MINOR TRANSIENT IRRITATION OF EYES & SKIN.  
Medical Cond Aggravated by Exposure :SKIN RASHES.

=====  
===== First Aid Measures =====

First Aid:EYE: FLUSH W/WATER 15 MINUTES HOLDING LIDS OPEN. SEE DR.  
SKIN: WASH W/SOAP & WATER. SEE DR IF RASH DEVELOPS. INHALATION: REMOVE TO FRESH AIR. GIVE ARTIFICIAL RESPIRATION IF NOT BREATHING. CONSULT DR.

=====  
===== Fire Fighting Measures =====

Flash Point Method:TOC  
Flash Point:365F,185C  
Lower Limits:NA  
Upper Limits:NA  
Extinguishing Media:WATER FOG, CARBON DIOXIDE, FOAM &/OR DRY CHEMICAL.  
Fire Fighting Procedures:DON'T ENTER CONFINED FIRE SPACE W/O PROPER PROTECTIVE EQUIPMENT (NIOSH APPROVED SCBA).  
Unusual Fire/Explosion Hazard:FIRE MAY GIVE OFF TOXIC FUMES.

=====  
===== Accidental Release Measures =====

Spill Release Procedures:AVOID EYE/SKIN CONTACT. SCRAPE UP OR ABSORB & PLACE IN CONTAINER FOR DISPOSAL.

=====  
===== Handling and Storage =====

Handling and Storage Precautions:STORE IN COOL DR

Y AREA AWAY FROM HEAT  
SOURCES. KEEP AWAY FROM CHILDREN.

Other Precautions:NA

===== Exposure Controls/Personal Protection =====

Respiratory Protection:NOT NORMALLY NECESSARY. USE ORGANIC VAPOR FOR  
FUMES FROM HEATED MATERIAL.

Ventilation:LOCAL AT A POINT OF CORE OR HEATING.

Protective Gloves:NEOPRENE

Eye Protection:GOGGLES

Other Protective Equipment:EYEWASH & SHOWER IN AREA.

Supplemental Safety and Health

NK

===== Physical/Chemical Properties =====

=====

Boiling Pt:B.P. Text:400F,204C

Decomp Temp:Decomp Text:400F,204C

Spec Gravity:1.422

Evaporation Rate & Reference:NA

Solubility in Water:NIL

Appearance and Odor:THICK BROWN LIQUID, AMINE ODOR

Percent Volatiles by Volume:0.0

Corrosion Rate:NA

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

EPOXY TYPE MATERIALS IN UNCONTROLLED CONDITIONS.

Hazardous Decomposition Products:CARBON DIOXIDE, CARBON MONOXIDE,  
AMMONIA, OTHER

TOXIC FUMES.

===== Disposal Considerations =====

Waste Disposal Methods:MAY BE HAZARDOUS IF DISCARDED. DISCARD ACCORDING  
TO LOCAL, STATE, FEDERAL REGS. INCINERATION IS THE PREFERRED  
METHOD.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department  
of Defense. The United States of America in no manner whatsoever,  
expressly or implied, warrants this information to be a

ccurate and  
disclaims all liability for its use. Any person utilizing this  
document should seek competent professional advice to verify and  
assume responsibility for the suitability of this information to their  
particular situation.