

RALRUBE -- FA 1030 NEUTRAL -- 8040-00-515-2246

===== Product Identification =====

Product ID:FA 1030 NEUTRAL

MSDS Date:03/22/1993

FSC:8040

NIIN:00-515-2246

Kit Part:Y

MSDS Number: CGNFN

=== Responsible Party ===

Company Name:RALRUBE

Address:36977 FOX GLENN

City:FARMINGTON HILLS

State:MI

ZIP:48331

Country:US

Info Phone Num:810-661-3941 FAX

Emergency Phone Num:810-661-0260

CAGE:KO232

=== Contractor

Identification ===

Company Name:RALRUBE

Address:36977 FOCX GLEN

Box:City:FARMINGTON HILLS

State:MI

ZIP:48331

Country:US

Phone:810-661-0261

CAGE:KO232

Company Name:RALRUBE INC.

Address:36977 FOX GLEN

Box:City:FARMINGTON HILLS

State:MI

ZIP:48331

Country:US

Phone:248-661-0260, FAX 248-661-3941

CAGE:6X798

===== Composition/Information on Ingredients =====

Ingred Name:TOLUENE (SARA 313) (CERCLA)

CAS:108-88-3

RTECS #:XS5250000

Fraction by Wt: 45.0%

Other REC Limits:NONE RECOMMENDE

D  
OSHA PEL:100 PPM  
ACGIH TLV:100 PPM  
EPA Rpt Qty:1000 LBS  
DOT Rpt Qty:1000 LBS

Ingred Name:HEXANE (N-HEXANE) (CERCLA)  
CAS:110-54-3  
RTECS #:MN9275000  
Fraction by Wt: 31.0%  
Other REC Limits:NONE RECOMMENDED  
OSHA PEL:50 PPM  
ACGIH TLV:50 PPM  
EPA Rpt Qty:1 LB  
DOT Rpt Qty:1 LB

Ingred Name:POLYCHLOROPRENE RUBBER  
CAS:9010-98-4  
RTECS #:EI9640000  
Other REC Limits:NONE RECOMMENDED

Ingred Name:CALCIUM CARBONATE  
CAS:1317-65-3  
RTECS #:EV9580000  
Other REC Limits:NONE RECOMMENDED

Ingred Name:TSR # 139725000  
2-5027P TRADESECRET  
Other REC Limits:NONE RECOMMENDED

Ingred Name:VOC = 5.49 G/L  
RTECS #:9999999VO  
Other REC Limits:NONE RECOMMENDED  
OSHA PEL:NOT RELEVANT  
ACGIH TLV:NOT RELEVANT

=====  
===== Hazards Identification =====

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES  
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO  
Health Hazards Acute and Chronic:EYE: IRRITATION. SKIN: DRYNESS,  
CRACKING. INHAL: NAUSEA, NARCOSIS, LIVER ABNORMALITIES, CNS  
AFFECTS

, PERIPHERAL NERVE TISSUE DAMAGE. INGEST: VOMIT, NUMBNESS,  
TINGLING, WEAKNESS OF ARMS/LEGS. CHRONIC: NERVE DAMAGE.  
Medical Cond Aggravated by Exposure:RESPIRATORY AILMENTS

===== First Aid Measures =====

First Aid:EYE: FLUSH W/WATER. SKIN: WASH W/SOAP AND WATER. INGEST: DONT  
INDUCE VOMIT. INHAL: REMOVE TO FRESH AIR. OXYGEN OR CPR IF NEEDED.  
IN ALL CASES, GET IMMED MED AID.

===== Fire Fighting Measures =====

F  
lash Point Method:TCC  
Flash Point: