View NSN Online: https://aerobasegroup.de/nsn/5610-00-236-4964

GIBSON-HOMANS CO -- BLACK JACK ALL WEATHER RF CMT -- 5610-00-236-4964

Product ID:BLACK JACK ALL WEATHER RF CMT

MSDS Date:10/12/1990

FSC:5610

NIIN:00-236-4964 Status Code:A

MSDS Number: CHXQB === Responsible Party ===

Company Name: GIBSON-HOMANS CO Address: 1755 ENTERPRISE PARKWAY

City:TWINSBURG

State:OH ZIP:44087 Country:US

Info Phone Num:216-467-8128

Emergency Pho

ne Num:216-425-3255

CAGE:GIBHO

=== Contractor Identification ===

Company Name: GIBBSON-HOMANS CO Address: 1755 ENTERPRISE PARKWAY

Box:City:TWINSBURG

State:OH ZIP:44087 Country:US

Phone:216-467-8128

CAGE:0U534

Company Name: GIBSON-HOMANS CO Address: 1755 ENTERPRISE PARKWAY

City:TWINSBURG

State:OH ZIP:44087 Country:US

Phone:216-425-3255

CAGE:GIBHO

======= Composition/Information on Ingredients ========

Ingred Name:STODDARD SOLVENT

CAS:8052-41-3

RTECS #:WJ8925000 Fraction by Wt: 10-30%

0

SHA PEL:500 PPM ACGIH TLV:100 PPM ========== Hazards Identification ================ LD50 LC50 Mixture: NONE SPECIFIED BY MANUFACTURER. Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:ACUTE: SKIN: PROLONGED/REPEATED CONTACT MAY CAUSE IRRITATION. EYES: MAY CAUSE IRRITATION, BLURRED VISION. INHALATION: EXCESSIVE BREATHING OF HIGH VAPOR CONCENTRATIONS CAN CAUSE NASAL AND RES PIRATORY I RRITATION. DIZZINESS, NAUSEA, POSSIBLE UNCONSCIOUSNESS AND EVEN ASPHYXIATION. INGESTION: CAN CAUSE (EFTS OF OVEREXP) Explanation of Carcinogenicity: NOT RELEVANT. Effects of Overexposure: HLTH HAZ: GASTROINTESTINAL IRRITATION, NAUSEA, VOMITING AND DIARRHEA. ASPIRATION OF MATERIAL INTO LUNGS CAN CAUSE CHEMICAL PNEUMONITIS WHICH CAN BE FATAL. Medical Cond Aggravated by Exposure: PRE-EXISTING LUNG AND SKIN DISORDERS. ======= First Aid Measures ======= First Aid:SKIN: WASH WITH SOAP AND WATER. EYES: FLUSH WITH LARGE AMOUNTS OF WATER FOR AT LEAST 15 MINUTES. INHALATION: REMOVE PERSON FROM AFFECTED AREA. IF BREATHING IS DIFFICULT ADMINISTER OXYGEN. IF BREATHING HAS STOPPED GIVE ARTIFICIAL RESPIRATION, INGESTION: DO NOT INDUCE VOMITING. SEEK MEDICAL ATTENTION IMMEDIATELY. Flash Point Method: PMCC Flash Point: 105F,41C Lower Limits:0.8% **Upper Lim** its:7.0% Extinguishing Media: FOAM, CARBON DIOXIDE, DRY CHEMICALS.

Extinguishing Media:FOAM, CARBON DIOXIDE, DRY CHEMICALS. Fire Fighting Procedures:USE NIOSH APPROVED SCBA & FULL PROTECTIVE EQUIPMENT. WATER MAY CAUSE FROTHING, APPLY CAUTIOUSLY.

Unusual Fire/Explosion Hazard: KEEP AWAY FROM SOURCES OF IGNITION.

======== Accidental Release Measures ===========

Spill Release Procedures:DIKE SPILL AREA. RECOVER FREE LIQUID, ADD ABSORBENT TO SPILL AREA. REMOVE SOURCES OF IGNITION. VENTILATE AREA IF NECESSARY.

Neutralizing A

gent:NONE SPECIFIED BY MANUFACTURER.
======================================
Handling and Storage Precautions:KEEP AWAY FROM SOURCES OF IGNITION. USE ONLY WITH ADEQUATE VENTILATION. AVOID PROLONGED/REPEATED CONTACT WITH SKIN. Other Precautions:KEEP OUT OF THE REACH OF CHILDREN.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:NOT NORMALLY NEEDED IN WELL VENTILATED AREA. IF TLV IS EXCEEDED, A NIOSH APPROVED BREA THING APPARATUS IS RECOMMENDED. Ventilation:AS NECESSARY TO MAINTAIN EXPOSURE BELOW TLV LEVEL. Protective Gloves:OIL RESISTANT GLOVES. Eye Protection:ANSI APPRVD CHEM WORKERS GOGGLES. Other Protective Equipment:ANSI APPRVD EYE WASH & DELUGE SHOWER. AS NECESSARY. Work Hygienic Practices:REMOVE CONTAMINATED CLOTHING, LAUNDER BEFORE REUSE. Supplemental Safety and Health NONE SPECIFIED BY MANUFACTURER.
========= Physical/Chemical Properties ==========
Boiling Pt:B. P. Text:>300F,>149C Vapor Pres:21 @ 25C Vapor Density:>1 Spec Gravity:1.1 Evaporation Rate & Description Rate & D