View NSN Online: https://aerobasegroup.de/nsn/3439-00-766-4711

\_\_\_\_\_

# AMERWAY INC

## -- 63/37 ROSIN CORE WIRE SOLDER

MSDS Safety Information

FSC: 3439 NIIN: 00-766-4711 MSDS Date: 01/01/2000 MSDS Num: CLMPM Product ID: 63/37 ROSIN CORE WIRE SOLDER MFN: 01 Responsible Party Cage: 0J598 Name: AMERWAY INC Address: 3701 BEALE AVE City: ALTOONA PA 16601 Info Phon e Number: 800-829-6337; FX:814-9441463 Emergency Phone Number: (814) 944-0200
Item Description Information
Item Manager: S9G Item Name: SOLDER,TIN ALLOY Specification Number: QQ-S-571 Type/Grade/Class: SN63WRP2 Unit of Issue: SL Quantitative Expression: 0000000016OZ UI Container Qty: 1 Type of Container: SPOOL
Ingredients ======
<pre>====================================</pre>
LD50 LC50 Mixture: NO DATA PROVIDED BY MANUFACTURER Route Of Entry Inds - Inhalation: YES Skin: NO Ingestion: YES Effects of Exposure: EYE: DUST OR FUME COULD BE IRRITANT TO EYE

Effects of Exposure: EYE: DUST OR FUME COULD BE IRRITANT TO EYES , NOSE & amp; THROAT. SKIN: NOT A ROUTE OF ENTRY INTO THE BODY. INGESTION: INGE

STION OF DUST OR FUME MUST BE AVOIDED. LEAD IS TOXIC & amp; CUMULATIVE, AFFECTING THE K IDNEYS, REPRODUCTIVE SYSTEM & amp; NERVOUS SYSTEM. SYMPTOMS OF CHRONIC OVEREXPOSURE INCLUDE ANEMIA, INSOMNIA, WEAKNESS, IRRITABILITY, CONSTIPATION & STOMACH PAINS. TIN IS NOT REGARDED AS TOXIC BUT EXCESSIV E EXPOSURE CAN CAUSE FEVER, NAUSEA, STOMACH CRAMPS OR DIARRHEA. INHALATION: INHALATION OF DUST & amp; FUMES MUST BE AVOIDED. IRRITATION OF NOSE & amp; BRONCHIAL TRACTS MAY OCCUR AS WELL AS EFF ECTS DUE TO ABSORP TION OF LEAD, ETC. IN BLOOD STREAM. Explanation Of Carcinogenicity: NO DATA PROVIDED BY MANUFACTURER Signs And Symptions Of Overexposure: EYE: DUST OR FUME COULD BE IRRITANT TO EYES, NOSE & amp; THROAT. INGESTION: LEAD IS TOXIC & amp; CUMULATIVE, AFFECTING THE KIDNEYS, REPRODUCTIVE SYSTEM & amp; NERVOUS SYSTEM. SYMPTOMS OF CHRONIC OVEREXPOSURE INCLUD E ANEMIA, INSOMNIA, WEAKNESS, IRRITABILITY, CONSTIPATION & amp; STOMACH PAINS. TIN IS NOT REGARDED AS TOXIC BUT EXCESSIVE EXPOSURE CAN CAUSE FEVER, NAUSEA, STOMACH CRAMPS OR DIARRHEA. INHALATION: IRRITATION OF NOSE & amp; BRONCHIAL TRACTS MAY OCCUR AS WELL AS EFFECTS DUE TO ABSORPTION OF LEAD, ETC. IN BLOOD STREAM. Medical Cond Aggravated By Exposure: NO DATA PROVIDED BY MANUFACTURER \_\_\_\_\_ Handling and Disposal \_\_\_\_\_\_ Spill Release Procedures: ALLOW TO SOLIDIFY AND COLLECT IN SEALED DRUMS FOR DISPOSAL. Neutral izing Agent: NO DATA PROVIDED BY MANUFACTURER Waste Disposal Methods: RETURN TO SUPPLIER FOR REPROCESSING. Handling And Storage Precautions: STORE IN DRY CONDITIONS. LEAD USE IS REGULATED UNDER OSHA 29 CFR 1910.1025. NO FOOD OR DRINK SHOULD BE ALLOWED IN AREAS WHERE THESE PRODUCTS ARE HANDLED. PERSONNEL MUST WASH THOROUGHLY AFTER HANDLING THE METAL BEFORE DRINKING, EATING OR SMOKING. Other Precautions: NO DATA PROVIDED BY MANUFACTURER \_\_\_\_\_ Fire and Explosion Hazard Information \_\_\_\_\_ Flash Point: =176.7C, 350.F Flash Point Text: FLUX ONLY Fire Fighting Procedures: IF METAL IS PRESENT WHERE THERE IS A FIRE, WEAR SELF-CONTAINED BREATHING APPARATUS IN CASE OF POISONOUS LEAD FUMES. Unusual Fire/Explosion Hazard: NONE. \_\_\_\_\_ **Control Measures** 

\_\_\_\_\_

Respiratory Protection: RESPIRATORY

PROTECTION IS RECOMMENDED BUT ONLY REQUIRED IF TLV'S ARE EXCEEDED. USE A NIOSH/MSHA APPROVED RESPIRATOR FOR TOXIC DUST AND/OR FUME. NOTE: SEE 29 CFR 1910.1025 SUBPART (F) OF OSHA'S LEAD ST ANDARD. Ventilation: IF FUME OR DUST IS BEING GENERATED, MECHANICAL VENTILATION MUST BE PROVIDED TO MAINTAIN EXPOSURE LEVELS BELOW TLV'S. Protective Gloves: NOT NORMALLY NEEDED. Eye Protection: WEAR SAFETY GLASSES DURING SOLDERING OPERATIONS. Work Hygienic Practices: NO FOOD OR DRINK SHOULD BE ALLOWED IN AREAS WHERE THESE PRODUCTS ARE HANDLED. PERSONNEL MUST WASH THOROUGHLY AFTER HANDLING THE METAL BEFORE DRINKING, EATING OR SMOKING. Supplemental Safety and Health: NO DATA PROVIDED BY MANUFACTURER \_\_\_\_\_ Physical/Chemical Properties \_\_\_\_\_ HCC: N1 Melt/Freeze Pt: =182.8C, 361.F Vapor Pres: NOT VOLATILE Spec Gravity: 7-11 APPROX., DEPENDING Solubility in Water: NIL Appearance and Odor: SILVER/G RAY COLORED METAL WIRE; SLIGHT ODOR. Percent Volatiles by Volume: 0-4% \_\_\_\_\_ **Reactivity Data** \_\_\_\_\_\_ Stability Indicator: YES Materials To Avoid: STRONG ACIDS, OXIDIZERS, REDUCING AGENTS Hazardous Decomposition Products: LEAD FUMES AT HIGH TEMPERATURES (ABOVE 800 DEGREES F). Hazardous Polymerization Indicator: NO Conditions To Avoid Polymerization: WILL NOT OCCUR. \_\_\_\_\_ \_\_\_\_\_ **Toxicological Information** \_\_\_\_\_ Toxicological Information: NO DATA PROVIDED BY MANUFACTURER \_\_\_\_\_ **Ecological Information** Ecological: NO DATA PROVIDED BY MANUFACTURER \_\_\_\_\_ **MSDS** Transport Information \_\_\_\_\_

Transport In

formation: NOT REGULATED FOR TRANSPORTATION. **Regulatory Information** \_\_\_\_\_ Sara Title III Information: THIS PRODUCT CONTAINS A CHEMICAL SUBJECT TO SECTION 313 OF SARA TITLE III. Federal Regulatory Information: NO DATA PROVIDED BY MANUFACTURER State Regulatory Information: NO DATA PROVIDED BY MANUFACTURER Other Information \_\_\_\_\_ \_\_\_\_\_ Other Information: NO DATA PROVIDED BY MANUFACTURER \_\_\_\_\_ Transportation Information \_\_\_\_\_ **Responsible Party Cage: 0J598** Trans ID NO: 159050 Product ID: 63/37 ROSIN CORE WIRE SOLDER MSDS Prepared Date: 01/01/2000 Review Date: 09/27/2001 **MFN: 1** Net Unit Weight: 1 LB Multiple KIT Number: 0 Unit Of Issue: SL Container QTY: 1 Type Of Container: SPOOL Addit ional Data: NOT REGULATED PER MSDS. Detail DOT Information \_\_\_\_\_ DOT PSN Code: ZZZ DOT Proper Shipping Name: NOT REGULATED BY THIS MODE OF TRANSPORTATION \_\_\_\_\_ Detail IMO Information

\_\_\_\_\_

#### IMO PSN Code: ZZZ

IMO Proper Shipping Name: NOT REGULATED FOR THIS MODE OF TRANSPORTATION

\_\_\_\_\_

**Detail IATA Information** 

IATA PSN Code: ZZZ IATA Proper Shipping Name: NOT REGULATED BY THIS MODE OF TRANSPORTATION

\_\_\_\_\_

**Detail AFI Information** 

\_\_\_\_\_

# AFI PSN Code: ZZZ

AFI Proper Shipping Name: NOT REGULATED BY THIS MODE OF TRANSPORTATION

\_\_\_\_\_

# HAZC

OM Label

\_\_\_\_\_

Product ID: 63/37 ROSIN CORE WIRE SOLDER Cage: 0J598 Company Name: AMERWAY INC Street: 3701 BEALE AVE **City: ALTOONA PA** Zipcode: 16601 Health Emergency Phone: (814) 944-0200 Label Required IND: Y Date Of Label Review: 09/27/2001 Status Code: A Year Procured: 2001 Origination Code: F Eye Protection IND: YES Skin Protection IND: YES Signal Word: CAUTION **Respiratory Protection IND: NO** Health Hazard: Slight Contact Hazard: None Fire Ha zard: None Reactivity Hazard: None Hazard And Precautions: TARGET ORGANS: N/P. EYE: DUST OR FUME COULD BE IRRITANT TO EYES, NOSE & amp; THROAT. INGESTION: INGESTION OF DUST OR FUME MUST BE AVOIDED. LEAD IS TOXIC & amp; CUMULATIVE, AFFECTING THE KIDNEYS, REPRODUCTIVE S YSTEM & amp; NERVOUS SYSTEM. TIN IS NOT REGARDED AS TOXIC BUT EXCESSIVE EXPOSURE CAN CAUSE FEVER, NAUSEA, STOMACH CRAMPS OR DIARRHEA. INHALATION: INHALATION OF DUST & amp; FUMES MUST BE AVOIDED. IRRITATION OF N OSE & amp; В

Disclaimer (provided with this information by the compiling agencies): This

information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever expressly or implied warrants, states, or intends said information to have any application, use or viability by or to any person or per

sons outside the Department of Defense

nor any person or persons contracting with any instrumentality of the United States of America and disclaims all liability for such use. Any person utilizing this instruction who is not a military or civilian employee of the United States of America should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation regardless of similarity to a corresponding Departm ent

of Defense or other government situation.