

THREE BOND OF AMERICAN,INC. -- TB 1361A -- 8030-00-067-6744

=====
Product Identification
=====

Product ID:TB 1361A
MSDS Date:01/01/1987
FSC:8030
NIIN:00-067-6744
MSDS Number: BCXCY
=== Responsible Party ===
Company Name:THREE BOND OF AMERICAN,INC.
Emergency Phone Num:213-879-9143
CAGE:60859
=== Contractor Identification ===
Company Name:THREE BOND OF AMERICA,INC.
Address:20815 HIGGINS COURT
Box:C
City:TORRANCE
State:CA
ZIP:90501
Country:US
Phone:310-320-3342
CAGE:60859

=====
Composition/Information on Ingredients
=====

Ingred Name:DIMETHACRYLATE ESTERS
Fraction by Wt: 94.0%

Ingred Name:TERTIARY AMINE
Fraction by Wt: 2.8%

Ingred Name:CATALYST
Fraction by Wt: 3.2%

=====
Hazards Identification
=====

Effects of Overexposure:EYE/SKIN IRRITANT. POTENTIAL SKIN SENSITIZER.

=====
First Aid Measures
=====

==

First Aid:SKIN:FLUSH WITH WATER. EYES:FLUSH WITH WATER FOR 15 MIN. CALL DR. WASH SOILED CLOTHES BEFORE REUSE. DISCARD CONTAMINATED SHOES.

=====
===== Fire Fighting Measures =====

Flash Point:> 200 F, 93 C CC

Extinguishing Media:FLAM,CO*2 OR DRY CHEM.,WATERSPRAY

Fire Fighting Procedures:COOL ALL CONTAINERS NOT IGNITED WITH FIRE HOSES.

Unusual Fire/Explosion Hazard:RAPID POLYMERIZATION MAY OCCUR AT HIGH TEMP. SMOKE MAY CONTAIN MONOMER-IRRITATE LUNGS.

=====
===== Accidental Release Measures =====

Spill Release Procedures:AVOID EYE AND SKIN CONTACT, OR ORAL INGESTION. WEAR PROTETIVE EQUIP.WASH AREA WELL AND COLLECT MATERIAL FOR INCINERTION.

=====
===== Handling and Storage =====

Handling and Storage Precautions:STORE IN A COOL PLACE OUT OF DIRECT SUNLIGHT.CHENGE OF CLOTHING SHOULD BE AVAILABLE.AT END OF SHIFT WORKER SHOULD SHOWER TO REMOVE VAPORS FROM PORES.

Other Precaution

s:FIRE FIGHTERS MUST WEAR SELF-CONTAINED AIR SUPPLY. SHOES SHOULD BE AIRED OUT DAILY.

=====
===== Exposure Controls/Personal Protection =====

Respiratory Protection:NO SPECIAL VENTILATION REQUIRED

Ventilation:LOCAL EXHAUST,NORMAL VENTILATION ADEQUATE

Protective Gloves:IMPERVIOUS

Eye Protection:CHEM.SAFETY GOGGLES

Other Protective Equipment:IMPERVIOUS OVERSHOES AND PROTECTIVE CLOTHING.

Supplemental Safety and Health

=====
===== Physical/Chemical Properties =====

=====

HCC:N1

Boiling Pt:B.P. Text:> 6000 F

Evaporation Rate & Reference:< ETHER

Appearance and Odor:RED LIQUID

Percent Volatiles by Volume:0.5

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:NO

PEROXIDES,STRONG OXIDIZING AGENTS,IRON RUST,STRONG BASES

Stability Condition to Avoid:> 90 F, EXPOSURE TO LIGHT,OPEN FLAME,METAL CONTACT,VACUUM

Hazardous Decomposition Products:CO AND CO*2

===== Disposal Considerations =====

Waste Disposal Methods:CHEM.INCINERTOR

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.