

DEFT CHEMICAL COMPANY -- 03-W-46 BASE,WHITE 37875,POLYURETHANE -- 8010-00-181-8285

=====
Product Identification
=====

Product ID:03-W-46 BASE,WHITE 37875,POLYURETHANE

MSDS Date:01/01/1985

FSC:8010

NIIN:00-181-8285

Kit Part:Y

MSDS Number: BDGTT

=== Responsible Party ===

Company Name:DEFT CHEMICAL COMPANY

Address:17451 VON KARMAN AVE

City:IRVINE

State:CA

ZIP:92714-6205

Country:US

CAGE:EO418

=== Con

tractor Identification ===

Company Name:DEFT CHEMICAL COATINGS

CAGE:EO418

Company Name:DEFT, INC.

Address:17451 VON KARMAN AVE

City:IRVINE

State:CA

ZIP:92614

Country:US

Phone:949-474-0400

CAGE:33461

=====
Composition/Information on Ingredients
=====

Ingred Name:METHYL ETHYL KETONE (2-BUTANONE) (MEK) (SARA III)

CAS:78-93-3

RTECS #:EL6475000

Fraction by Wt: 10.0%

OSHA PEL:200 PPM/300 STEL

ACGIH TLV:200 PPM/300STEL 9192

EPA Rpt Qty:5000 LBS

DOT Rpt Qty:5000 LBS

Ingred Name:2-

ETHOXYETHYL ACETATE (CELLOSOLVE ACETATE) (EGEEA)

CAS:111-15-9

RTECS #:KK8225000

Fraction by Wt: 20.0%

OSHA PEL:S,100 PPM

ACGIH TLV:S, 5 PPM; 9192

Ingred Name:ETHYL ACETATE (CAS #141-78-6)

RTECS #:AH4250000

Fraction by Wt: 11.0%

ACGIH TLV:400 PPM

Ingred Name:NON-AQUEOUS SOLUTION,HAZARD UNKNOWN,UNIDENTIFIED (% WT BY DIFFERENCE)

Fraction by Wt: 59.0%

=====
Hazards Identification
=====

Effects of Overexposure:EYES :MODERATE IRRIT;SKIN:POSSIBLE IRRIT BY
S
OLVENTS;INH:SOLVENT VAPORS CAN CAUSE IRRIT OR NARCOSIS.

=====
First Aid Measures
=====

First Aid:SKIN:WIPE OFF WITH A RAG THEN THOROUGH RINSING W/H*2O &
WASHING W/MILD SOAP AND WATER;EYES:FLUSH W/WATER FOR AT LEAST 10
MIN & CONSULT AN EYE PHYSICIAN;INH:REMOVE TO FRESH AIR.GIVE
CPR/OXYGEN IF NEEDED.

=====
Fire Fighting Measures
=====

Flash Point:20F(-6.6C)-OC

Lower Limits:1.6

Extinguishing Media:CO*2, FOAM, D
RY CHEM & H*2O FOG.

Fire Fighting Procedures:WEAR SELF-CNTND BRTHG APP:H*2O SPRAY TO COOL
CONTR.

Unusual Fire/Explosion Hazard:CAUTION AGAINST APPLICATION TO HOT
SURFACES & USE IN AREASWHERE SOURCES OF IGNITION MAY BE PRESENT.

=====
Accidental Release Measures
=====

Spill Release Procedures:ELIMINATE IGNITION SOURCES. STOP LEAK.
EVACUATE AREA.DO NOT TOUCH SPILLAGE. SM SPILL:ABSORB W. INERT
ABSORBENT. PLACE IN CLOSED CONTAINER. FLUSH AREA W. WATER. LG

SPILL:DIKE AHEAD FOR LATER DISPOSAL. NOTIFY AUTHORITIES.

=====
===== Handling and Storage =====

Handling and Storage Precautions:STORE IN COOL,DRY,WELL VENT,LOW FIRE RISK AREA. PROTECT FROM PHYSICAL DAMAGE.AVOID ANY PHYSICAL CONTACT. KEEP CONTAINERS TIGHTLY CLOSED.

Other Precautions:AVOID PROLONGED INHALATION OF VAPORS.IF VENTILATION IS POOR,USE A FRESH AIR SUPPLY MASK.DO NOT USE H*2O STREAM ON FIR.H*2O SPRAY/FOG CAN BE USED EFFECTLY.

=====
===== Exposure Controls/Personal Protection =====

Respiratory Protection:WEAR SCBA,IN FIRE, OTHERWISE NIOSH APPRVD RESPIR Ventilation:MECH(GEN)OR LOCAL EXHAUST THAT PROVIDES ADEQUATE VENTILATION

Protective Gloves:RUBBER/NEOPRENE

Eye Protection:SAFETY/CHEM GOGGLES

Other Protective Equipment:FULL WORK CLOTHING TO PREVENT REPEATED OR PROLONGED CONTACT.

Supplemental Safety and Health

TWO PART RESIN MODIFIED POLYURETHANE COATING;THIS DATA IS FOR BASE;SEE P/N IND "A" DATA FOR CATALYST;SPEC REF:MIL-C-83286B,GRADE B

=====
===== Physical/Chemical Properties =====

Boiling Pt:B.P. Text:169F

Vapor Pres:16

Vapor Density:>1.0

Spec Gravity:1.26

Evaporation Rate & Reference: