View NSN Online: https://aerobasegroup.de/nsn/9150-00-273-8663

Product ID:WELCH DUOSEAL HIGH VACUUM PUMP OIL #1407K MSDS Date:08/29/1991 FSC:9150 NIIN:00-273-8663 MSDS Number: BDSBP === Responsible Party === Company Name: WELCH VACUUM TECHNOLOGY (FORMERLY SARGENT-WELCH CO Address:7300 N LINDER AVE Box:1026 City: SKOKIE State:IL ZIP:60077-3217 Country:US Info Phone Num:312-267-5300 Emergency Phone Num:312-267-5300 CAGE:IO538 === Contractor Identification === Company Name: SARGENT-WELCH SCIENTIFIC CO Address:7300 N LINDER AVE Box:1026 City:SKOKIE State:IL ZIP:60076 Country:US Phone:312-267-5300 CAGE:64484 Company Name: WELCH VACUUM TECHNOLOGY INC/THOMAS INDUSTRIES INC Address:7300 NORTH LINDER AVE Box:183 City:SKOKIE State:IL ZIP:60076-0183 Country:US Phone:708-676-8800 EXT. 1 CAGE:IO538

====== Com

position/Information on Ingredients =========

Ingred Name:MINERAL OIL, PETROLEUM DISTILLATES, SOLVENT-DEWAXED HEAVY PARAFFINIC CAS:64742-65-0 RTECS #:PY8038500 Fraction by Wt: 100% Other REC Limits:NONE SPECIFIED ACGIH TLV:5 MG/M3 (OIL MIST)

Ingred Name:REFINED HEAVY PARAFFINIC DISTILLATES CAS:64741-88-4 Fraction by Wt: SEE #1% Other REC Limits:NONE SPECIFIED OSHA PEL:5 MG/M3 (OIL MIST) ACGIH TLV:5 MG/M3 (OIL MIST)

LD50 LC50 Mixture:LD50 (ORAL RAT)=15G/KG Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic: EYES/SKIN: IRRITATION. AVOID BREATHING OF MIST. PROLONGED OVEREXPOSURE MAY RESULT IN DERMATITIS AND RESPIRATORY DIFFICULTIES. ANIMAL STUDIES ALSO SHOW AN EFFECT ON THE KIDNEYS FOR EXPOSURE TO MATERIAL S SIMILAR TO THIS. AT HIGH TEMPERATURES, MISTS ABOVE TLV MAY CAUSE LUNG DAMAGE. Explanation of Carc inogenicity:NONE OF THE CHEMICALS IN THIS PRODUCT IS LISTED BY IARC, NTP OR OSHA AS A CARCINOGEN. Effects of Overexposure: IRRITATION OF EYES AND SKIN UPON CONTACT. IRRITATION OF THE RESPIRATORY TRACT, HEADACHES, DIZZINESS, ANESTHETIC EFFECT AND OTHER CENTRAL NERVOUS SYSTEM EFFECTS INCLUDING DEATH IN RARE CASES. INGESTION MAY CAUSE CRAMPS AND DIARRHEA. INHALATION MAY CAUSE BRONCHITIS OR PULMONARY IRRITATION. Medical Cond Aggravated by Exposure: PERSONS WITH A HISTORY OF EYE, S KIN AND RESPIRATORY DISORDERS MAY BE AT INCREASED RISK FROM EXPOSURE.

First Aid:EYE: IMMEDIATELY FLUSH WITH PLENTY OF WATER FOR 15 MINUTES. GET MEDICAL ATTENTION. SKIN: WASH WITH SOAP AND WATER. INHALATION: REMOVE TO FRESH AIR. IF BREATHING IS IRREGULAR OR HAS STOPPED, START RESU SCITATION AND ADMINISTER OXYGEN. GET MEDICAL HELP IMMEDIATELY. INGESTION: DO NOT INDUCE VOMITING. GET MEDICAL ATTENTION AT O NCE. IN CASE OF SUBCUTANEOUS OR INTRAMUSCULAR INJECTION, SEEK HELP AT ONCE.

Spill Release Procedures:WEAR PROTECTIVE EQUIPMENT, ELIMINATE SOURCES OF IGNITION, AND VENTILATE AREA AS REQUIRED. RECOVER FREE LIQUID. ABSORB SMALL SPILL WITH INERT MATERIAL. PLACE WASTE IN DOT APPROVED CONTAINER FOR DISPOSA L. KEEP MATERIAL FROM WATERWAYS.WASH SPILL AREA.

Neutralizing Agent:NONE

=======

Handling and Storage Precautions:STORE IN A COOL, DRY, WELL VENTILATED AREA AWAY FROM SOURCES OF IGNITION. KEEP CONTAINER CLOSED WHEN NOT IN USE. PROTECT FROM PHYSICAL DAMAGE.

Other Precautions: AVOID BREATHING OF MIST. MINIMIZE PERIODS OF EXPOSURE TO HIGH TEMPERATURE. AVOID WATER CONTAMINATION. SPILLS ARE SPILLERY AND A HAZARD TO PEDESTRIANS. CLEAN UP AT ONCE.

===== Exposure Controls/Personal Protection =====

=======

Respiratory Protection:NOT USUALLY REQUIRED.WHERE ENVIRNOMENTAL CONTROLS ARE LACKING USE A NIOSH RESPIRATOR FOR ORGANIC VAPORS AND MISTS.

Ventilation:LOCAL EXHAUST WHEN TLV IS EXCEEDED.

Protective Gloves:OIL IMPERVIOUS

Eye Protection: SAFETY GLASSES/CHEMICAL SPLASH GOGGLES

Other Protective Equipment:SAFETY SHOWER AND EYE BATH. INDUSTRIAL TYPE WORK CLOTHING AND APRON AS REQUIRED TO AVOID PROLONGED OR REPEATED CONTACT.

Work Hygienic Practices: WASH THOROUGHLY AFTER HANDLING

AND BEFORE EATING OR DRINKING. LAUNDER CONTAMINATED CLOTHING BEFORE REUSE. Supplemental Safety and Health USE AIR-SUPPLIED RESPIRATORY EQUIPMENT IF EXPOSED TO HOT FUMES. TREAT EMPTY CONTAINERS AS DANGEROUS; DO NOT PRESSURIZE, CUT, WELD, BRAZE, SOLDER, DRILL, GRIND OR EXPOSE CONTAINERS TO HEAT, FLAME, SPAR KS, PILOT LIGHTS, STATIC ELECTRICITY. RESIDUE MAY BE DIFFICULT TO REMOVE.

HCC:V6 NRC/State Lic Num:NO NE Boiling Pt:B.P. Text:750F,399C Vapor Pres:1 AIR=1 Spec Gravity:0.88 Evaporation Rate & amp; Reference: