

PETERSON HARRY S CO INC -- AEROBOND 2185 PART A -- 8040-00-463-7042

=====
Product Identification
=====

Product ID:AEROBOND 2185 PART A
MSDS Date:01/01/1987
FSC:8040
NIIN:00-463-7042
Kit Part:Y
MSDS Number: BDZLF
=== Responsible Party ===
Company Name:PETERSON HARRY S CO INC
Address:1565 INDUSTRIAL RD
City:SAN CARLOS
State:CA
ZIP:94070-5000
Country:US
Info Phone Num:415-592-8354/415-592-7900
Emerg
ency Phone Num:415-592-8354/415-592-7900
CAGE:FO335
=== Contractor Identification ===
Company Name:ADHESIVE ENGINEERING CO.
Address:1411 INDUSTRIAL CO.
Box:2449
City:SAN CARLOS
State:CA
ZIP:94070
Country:US
CAGE:17433
Company Name:PETERSON HARRY S CO INC
Address:1565 INDUSTRIAL RD
City:SAN CARLOS
State:CA
ZIP:94070-5000
Country:US
Phone:415-592-8354/415-592-7900
CAGE:FO335

=====
Composition/Information on Ingredients
=====

Ingred Name:MODIFIED EPOXY NOVOLAC RESIN

=====

=====
Hazards Identification
=====

Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:EYES: MAY CAUSE MINOR TRANSIENT
IRRITATION. SKIN: MAY CAUSE MINOR IRRITATION, MAY BE A SENSITIZER.
Explanation of Carcinogenicity:NONE
Effects of Overexposure:IRRITATION.

=====
First Aid Measures
=====

First Aid:SKIN: WASH W/SOAP & WATER. EYES: FLUSH W/WATER
. INHALATION:
REMOVE TO FRESH AIR. OBTAIN MEDICAL ATTENTION IN ALL CASES.

=====
Fire Fighting Measures
=====

Flash Point Method:TOC
Flash Point:>200F
Extinguishing Media:FOAM, CO2, DRY CHEMICAL.
Fire Fighting Procedures:AVOID BREATHING SMOKE.
Unusual Fire/Explosion Hazard:NONE

=====
Accidental Release Measures
=====

Spill Release Procedures:SOAK UP W/ABSORBENT MATERIAL. IF SOLVENTS ARE
USED, OBSERVE FIRE HAZARDS.

=====
=====
Handling and Storage
=====

Handling and Storage Precautions:STORE AT/