

GRACE,W.R.& CO.EMERSON&CUMING DEWEY&ALMY CHEM DIV. -- ECCOBOND SOLDER 57C,
PART B -- 8040-00-738-1780

=====
Product Identification
=====

Product ID:ECCOBOND SOLDER 57C, PART B

MSDS Date:01/01/1987

FSC:8040

NIIN:00-738-1780

Kit Part:Y

MSDS Number: BFMVF

=== Responsible Party ===

Company Name:GRACE,W.R.& CO.EMERSON&CUMING DEWEY&ALMY CHEM DIV.

Emergency Phone Num:617-828-3300

CAGE:LO871

=== Contract

or Identification ===

Company Name:GRACE W R & CO EMERSON & CUMING DEWEY & ALMY CHEM

Address:869 WASHINGTON ST

City:CANTON

State:MA

ZIP:02021-2513

Country:US

Phone:617-935-4850

CAGE:04552

Company Name:GRACE,W.R.& CO.EMERSON&CUMING DEWEY&ALMY CHEM DIV.

CAGE:LO871

=====
Composition/Information on Ingredients
=====

Ingred Name:NO INGREDIENT FOR THIS FORMULATION_INGREDIENT

=====
Hazards Identification
=====

Effects of Overexposure:IRRIT TO EYES

, NOSE & SKIN. HARMFUL IF

INGESTED. LONG TERM EXPOSURE MAY DISCOLOR SKIN.

=====
First Aid Measures
=====

First Aid:INHAL:RMV TO FRESH AIR. IF NOT BRTHNG GIVE CPR; IF BRTHNG
DIFF GIVE OXYGEN. EYE:IMMED FLUSH W/PLENTY OF WATER. SKIN:WASH
W/SOAP&WATER. RMV CONTAM CLTHG&SHOES. INGEST:INDUCE VOMIT. RPT
UNTIL VOMIT IS C LEAR. NOTHG BY MOUTH IF UNCONSC. GET MEDICAL ATTN.

=====
Fire Fighting Measures
=====

Flash

Point:>300F,149C

Extinguishing Media:CARBON DIOXIDE,DRY CHEMICAL,FOAM,WATER FOG

Fire Fighting Procedures:WEAR SCBA

Unusual Fire/Explosion Hazard:TOXIC FUMES MAY BE EVOLVED UPON EXPOSURE TO HEAT OR OPEN FLAME.

===== Accidental Release Measures =====

Spill Release Procedures:SM SPILL:WIPE UP OR ABSORB ON INERT MATL.
COLLECT WASTE IN SEALED CONTAINER. WASH RESIDUE W/SOAP & WATER. LG
SPILL:DIKE TO PREVENT SPREAD. SHOVEL/PUMP TO SALVAGE DRUM. ABSORB
RESID
UE ON INERT MATL. WA SH W/SOAP & WATER.

===== Handling and Storage =====

Handling and Storage Precautions:STORE IN CLOSED CONTAINERS BELOW
80F.PROTECT FROM PHYSICAL DAMAGE.AVOID IGNITION SOURCES & ACUTE
FIRE HAZARDS.

Other Precautions:NONE

===== Exposure Controls/Personal Protection =====

Respiratory Protection:WEAR NIOSH/MSHA APPROVED RESP WHEN VENT IS NOT
ADEQUATE.

Ventilation:LOCAL & MECHANICAL (GEN) ARE REQUIRED.

Protective

Gloves:RUBBER

Eye Protection:SAFETY GLASSES

Other Protective Equipment:FULL WORK CLOTHING TO PREVENT REPEATED OR
PROLONGED CONTACT.

Supplemental Safety and Health

MSDS DATED 5/28/85. PART OF A 2 PART KIT, SEE OTHER P/N IND,THIS NSN,
FOR ADDITIONAL INFORMATION.

===== Physical/Chemical Properties =====

HCC:N1

Vapor Pres:1

Spec Gravity:3.20

Appearance and Odor:SILVER COLORED PASTE

Percent Volatiles by Volume:0

===== Stability and Reactivity Data

=====

Stability Indicator/Materials to Avoid: YES
STRONG OXIDIZERS, ACIDS & EPOXIDES.
Stability Condition to Avoid: STORAGE IN OPEN CONTAINERS, EXPOSURE TO
HEAT/FLAME.
Hazardous Decomposition Products: CARBON MONOXIDE, CARBON DIOXIDE,
OXIDES OF NITROGEN.

===== Disposal Considerations =====

Waste Disposal Methods: LANDFILL I/A/W ALL LOCAL, STATE & FEDERAL
REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):
Th

is information is formulated for use by elements of the Department
of Defense. The United States of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document should seek competent professional advice to verify and
assume responsibility for the suitability of this information to their
particular situation.