View NSN Online: https://aerobasegroup.de/nsn/5910-00-752-4884

CORNELL DUBILIER ELEC DIV OF FED PAC ELEC CO -- KX23250/1 -- 5910-00-752-4884

Product ID:KX23250/1 MSDS Date:01/01/1985 FSC:5910 NIIN:00-752-4884 MSDS Number: BFMXN === Responsible Party === Company Name: CORNELL DUBILIER ELEC DIV OF FED PAC ELEC CO Address: ONE INTERCHANGE PLZ City:WAYNE State:NJ ZIP:07470 Country:US **Emergency Phone Num:NONE** CAGE:09023 === Contrac tor Identification === Company Name: CORNELL DUBILIER ELEC DIV FED PAC ELEC Address: ONE INTERCHANGE PLZ Box:B-967 **City:WAYNE** State:NJ ZIP:07470 Country:US Phone:201-694-8600 CAGE:09023 Company Name: CORNELL-DUBILIER ELECTRONICS Address: ONE INTERCHANGE PLZ Box:City:WAYNE State:NJ ZIP:07470 Country:US Phone:201-694-8600 CAGE:14655

Ingred Name:POLYCHLORINATED BIPHENYLS (PCBS) (SARA III) CAS:1336-36-3 RTECS #:TQ1350000 EPA Rpt Qty

======================================
Effects of Overexposure:ABSORBED THRU SKIN,LUNGS,INTESTINE.CAUSES CANCER,LIVER,KIDNEY,STOMACH,EYE,HEARING DISORDER(SUP DATA)
======================================
First Aid:EYES:FLUSH W/WATER IMMEDIATELY.SKIN:WASH W/SOAP IMMEDIATELY.INHAL:REMOVE TO FRESH AIR,GIVE ART.RESPIR.AS NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE QTY OF SALT WATER,INDUCE VOMITING,BUT DO NOT MAKE UNC ONSCIOUS PERSON VOMIT.
======================================
Spill Release Procedures: USE ABSORBENT & DIKES TO PREVENT RUNOFF. ISOLATE & NOTIFY PROPER AUTHORITIES.
======================================
Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENTS.
======================================
Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOOD
ilation:LOCAL EXHAUST Protective Gloves:RUBBER-IMPERV
Eye Protection: GOGGLES, FACE SHIELD
Other Protective Equipment: FULL CLOTHING TO PREVENT SKIN CONTACT Supplemental Safety and Health
OVEREXPOS:CAN CAUSE FORMATION OF CYSTS,CAUSES STILLBIRTHS.IRRITATES EYES,NOSE THROAT.
======================================
HCC:Z3 Appearance and Odor:LIGHT STRAW-COLORED LIQUID,AROMATIC ODOR
======================================

STRONG OXIDIZERS

Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED-GENERALLY HIGH TEMPERATURE INCINERATION.ONLY APPROVED DISPOSAL OPERATOR PERMITTED.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims

all liability for its use. Any person utilizing this

document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.