

CORNELL-DUBILIER ELEC DIV.OF FED.PAC.ELEC.CO. -- KGT4150 -- 5910-00-777-5548

=====
Product Identification
=====

Product ID:KGT4150

MSDS Date:01/01/1985

FSC:5910

NIIN:00-777-5548

MSDS Number: BFPCC

=== Responsible Party ===

Company Name:CORNELL-DUBILIER ELEC DIV.OF FED.PAC.ELEC.CO.

Address:1605 E RODNEY FRENCH BLVD

Box:B-967

City:NEW BEDFORD

State:MA

ZIP:02741-9990

Country:US

Emergency Phone Num:NO

NE

CAGE:93790

=== Contractor Identification ===

Company Name:CORNELL-DUBILIER ELECTRONICS

Address:1605 E RODNEY FRENCH BLVD

Box:B-967

City:NEW BEDFORD

State:MA

ZIP:02741-9990

Country:US

Phone:508-996-8561

CAGE:93790

=====
Composition/Information on Ingredients
=====

Ingred Name:POLYCHLORINATED BIPHENYLS (PCBS) (SARA III)

CAS:1336-36-3

RTECS #:TQ1350000

EPA Rpt Qty:1 LB

DOT Rpt Qty:1 LB

=====
Hazards Identification
=====

Effects of Overexpo

sure:ABSORBED THRU SKIN,LUNGS,INTESTINE.CAUSES
CANCER,LIVER,KIDNEY,STOMACH,EYE,HEARING DISORDER(SUP DATA)

=====
First Aid Measures
=====

First Aid:EYES:FLUSH W/WATER IMMEDIATELY.SKIN:WASH W/SOAP
IMMEDIATELY.INHAL:REMOVE TO FRESH AIR,GIVE ART.RESPIR. AS
NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE OTY OF SALT WATER,INDUCE
VOMITING,BUT DO NOT MAKE UN CONSCIOUS PERSON VOMIT.

=====
Accidental Release Measures
=====

Sp
ill Release Procedures:USE ABSORBENT & DIKES TO PREVENT
RUNOFF.ISOLATE & NOTIFYPROPER AUTHORITIES.

=====
Handling and Storage
=====

Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENTS.

=====
Exposure Controls/Personal Protection
=====

Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOOD
Ventilation:LOCAL EXHAUST
Protective Gloves:RUBBER-IMPERV
Eye Protection:GOGGLES,FACE SHIELD
Other Protective Equipme
nt:FULL CLOTHING TO PREVENT SKIN CONTACT
Supplemental Safety and Health
OVEREXPOS:CAN CAUSE FORMATION OF CYSTS,CAUSES STILLBIRTHS.IRRITATES
EYES,NOSE THROAT.

=====
Physical/Chemical Properties
=====

HCC:Z3
Appearance and Odor:LIGHT STRAW-COLORED LIQUID,AROMATIC ODOR

=====
Stability and Reactivity Data
=====

STRONG OXIDIZERS

=====
Disposal Considerations
=====

Waste Disposal Methods:CONTROLLED DISPOSAL

REQUIRED-GENERALLY HIGH

TEMPERATURE INCINERATION. ONLY APPROVED DISPOSAL OPERATOR PERMITTED.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this

document should seek competent professional advice to veri

fy and

assume responsibility for the suitability of this information to their

particular situation.