

CROWN INDUSTRIAL PRODUCTS CO., INC -- FAULT FINDER CLEANER 1071 -- 6850-00-826-0981

=====
Product Identification
=====

Product ID:FAULT FINDER CLEANER 1071

MSDS Date:01/16/1986

FSC:6850

NIIN:00-826-0981

Kit Part:Y

MSDS Number: BFRKC

=== Responsible Party ===

Company Name:CROWN INDUSTRIAL PRODUCTS CO., INC

Address:STATE LINE ROAD

City:HEBRON

State:IL

ZIP:60034

Country:US

Info Phone Num:815-648-242

4

Emergency Phone Num:815-648-2424

Preparer's Name:ROBERT E. BAYTON

CAGE:92381

=== Contractor Identification ===

Company Name:CROWN INDUSTRIAL PRODUCTS CO

Address:HWY 47 N

Box:350

City:HEBRON

State:IL

ZIP:60034

Country:US

Phone:815-648-2424

CAGE:92381

=====
Composition/Information on Ingredients
=====

Ingred Name:ISOPROPYL ALCOHOL (SARA III)

CAS:67-63-0

RTECS #:NT8050000

Fraction by Wt: 51-70%

OSHA PEL:400 PPM/500 STEL

ACGIH TLV:400 PPM/500STEL;9192

Ingred Name:CHLORINATED

HYDROCARBONS
Fraction by Wt: 40%
ACGIH TLV:1000 PPM

=====
===== Hazards Identification =====
=====

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:CAN CAUSE IRRITATION TO NOSE, THROAT,
RESPIRATORY TRACT, EYES, AND SKIN. PROLONGED EXPOSURE ABOVE OSHA
PERMISSIBLE EXPOSURE LIMITS MAY RESULT IN KIDNEY AND LIVER DAMAGE.
Effects of Overexposure:INHALATION: MAY BE IRRITATING T
O NOSE, THROAT,
AND RESPIRATORY TRACT. HIGH CONCENTRATION MAY RESULT IN CNS
DEPRESSION. INGESTION: HARMFUL IF SWALLOWED. MAY CAUSE CNS
DEPRESSION. EYES: LIQUID/VAPORS M AY CAUSE IRRITATION. SKIN:
MODERATE IRRITANT. PROLONGED OR REPEATED CONTACT DEFATTING AND
DRYING OF SKIN.
Medical Cond Aggravated by Exposure:PREEXISTING EYE, SKIN AND
RESPIRATORY DISORDERS MAY BE AGGRAVATED BY EXPOSURE TO THIS
PRODUCT.

=====
===== First Aid Measures =====
=====

First Aid:INGESTION: DRINK WATER.DO NOT INDUCE VOMITING.IF VOMITING
OCCURS, KEEP HEAD BELOW HIPS TO PREVENT ASPIRATION OF LIQUID INTO
THE LUNGS. CALL A DOCTOR. INHALATION: REMOVE TO FRESH AIR. GIVE
OXYGEN IF BR EATHING IS DIFFICULT GIVE ARTIFICIAL BREATHING AND
ADMINISTER OXYGEN. EYES: FLUSH WITH WATER FOR AT LEAST 15
MINUTES.GET MED ATTENTION IF IRRITATION PERSISTS.SKIN:WASH WITH
SOAP AND WATER.REMOVE CLOTH

=====
===== Fire Fighting Measures =====
=====

Flash Point:N/R (AEROSOL CAN
Lower Limits:1.8
Upper Limits:9.5
Extinguishing Media:WATER FOG, DRY CHEMICAL, FOAM, CARBON DIOXIDE
Fire Fighting Procedures:COOL EXPOSED CONTAINERS WITH WATER SPRAY.
Unusual Fire/Explosion Hazard:AEROSOPL CANS WILL EXPLODE IN HEAT OF
FIRE. TREAT AS CYLINDER OF COMPRESSED GAS. FACE SHIELDS, HELMETS
AND SELF CONTAINED BREATHING APPARATUS IS RECOMMENDED.

=====
===== Accidental Release Measures =====
=====

Spill Release Procedures:l

F LIQUID SPILLS OUT, VENTILATE AREA. REMOVE ALL SOURCES OF IGNITION. CLEAN UP WITH INERT MATERIALS. SEGREGATE AND REMOVE THE LEAKING AEROSOL CANS.

=====
===== Handling and Storage =====

Handling and Storage Precautions:DO NOT STORE IN DIRECT SUNLIGHT OR WHERE TEMPERATURE EXCEED 120F. AVOID SPLASH FILLING, OPEN FLAME, SPARKS. USE IN WELL-VENTILATED AREA.

Other Precautions:DO NOT SPRAY ON FLAMES, HOT SURFACES. AVOID INHALATION OF VAPORS. AVOID PHYSICAL DAMAGE TO THE CONTAINERS.

=====
===== Exposure Controls/Personal Protection =====

Respiratory Protection:USE NIOSH APPROVED RESPIRATOR TO PREVENT OVER-EXPOSURE IN ACCORDANCE WITH 29CFR1910.134

Ventilation:LOCAL EXHAUST IS ADEQUATE.

Protective Gloves:POLYETHYLENE OR NEOPRENE

Eye Protection:SAFETY GLASSES.

Other Protective Equipment:NONE

Work Hygienic Practices:AIR DRY CONTAMINATED CLOTHING AND LAUNDRER BEFORE RE-USE.

Supplemental Safety and Health

NSN FOR A KIT OF FOLLO

WING 3 PARTS: FAULT FINDER - CLEANER 1071, -

PENETRANT 1075 AND - DEVELOPER 1079. THIS ENTRY DESCRIBES CLEANER 1071 WHICH WAS GROUP 1 UNDER QPL-25135-13. NOW UNDER QPL-25135-15 IS TYPE II, FORM D CLEANER FOR MIL-I-25135, REVISION E; FOR OTHER PARTS, SEE PNI B & C OF THIS NSN; KEY1:F1

=====
===== Physical/Chemical Properties =====

HCC:V3

Vapor Pres:45-50 PSIG

Vapor Density:>1

Spec Gravity:>1

Evaporation Rate & Reference: