View NSN Online: https://aerobasegroup.com/nsn/8040-00-943-2502 B.F.GOODRICH CO. -- A934BY ADHESIVE PRIMER -- 8040-00-943-2502 Product ID:A934BY ADHESIVE PRIMER MSDS Date:01/01/1987 FSC:8040 NIIN:00-943-2502 MSDS Number: BFYLR === Responsible Party === Company Name: B.F.GOODRICH CO. Address:3925 EMBASSY PKY Box:5471 City:AKRON State:OH ZIP:44313-0471 Country:US **Emergency Phone Num:NONE** CAGE:MO329 === Contractor Identification Company Name: B.F.GOODRICH CO. Address:3925 EMBASSY PKY Box:5471 City: AKRON State:OH ZIP:44313-0471 Country:US CAGE:MO329 Company Name: BF GOODRICH CO Address:3925 EMBASSY PKY Box:5471 City:AKRON State:OH ZIP:44313-0471 Country:US Phone:216-374-3985 CAGE:25472 ======= Composition/Information on Ingredients ======== Ingred Name: ETHYL ALCOHOL (ETHANOL) CAS:64-17-5

RTECS #:KQ6300000 = Wt:100.

OSHA PEL:1000 PPM

ACGIH TLV:1000 PPM; 9192

======= Hazards Identification

=======================================
Effects of Overexposure:EYE:IRRIT,CORNEAL CLOUDING,SKIN:DEFAT,DERM.INHL:IRRIT,HEAD,NAUS,DIZZ,ASDAYX.INGEST:IN TOX,LOSS COORD.
======================================
First Aid:INHAL:RMV TO FRESH AIR. IF NOT BRTHNG GIVE CPR; IF BRTHNG DIFF GIVE OXYGEN. EYE:IMMED FLUSH W/PLENTY OF WATER. SKIN:WASH W/SOAP & WATER. RMV CONTAM CLTHG & SHOES. INGEST:DO NOT INDUCE VOMIT. NOTHG BY MOUTH IF UNCONSC. GET MEDICAL ATTN.
======== Fire Fighting Measures ================
Flash Point:=12.2C, 54.F Lower Limits:1.4 Extinguishing Media:WATER FOC. CARRON PIOXIDE, ALCOHOL FOAM, DRY
Extinguishing Media:WATER FOG, CARBON DIOXIDE, ALCOHOL FOAM, DRY CHEMICAL
Fire Fighting Procedures:WEAR SCBA AND FULL PROTECTIVE EQUIPMENT.KEEP EXP CNTRS COOL.
Unusual Fire/Explosion Hazard:FLAMMABLE VAPOR IS HEAVIER THAN AIR, EXPLOSION HAZARD.
========= Accidental Release Measures ==========
Spill Release Procedures:REMOVE IGNITION SOURCES, ESTABLISH ADEQUATE
VENTILATION. COLLECT SPILL WITH ABSORBENT OR RAGS, PLACE INSUITABLE CLOSED DISPOSAL CONTAINER. AVOID EYE/SKN CONTACT. WEAR SCBA IF IN CONFINED AREA.
======================================
Handling and Storage Precautions:AVOID EXCESS HEAT & IGNITION SOURCES.AVOID EYE/SKIN CONTACT, AVOID INHL VAPORS.KEEP CONTAINERS CLOSED.PURGE EMPTY CONTAINERS OF VAPORS.
====== Exposure Controls/Personal Protection ========

Respiratory Protection:U

Eye Protection:GOGGLES Other Protective Equipment:NONE Supplemental Safety and Health ENTRY PER OSHA HCS MSDS DTD 70CT86.
======== Physical/Chemical Properties ==========
HCC:F2 Boiling Pt:=78.9C, 174.F Vapor Pres:40 Vapor Density:>1 Appearance and Odor:THIN YELLOW LIQUID, ALCOHOL ODOR.
========= Stability and Reactivity Data =========
Stability Indicator/Materials to Avoid:YES OXIDIZERS Hazardous Decomposition Products:CARBON OXIDES, SMOKE, ALIPHATIC HYDROCARBOD FUMES, OTHERS
======== Disposal Considerations ===========

SE CCROV RESPIRATOR AS REQD Ventilation:USE LOCAL EXHAUST Protective Gloves:IMPERVIOUS

Waste Disposal Methods:INCINERATE IN APPROVED FACILITY IAW ALL LAWS & REGS

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, wa rrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.