View NSN Online: https://aerobasegroup.com/nsn/9150-01-013-5281

FISKE BROTHERS REFINING CO. -- THREAD-EZY CLEAR CUTTING OIL -- 9150-01-013-5281

Product ID:THREAD-EZY CLEAR CUTTING OIL

MSDS Date:01/01/1987

FSC:9150

NIIN:01-013-5281

MSDS Number: BGDJH === Responsible Party ===

Company Name: FISKE BROTHERS REFINING CO.

Emergency Phone Num:(419)691-2491

CAGE:9N579

=== Contractor Identification ===

Company Name: FISKE BROS REFINING

CO

Address:129 LOCKWOOD ST

Box:City:NEWARK

State:NJ

ZIP:07105-4720 Country:US

Phone:201-589-9150

CAGE:73219

Company Name: FISKE BROTHERS REFINING CO

Address:1500 OAKDALE AVE

Box:City:TOLEDO

State:OH ZIP:43605 Country:US

Phone:419-691-2491

CAGE:9N579

======= Composition/Information on Ingredients ========

Ingred Name:LUBE OIL (TAKE TLV AS OIL MIST)

Fraction by Wt: U/K

ACGIH TLV:TMG/CUM(OILMIST

Ingred Name: FATTY OILS(TLV AS OIL MIST)

Fraction by Wt: U/K

ACGIH TLV:NOT SPECIFIED

Ing

CAS:7704-34-9 RTECS #:WS4250000 Fraction by Wt: U/K ACGIH TLV:NOT SPECIFIED
========== Hazards Identification ===========
Effects of Overexposure:MAY IRRITATE EYES,SKIN AND RESPIRATORY TRACT PROLONGED EXPOSURE MAY GIVE DERMATITIS.
======================================
First Aid:INHALE:REMOVE TO FRESH AIR, GIVE CPR/O*2 IF NEED;EYES/SKIN:FLUSH W LG AMTS H*20 FOR 15 MIN;INGEST:RINSE MO UTH; GET MEDICAL ATTENTION FOR EYES, BREATHING DIFFICULTY, OR OTHER
SYMPTOMS OF OVEREXPOSURE.
============ Fire Fighting Measures ============
Flash Point:350F/177C (C.O.C Lower Limits:U/K Upper Limits:U/K Extinguishing Media:CO*2,FOAM,WATER MIST (CHEMICALS DRY) Fire Fighting Procedures:USE SCBA WITH FULL PROTECTION IN FIRES AND IN CONFINED AREA. Unusual Fire/Explosion Hazard:BY PRODUCTS OF SULPHUR COMPOUND - SO*2 ETC.
=========== Accidental Release Measures ====================================
Spill Release Procedures:USE PROPER PERSONAL PROTECTIVE EQUIPMENT.RECOVER SPILLED MATERIAL,ALSO OIL ABSORBENT MATERIAL AND RECOVER FOR PROPER DISPOSAL.
============= Handling and Storage =============
Handling and Storage Precautions:STORE IN COOL DRY AND WELL VENTILATED AREA.KEEP AWAY FROM HEAT AND OPEN FLAMES.KEEP CONTAINER CLOSED WHEN NOT IN USE.
Other Precautions:AVOID SKIN,EYES CONTACT.WASH HANDS AFTER EACH USE.DO NOT U

red Name:SULPHUR CAS#7704-34-9 (USE TLV AS SO*2)

SE CONTAMINATED CLOTHES
====== Exposure Controls/Personal Protection ========
Respiratory Protection:USE NIOSH/MSHA APPROVED RESPIRATOR FOR ORGANIC VAPORS/OIL MIST. Ventilation:MECHANICAL(GENERAL) RECOMMENDED,LOCAL EXHAUST IF NEEDED Protective Gloves:PV/RUBBER Eye Protection:SAFETY/CHEM GOGGLES Other Protective Equipment:FULL WORK CLOTHING TO PREVENT REPEATED OR PROLONGED CONTACT. Supplemental Safety and Health MSDS DATED MAY 13, 1981
======================================
HCC:V6 Boiling Pt:B.P. Text:U/K Vapor Pres:U/K Vapor Density:U/K Spec Gravity:0.9188 Evaporation Rate & Description Rate & Desc
========= Stability and Reactivity Data =========
Stability Indicator/Materials to Avoid:YES STRONG OXIDIZERS Stability Condition to Avoid:NONE SPECIFIED Hazardous Decomposition Products:SO*2 AND POSSIBLY OTHER SULFUR
COMPOUNDS.
======== Disposal Considerations ===========
Waste Disposal Methods:INCINERATE OR DISPOSE OF IN ACCORDANCE WITH

LOCAL, STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability fo

r its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.