

RALPH SHRADER INC. -- POSITRACTION ADDITIVE 1052358 -- 9150-01-198-3829

===== Product Identification =====

Product ID:POSITRACTION ADDITIVE 1052358

MSDS Date:09/26/1983

FSC:9150

NIIN:01-198-3829

MSDS Number: BGQKB

=== Responsible Party ===

Company Name:RALPH SHRADER INC.

Address:3450 LOVETT AVE

City:DETROIT

State:MI

ZIP:48210-3240

Country:US

Info Phone Num:313-556-1597

Emergency Phone Num:(313)894

-4800

CAGE:NO193

=== Contractor Identification ===

Company Name:RALPH SHRADER INC.

Address:3450 LOVETT AVE

City:DETROIT

State:MI

ZIP:48210-3240

Country:US

Phone:313-556-1597

CAGE:NO193

Company Name:SHRADER RALPH INC

Address:ONE RUNWAY RD

Box:2800

City:SOUTH PORTLAND

State:ME

ZIP:04106

Country:US

CAGE:62986

===== Composition/Information on Ingredients =====

Ingred Name:PHOSPHORIC ACID ANHYDRIDE

CAS:989938-00-0

Fraction by Wt: 20.0%

Ingred Name:ALKYL AMINE SALT OF PHOSPHORIC A

CID
CAS:989938-00-1
Fraction by Wt: 20.0%

Ingred Name:MINERAL OIL (EXPOSURE REGULATED AS 'OIL MIST')
CAS:8012-95-1
RTECS #:PY8030000
Fraction by Wt: 55.0%
Other REC Limits:5MG/CUM,OIL MIST
OSHA PEL:5 MG/M3
ACGIH TLV:5 MG/M3/10 STEL;9192

===== Hazards Identification =====

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES
Health Hazards Acute and Chronic:ACUTE:IRRITATING TO EYES,SKIN AND
IRRITATING TO RESPIRATORY TRACT (IN CASE OF INHALATION).
CH
RONIC:NOT KNOWN.
Medical Cond Aggravated by Exposure:NO DATA AVAILABLE

===== First Aid Measures =====

First Aid:SKIN:WASH WITH SOAP AND WATER. EYES: FLUSH WITH WATER.
INHALED: REMOVE TO FRESH AIR. REMOVE CONTAMINATED CLOTHING.

===== Fire Fighting Measures =====

Flash Point:338F,170C,PMCC
Extinguishing Media:CO*2, FOAM, DRY CHEM.
Fire Fighting Procedures:MFR DID NOT SPECIFY

===== Accidental Release Measures =====

Spill Release Procedures:SM SPL: TAKE UP WITH SAND, OR OTHER NONCOMB.
ABSORB MATL THEN FLUSH AREA WITH H*20. SM DRY SPL: SHOVEL INTO DRY
CONTRS, THEN FLUSH AREA W/H*20.LG SPLS:DIKE FAR AHEAD OF SPL FOR
LATER DISPOSAL. NO CONT ACT W/SPILLED MATL. STOP LK.ELIM IGN
SOURCES.

===== Handling and Storage =====

Handling and Storage Precautions:STORE IN COOL,DRY WELL VENTED LOW FIRE
RISK AREA. PROTECT FROM HEAT,SHOCK,FRICT

ION. KEEP CONTAINERS

CLOSED.

Other Precautions:AVOID PROLONGED OR REPEATED SKIN CONTACT.

===== Exposure Controls/Personal Protection =====

Ventilation:MECHANICAL (GENERAL) VENTILATION

Protective Gloves:RUBBER/PLASTIC

Eye Protection:CHEM SPLASH GOGGLES

Other Protective Equipment:NORMAL WORK CLOTHING COVERING ARMS & LEGS.

Supplemental Safety and Health

MSDS DATED 09-26-83/

===== Physical/Chemical Properties =====

HCC:V6

Spec Gravity:0.925

Solub

ility in Water:INSOLUBLE

Appearance and Odor:DARK COLORED LIQUID

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

STRONG OXIDIZING AGENTS.

Stability Condition to Avoid:TEMPS GREATER THAN 100F

Hazardous Decomposition Products:OXIDES OF CARBON,SULFUR,NITROGEN &
PHOSPHORUS

===== Disposal Considerations =====

Waste Disposal Methods:KEEP IN COVERED DRUMS,PENDING DISPOSAL. HANDLE &
DISPOSE IN FULL

COMPLIANCE WITH ALL APPLICABLE

INTERNATIONAL,FEDERAL,STATE, & LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department
of Defense. The United States of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document should seek competent professional advice to verify and
ass

ume responsibility for the suitability of this information to their particular situation.