

VANCHEM,INC. -- ETHYL CENTRALITE;DIETHYLDIPHENYL UREA -- 6810-01-226-7169

=====
Product Identification
=====

Product ID:ETHYL CENTRALITE;DIETHYLDIPHENYL UREA

MSDS Date:06/26/1987

FSC:6810

NIIN:01-226-7169

MSDS Number: BGQXV

=== Responsible Party ===

Company Name:VANCHEM,INC.

Address:1 N.TRANSIT ROAD

City:LOCKPORT

State:NY

ZIP:14094

Country:US

Info Phone Num:716-434-2624

Emergency Phone Num:716-43

4-2624

Preparer's Name:MATTHEW BARMASSE

CAGE:NO246

=== Contractor Identification ===

Company Name:VAN DE MARK CHEMICAL CO INC

Address:1 N TRANSIT RD

Box:City:LOCKPORT

State:NY

ZIP:14094-2323

Country:US

CAGE:6X504

Company Name:VANCHEM,INC.

Address:1 N.TRANSIT ROAD

City:LOCKPORT

State:NY

ZIP:14094

Country:US

Phone:716-434-2624

CAGE:NO246

=====
Composition/Information on Ingredients
=====

Ingred Name:ETHYL CENTRALITE,DIETHYLDIPHENYL UREA

ORN,N-DIETHYLCARBANILIDE

CAS:85-98-3

RTECS #:FE0350000
Fraction by Wt: >99.0%

=====
Hazards Identification
=====

LD50 LC50 Mixture:IPR/MOUSE LD50:200MG/KG
Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:ACUTE:IRRITATION OF THROAT,NASAL
PASSAGE,COUGHING AND SCRATCHY THROAT,REDNESS AND TEARING OF
EYES;INGESTION MAY CAUSE NAUSEA,VOMITING & HEADACHES. CHRONIC:NOT
KNOWN OR NO DATA AVAILABLE.
Expl
anation of Carcinogenicity:N/K (PER MSDS)
Effects of Overexposure:SHARP NEEDLE-LIKE CRYSTALS CAN CAUSE IRRITATION
TO SENSITIVE SKIN AND EYES OR RESPIRATORY OR G.I. TRACTS.
Medical Cond Aggravated by Exposure:NOT KNOWN

=====
First Aid Measures
=====

First Aid:INHALE:REMOVE TO FRESH AIR, GIVE CPR/O*2 IF
NEED;EYES/SKIN:FLUSH W LG AMTS H*2O FOR 15 MIN;INGEST:RINSE MOUTH;
GET MEDICAL ATTENTION FOR EYES, BREATHING DIFFICULTY, OR OTHER
SYMPTOMS OF
OVEREXPOSURE.

=====
Fire Fighting Measures
=====

Flash Point Method:CC
Flash Point:302F/150C
Extinguishing Media:AS APPROPRIATE FOR CLASS B FIRES.
Fire Fighting Procedures:USE NIOSH/MSHA APPROVED SCBA IN CONFINED AREA.
Unusual Fire/Explosion Hazard:WHEN HEATED TO DECOMPOSITION,TOXIC FUMES
ARE EMITTED.POWDER WILL BURN IN OPEN FLAME.

=====
Accidental Release Measures
=====

Spill Release Procedures:USE PROPER PERSONAL PROTECTION
;SHOVEL INTO
DRUMS FOR PROPER DISPOSAL.

=====
Handling and Storage
=====

Handling and Storage Precautions:STORE IN COOL,DRY AND WELL VENTILATED
AREA.DO NOT STORE NEAR STRONG OXIDIZING AGENTS.

=====
Exposure Controls/Personal Protection
=====

Respiratory Protection:USE NIOSH/MSHA APPROVED RESPIRATOR FOR ORGANIC
DUST/VAPORS/MIST(HIGH EFFICIENCY DUST FILTER) OR SCBA IN AN
ENCLOSED AREA.
Ventilation:PROVIDE MECHAN(GEN/LOCAL EXH

AUST)VENT TO MAINTN