

MAGNAFLUX CORPORATION -- ZL-38 ZYGLO PENETRANT -- 6850-01-268-6695

=====
Product Identification
=====

Product ID:ZL-38 ZYGLO PENETRANT

MSDS Date:04/10/1986

FSC:6850

NIIN:01-268-6695

MSDS Number: BGSCG

=== Responsible Party ===

Company Name:MAGNAFLUX CORPORATION

Address:7300 W. LAWRENCE AVENUE

City:CHICAGO

State:IL

ZIP:60656-3504

Country:US

Info Phone Num:312-867-8000

Emergency Phone Num:312-867-80

00

Preparer's Name:BRUCE C. GRAHAM

CAGE:37676

=== Contractor Identification ===

Company Name:ILLINOIS TOOL WORKS INC MAGNAFLUX DIV

Address:3624 WEST LAKE AVENUE

Box:City:GLENVIEW

State:IL

ZIP:60025

Country:US

Phone:847-657-5300/

CAGE:37676

=====
Composition/Information on Ingredients
=====

Ingred Name:PARAFFIN OILS(PETROLEUM),C5-C20

CAS:64771-72-8

Fraction by Wt: 20.0%

Other REC Limits:300PPM

Ingred Name:UNIDENTIFIED COMPONENTS;PER MFR,CONTAINS NO OTHER
INGREDIENTS SUSPE

CTED OF BEING HAZARDOUS I/A/W INFO IN

29CFR1910.1200

Fraction by Wt: 80.0%

=====
===== Hazards Identification =====

Routes of Entry: Inhalation:NO Skin:YES Ingestion:NO

Health Hazards Acute and Chronic:ACUTE:CAUSES DIZZINESS,NAUSEA IF
INHALED AND CAUSES SKIN/EYE IRRITATION ON CONTACT.

Explanation of Carcinogenicity:PER MFR,CONTAINS NO KNOWN OR SUSPECTED
CARCINOGENS.

Effects of Overexposure:INHALATION:CAUSES DIZZINESS,DROWSINESS,NAUSEA;
SKIN:LIQUID I

RRITATES BY DISSOLVING SKIN OIL; EYES:VAPORS/LIQUID

CAUSES IRRITATION; INGESTION:NOT LISTED ON MSDS BY MFR BUT MAY BE
HARMFUL.

Medical Cond Aggravated by Exposure:NOT KNOWN

=====
===== First Aid Measures =====

First Aid:INHALATION:REMOVE TO FRESH AIR.IF BREATHING IS DIFFICULT,GIVE
OXYGEN; SKIN:REMOVE CONTAMINATED CLOTHES.WASH OFF WITH FLOWING
WATER.USE SOOTHING LOTION.IF IRRITATION PERSISTS,GET MEDICAL ATTN;
EYES:IMM EDIATELY RINSE/FLUSH WITH
COPIOUS AMOUNT OF RUNNING
WATER,AND GET MEDICAL ATTENTION.

=====
===== Fire Fighting Measures =====

Flash Point Method:PMCC

Flash Point:>200F/>93C

Extinguishing Media:CARBON DIOXIDE,FOAM

Fire Fighting Procedures:KEEP CONTAINERS COOL WITH WATER SPRAY.DO NOT
SPRAY WATER ON BURNING ZL-38.

Unusual Fire/Explosion Hazard:WHEN INVOLVE IN COMBUSTION,MAY EMIT TOXIC
GASES AT OR ABOVE DECOMPOSITION TEMPERATURE.

=====
===== Accidental Release Measures ====
=====

Spill Release Procedures:REMOVE IGNITION SOURCES.SM QTY:WIPE UP OR MOP
UP BUT DO NOT BREATHE VAPORS.PLACE RAGS IN CLOSED DRUMS; LG
QTY:WEAR PERSONAL SAFETY EQUIPMENTS.DIKE AREA FAR AHEAD.ABSORB
LIQUID WITH COMMERCIAL ABSORBEN T.TRANSFER WASTE MATL IN SALVAGE
TANKS.

=====
===== Handling and Storage =====

Handling and Storage Precautions:STORE AWAY FROM HEAT SOURCES IN WELL
VENTILATED AREA.AVOID AGAINST PHYSICAL DAMAGE TO CONTAINERS

RS.KEEP

CONTAINERS TIGHTLY CLOSED.

Other Precautions:DO NOT BREATHE VAPORS.DO NOT SMOKE WHILE USING.DO NOT HEAT ABOVE 130F(54C).AVOID FREQUENT OR PROLONGED SKIN CONTACT.

=====
===== Exposure Controls/Personal Protection =====

Respiratory Protection:USE NIOSH APPROVED RESPIRATOR FOR CONFINED AREAS; IF USING IN POORLY VENTILATED AREA,USE RESPIRATOR WITH CHEMICAL CARTRIDGE.

Ventilation:GENERAL ROOM VENTILATION TO KEEP BELOW TLV LIMITS;PER MFR,USE IN SPRAY BOOTH OR WHERE VENTILATION IS ADEQUATE.

Protective Gloves:USE NITRILE RUBBER GLOVES IF NEEDED.

Eye Protection:FULL GOGGLES/SAFETY GLASSES W/SIDEHSIELD

Other Protective Equipment:NOT KNOWN

Work Hygienic Practices:WASH OFF PROMPTLY WITH WATER.AVOID SKIN CONTACT WITH ZL-38.

Supplemental Safety and Health

NSN OF MIL-I-25135,TYPE I,METHOD C,LEVEL 4;PER QPL-25135-15,MAGNAFLUX MAY SUPPLY ONE OF THE FOLLOWING PENETRANTS FOR TYPE I,METHOD B,LEVEL 4 UNDER THIS NSN:ZL-38,ZL-37,OR ZL-30B;THIS ENTRY DESCR

IBES

Z L-38;PRODUCT NOT AVAILABLE IN AEROSOL CANS.SEE OTHER PNI OF THIS NSN FOR OTHER QUALIFIED ITEMS OF REV "D" SPEC.

=====
===== Physical/Chemical Properties =====

HCC:N1

Boiling Pt:B.P. Text:430F/221C

Vapor Pres:1.0

Spec Gravity:0.92

Solubility in Water:NEGLIGIBLE

Appearance and Odor:GREEN OILY LIQUID

Percent Volatiles by Volume:5%

=====
===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

NONE KNOWN

Stabili

ty Condition to Avoid:HEAT,HIGH TEMPERATURES

Hazardous Decomposition Products:EMITS OXIDES OF CARBON AND NITROGEN ON COMBUSTION.

===== Disposal Considerations =====

Waste Disposal Methods:INCINERATE OR DISPOSE OF AS EPA HAZARDOUS WASTE D001 (IGNITABLE WASTE),IN ACCORDANCE WITH ALL APPLICABLE FEDERAL,STATE,LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department

of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.