

DEXTER CORPORATION/HYSOL AIR DIVISION -- EA 9330 PART B -- 8040-01-137-8414

===== Product Identification =====

Product ID:EA 9330 PART B

MSDS Date:04/14/1988

FSC:8040

NIIN:01-137-8414

MSDS Number: BHBDK

=== Responsible Party ===

Company Name:DEXTER CORPORATION/HYSOL AIR DIVISION

Address:2850 WILLOW PASS ROAD

Box:312

City:PITTSBURG

State:CA

ZIP:94565

Info Phone Num:(415) 687-4201

Emergency Phone Nu

m:(415) 687-4201

CAGE:79436

=== Contractor Identification ===

Company Name:DEXTER CORP DEXTER ELECTRONIC MATERIALS

Address:15051 E DON JULIAN RD

Box:City:INDUSTRY

State:CA

ZIP:91746-1282

Country:US

Phone:626-968-6511

CAGE:79436

Company Name:DEXTER CORPORATION ADHESIVE & COATING SYSTEMS

Address:2850 WILLOW PASS ROAD

Box:312

City:BAY POINT

State:CA

ZIP:94565-3299

Country:US

Phone:202-483-7616

CAGE:33564

===== Composition/Information on Ingredients =====

Ingred Name:EPOXY RESIN

=====
===== Hazards Identification =====
=====

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:EYE/SKIN: CAUSE SEVERE
BURNS/IRRITATION. INHALATION: VAPORS MAY BE IRRITATING TO THE
RESPIRATORY TRACT.
Explanation of Carcinogenicity:NONE
Effects of Overexposure:EYE/SKIN: SEVERE BURNS & IRRITATION.
INHALATION: VAPORS MAY BE IRRITATING TO THE RESPIRATORY TRAC
T.

=====
===== First Aid Measures =====
=====

First Aid:IN CASE OF EYE CONTACT, FLUSH WITH PLENTY OF WATER FOR AT
LEAST 15 MINUTES. SKIN: WASH WITH SOAP & WATER AT ONCE. SEEK
MEDICAL ATTENTION. REMOVE CONTAMINATED CLOTHING/THOROUGHLY CLEAN
BEFORE RE-USE. DESTROY CONTAMINATED LEATHER GOODS.

=====
===== Accidental Release Measures =====
=====

Spill Release Procedures:TRANSFER TO METAL CONTAINER. WIPE UP REMAINING
RESIDUE WITH SOLVENTS,
OBSERVING SOLVENT FLAMMABILITY CAUTIONS.

=====
===== Handling and Storage =====
=====

Handling and Storage Precautions:KEEP COOL IN ACCORDANCE WITH LABEL
INSTRUCTIONS. FOLLOW RECOMMENDED CURING SCHEDULE. STORE AT ROOM
TEMP 77F. FOR 12 MONTHS.
Other Precautions:DANGER CAUSE SEVERE EYE/SKIN BURNS. CONTAINS
POLYGLYCOLDIAMINE. AVOID CONTACT. WASH AFTER HANDLING. AVOID
BREATHING VAPORS. KEEP CONTAINER CLOSED. USE ONLY W/GOOD
VENTILATION. DON'T CUT/WELD C
ONTAINER.

=====
===== Exposure Controls/Personal Protection =====
=====

Respiratory Protection:NOT NEEDED WITH GOOD INDUSTRIAL VENTILATION.
Ventilation:LOCAL EXHAUST RECOMMENDED
Protective Gloves:IMPERVIOUS
Eye Protection:SAFETY GLASSES, GOGGLES
Other Protective Equipment:AS NEEDED TO PROTECT SKIN & CLOTHING.
Work Hygienic Practices:REMOVE CONTAMINATED CLOTHING/THOROUGHLY CLEAN
BEFORE REUSE. WASH AFTER HANDLING.
Supplemental Safety and Health

=====
===== Physical/Chemical P
=====

roperties =====

Boiling Pt:B.P. Text:DECOMPOSES

Vapor Pres:1

Solubility in Water:NIL

Appearance and Odor:REDDISH-ORANGE LIQUID WITH AMMONIACAL ODOR

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

===== Disposal Considerations =====

Waste Disposal Methods:DISPOSE OF AS HAZARDOUS WASTE ACCORDING TO DOT HAZARD CLASS. IF NOT REGULATED BY DOT, DISPOSE OF AS ORM-E.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.