View NSN Online: https://aerobasegroup.com/nsn/8010-00-579-9201

CHEMRAY COATINGS, CORP. -- ENAMEL, FLOOR AND DECK -- 8010-00-579-9201

Product ID: ENAMEL, FLOOR AND DECK MSDS Date:08/16/1989 FSC:8010 NIIN:00-579-9201 **MSDS Number: BHFQY** === Responsible Party === Company Name: CHEMRAY COATINGS, CORP. Address:209 N. MICHIGAN AVE. City:KENILWORTH State:NJ ZIP:07033 Country:US Info Phone Num:201-245-1111 Emergency Phone Num:201-245-1111 CAGE:OBRN9 === Contractor Identification === Company Name: CHEMRAY COATING CORP Address:209 N MICHIGAN AVE Box:City:KENILWORTH State:NJ ZIP:07033 Country:US Phone:201-245-1111 CAGE:33832 Company Name: CHEMRAY COATINGS CORP. Address:209 N. MICHIGAN AVE. Box:NA City:KENILWORTH State:NJ ZIP:07033 Country:US Phone:800-924-9300 CAGE:OBRN9

Ingred Name:PETROLEUM SOLVENT,M.S. 66 CAS:8052-41-3 Fraction by Wt: 25% OSHA PEL:500 PPM A Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Effects of Overexposure:INHALATION: CAN CAUSE NAUSEA, HEADACHE, DIZZINESS.

First Aid:EYES: FLUSH WITH WATER 15 MINUTES OR UNTIL IRRITATION SUBSIDES. IF IRRITATION PERSISTS. CALL PHYSICIAN. SKIN: REMOVE CONTAMINATED CLOTHING AND WASH THO- ROUGHLY WITH SOAP AND WATER.

INHALATION : IF OVERCOME BY VAPORS, REMOVE TOFRESH AIR, CALL PHYSICIAN. INGESTION: DO NOT INDUCE VOMITING, CALL PHYSICIAN.

Flash Point:103F/40C Lower Limits:.9 Upper Limits:7 Extinguishing Media:CARBON DIOXIDE, FOAM, WATER FOG, DRY CHEMICAL Fire Fighting Procedures:USE AIR-SUPPLIED BREATHING EQUIPMENT FOR ENCLOSED CONTAINERS WITH WATER SPRAY. AVOID BREATHING VAPOR OR FUMES. Unusual Fire/Explosion Ha zard:IF LEAK OR SPILL WAS IGNITED, USE WATER

SPRAY TO DISPERSE THE VAPORS FROM FIREFIGHTERS.

Spill Release Procedures:REMOVE ALL IGN SOURCES. KEEP FROM HEAT SPARKS ANDOPEN FLAME. ADD ABSORBENT(SAND, EARTH, SAWDUST) TO SPILL. VENTILATE AREA (OPEN WINDOWS, DOORS). IF LG SPILL, KEEP PRODUCT FROM ENTERING SEWERS & WTRCOURSES BY DIKING. ADVISE AUTHORITIES OF SPILL Neutralizing Agent:NA

==============

Handling and Storage Precautions:STORE AWAY FROM IGNITION SOURCES.
KEEP IN COOL, DRY, WELL-VENTILATED AREA. AVOID DIRECT SUNLIGHT AND EXTREME TEMPERATURES - HOT AND COLD.
Other Precautions:AVOID EYE, SKIN CONTACT, INHALATION, INGESTION OF MISTS, SPRAY OR VAPORS. AVOIDBREATHING SANDING OR BLASTING DUST.

======= Exposure Controls/Personal Protection ===============

Respiratory Protection:USE HYDROCARBON VAPOR CANNISTER OR SUPPLIED AIR RESPIRATOR IN CONFINED AREA. Ventilation:LOCAL EXHAUST-FACE VELOCITY 60PPM SPECIAL-USE ONLY WITH ADE-QUATE VENTILATN. MECHANICAL-USE EXPLOSN-PROOF EQUIPMENT. Protective Gloves:CHEMICAL RESISTANT Eye Protection:SPLASH GOGGLES OR FACE SHIELD Other Protective Equipment:CHEMICAL RESISTANT APRON OR CLOTHING Supplemental Safety and Health NK

Boiling Pt:B.P. Text:308F Decomp Temp:Decomp Text:600F/316C Vapor Pres: