

SHERWIN INC -- RC88 FLUORSCENT PENETRANT -- 6850-01-263-8224

===== Product Identification =====

Product ID:RC88 FLUORSCENT PENETRANT

MSDS Date:01/01/1986

FSC:6850

NIIN:01-263-8224

MSDS Number: BJNZS

=== Responsible Party ===

Company Name:SHERWIN INC

Address:5530 BORWICK AVE

City:SOUTH GATE

State:CA

ZIP:90280-7402

Country:US

Info Phone Num:213-861-6324

Emergency Phone Num:213-861-6324

CAGE:21405

=

== Contractor Identification ==

Company Name:SHERWIN INC.

Address:5530 BORWICK AVE.

City:SOUTH GATE

State:CA

ZIP:90280-7402

Country:US

Phone:562-861-6324/FAX 923-8370

CAGE:21405

===== Composition/Information on Ingredients =====

Ingred Name:MIXTURE OF ESTERS, PHOSPHATE/PHTHALATE. SEE NEXT TWO  
INGREDIENTS FOR THE LAIDN NUMBERS OF EACH ESTER.

RTECS #:9999999ZZ

Fraction by Wt: 90-99%

Other REC Limits:NONE SPECIFIED

Ingred Name:PHTHALATE ESTER

Other REC Limits:NONE SPECIFIE

D

Ingred Name:PHOSPHATE ESTER  
Other REC Limits:NONE SPECIFIED

Ingred Name:FLUORESCENT DYES (AMINOKETONE/COURMARIN DERIVED)  
Fraction by Wt: 1-10%  
Other REC Limits:NONE SPECIFIED

=====  
===== Hazards Identification =====

Routes of Entry: Inhalation:NO Skin:YES Ingestion:NO  
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO  
Health Hazards Acute and Chronic:WARNING! ELEVATED TEMPERATURES MAY  
CAUSE RELEASE OF HARMFUL VAPORS IF INHALED. AVOID CREATING AND  
BREA  
THING MISTS.  
Effects of Overexposure:RESPIRATORY TRACT IRRITATION. CENTRAL NERVOUS  
SYSTEM STIMULATION, FOLLOWED BY DEPRESSION IN VARYING DEGREES.  
Medical Cond Aggravated by Exposure:NONE SPECIFIED BY MANUFACTURER.

=====  
===== First Aid Measures =====

First Aid:EYES:WATER FLUSH FOR 15 MIN-GET MEDICAL ATTENTION! SKIN:SOAP  
AND WATER WASH. REMOVE AND WASH CONTAMINATED CLOTHING. INGESTION:DO  
NOT INDUCE VOMITING. GET MEDICAL ATTENTION! IF VOMITING OCCURS  
  
SPONTANEOUSLY, KEEP HEAD BELOW HIPS TO PREVENT ASPIRATION OF  
LIQUID INTO LUNGS. INHALATION:REMOVE TO FRESH AIR. IF NOT  
BREATHING, GIVE ARTIFICIAL RESPIRATION. IF BREATHING DIFFICULT,  
GIVE OXYGEN. GET MEDICAL.

=====  
===== Fire Fighting Measures =====

Flash Point Method:CC  
Flash Point:200F,93C  
Extinguishing Media:WATER FOG, CARBON DIOXIDE, FOAM, DRY CHEMICAL  
Fire Fighting Procedures:DO NOT USE A DIRECT STREAM OF WATER. IT  
SPREADS THE FIRE. PRODUCT  
MAY FLOAT AND REIGNITE ON SURFACE OF  
WATER.  
Unusual Fire/Explosion Hazard:ON BURNING, THIS PRODUCT CAN RELEASE  
TOXIC FUMES AND VAPORS. FIREFIGHTERS SHOULD WEAR SELF-CONTAINED  
BREATHING APPARATUS AND FULL PROTECTIVE CLOTHING.

=====  
===== Accidental Release Measures =====

Spill Release Procedures:EXTINGUISH ALL FLAMES. TAKE UP WITH AN  
ABSORBENT MATERIAL AND DISPOSE OF IN COMPLIANCE WITH LOCAL, STATE,  
AND FEDERAL REGULATIONS.  
Neutralizing Agent:NONE SPECIFIED

