

LOCTITE CORPORATION -- QUICK SET 404 INDUSTRIAL ADHESIVE SPLICING

=====
MSDS Safety Information
=====

FSC: 4940
NIIN: 01-131-1915
MSDS Date: 01/28/1991
MSDS Num: BJQJG
Product ID: QUICK SET 404 INDUSTRIAL ADHESIVE SPLICING
MFN: 03
Kit Part: Y
Responsible Party
Cage: 05972
Name: LOCTITE CORPORATION
Address: 1001 TROUT B
ROOK CROSSING
City: ROCKY HILL (FORMALLY IN NEWINGTON) CT 06067
Info Phone Number: 860-571-5100/FAX 860-571-5465
Emergency Phone Number: 860-571-5100/FAX 860-571-5465
Preparer's Name: STEPHEN REPETTO
Published: Y

=====
Contractor Summary
=====

Cage: 05972
Name: LOCTITE CORPORATION
Address: 1001 TROUT BROOK CROSSING
City: ROCKY HILL CT 06067-3910
Phone: 860-571-5100
Cage: 97403
Name: US ARMY
Addre
ss: RESEARCH AND DEVELOPMENT CENTER
City: FORT BELVOIR VA 22060-5606
Phone: UNKNOWN

=====
Item Description Information
=====

Item Manager: S9C
Item Name: SPLICING KIT O RING
Specification Number: NONE
Type/Grade/Class: NONE
Unit of Issue: KT
UI Container Qty: 1
Type of Container: UNKNOWN

=====
Ingredients
=====

=====

Cas: 7085-85-0

Name: ETHYL CYANOACRYLATE (CAS NUMBER PER MANUFACTURER)

% Wt: 90-95 %

Other REC Limits: NONE SPECIFIED

OSHA PEL: NOT ESTABLISHED

ACGIH TLV: NOT ESTABLISHED

Cas: 9011-14-7

Name: METHACRYLATE POLYMER (CAS NUMBER PER MANUFACTURER)

% Wt: 5-10 %

Other REC Limits: NONE SPECIFIED

OSHA PEL: NOT ESTABLISHED

ACGIH TLV: NOT ESTABLISHED

Cas: 123-31-9

RTECS #: MX3500000

Name: HYDROQUINONE (SARA III)

% Wt: 0.1-1 %

Oth

er REC Limits: NONE SPECIFIED

OSHA PEL: 2 MG/M3

ACGIH TLV: 2 MG/M3; 9192

EPA Rpt Qty: 1 LB

DOT Rpt Qty: 1 LB

=====

Health Hazards Data

=====

LD50 LC50 Mixture: > 5000MG/KG LD50 ORAL ESTIMATED

Route Of Entry Inds - Inhalation: NO

Skin: YES

Ingestion: NO

Carcinogenicity Inds - NTP: NO

IARC: NO

OSHA: NO

Effects of Exposure: BONDS SKIN RAPIDLY AND STRONGLY. SKIN/EYE IRRITANT.

Explanation Of Carcin

ogenicity: PRODUCT CONTAINS NO MATERIALS CURRENTLY

CLASSIFIED AS CARCINOGENIC BY NTP, IARC OR OSHA.

Signs And Symptoms Of Overexposure: VAPOR IS IRRITATING TO EYES AND MUCOUS

MEMBRANES ABOVE TLV. PROLONGED AND REPEATED CONTACT TO VAPORS MAY PROVIDE

ALLERGIC REACTIONS WITH ASTHMA-LIKE SYMPTOMS IN SENSITIVE INDIVIDUALS.

Medical Cond Aggravated By Exposure: NONE SPECIFIED BY MANUFACTURER.

First Aid: SKIN: IMMERSSE THE BONDED SURFACES IN WARM SOAPY WATER. PEEL OR ROOL

THE SURFACES APART WITH

AID OF BLUNT EDGE. DO NOT TRY TO PULL SURFACES APART WITH A DIRECT OPPOSING ACTION. EYES: WASH WITH WARM WATER AND APPLY A GAUZE PATCH. EYE WILL OPEN WITHOUT FURTHER ACTION, TYPICALLY IN 1-4 DAYS. MOUTH: APPLY LOTS OF WARM WATER TO LIPS. PEEL OR ROLL LIPS APART. DO NOT PULL WITH DIRECT FORCE. SEE SUPP DATA.

=====
Handling and Disposal
=====

Spill Release Procedures: FLOOD WITH WATER TO POLYMERIZE COMPLETELY. SOAK UP WITH AN INERT ABSORBENT.

Neutralizing Agent: NONE SPECIFIED BY MANUFACTURER.

Waste Disposal Methods: POLYMERIZE WITH WATER. INCINERATE IN ACCORDANCE WITH EPA AND LOCAL REGULATIONS.

Handling And Storage Precautions: STORE AT OR BELOW 75F TO PRESERVE SHELF LIFE. AVOID CONTACT WITH SKIN AND EYES. AVOID BREATHING VAPOR.

Other Precautions: NONE SPECIFIED BY MANUFACTURER.

=====
Fire and Explosion Hazard Information
=

=====
Flash Point Method: TCC

Flash Point Text: 150F,66C

Lower Limits: UNKNOWN

Upper Limits: UNKNOWN

Extinguishing Media: USE WATER FOG, CARBON DIOXIDE, FOAM, OR DRY CHEMICAL.

Fire Fighting Procedures: WEAR FIRE FIGHTING PROTECTIVE EQUIPMENT AND A FULL FACED SELF CONTAINED BREATHING APPARATUS.

Unusual Fire/Explosion Hazard: COMBUSTION OR HEAT OF FIRE MAY PRODUCE HAZARDOUS DECOMPOSITION PRODUCTS AND VAPORS.

=====
Control Measures
=====

Respiratory Protection: NONE SPECIFIED BY MANUFACTURER.

Ventilation: POSITIVE DOWN-DRAFT EXHAUST VENTILATION SHOULD BE PROVIDED TO MAINTAIN VAPOR CONCENTRATION BELOW TLV.

Protective Gloves: POLYETHYLENE GLOVES. DO NOT USE COTTON.

Eye Protection: SAFETY GLASSES OR GOGGLES.

Other Protective Equipment: SAFETY SHOWER AND EYE WASH STATION.

Work Hygienic Practices: HANDLE CAREFULLY. AVOID SKIN CONTACT.

Suppl

emental Safety and Health: IT IS ALMOST IMPOSSIBLE TO SWALLOW PRODUCT.
PRODUCT WILL SOLIDIFY IN MOUTH. CYANOACRYLATES GIVE OFF HEAT ON
SOLIDIFICATION. IN RARE CASES A DROP WILL CAUSE A BURN. BURNS SHOULD BE
TREATED NORMALLY AFT ER THE LUMP OF CYANOACRYLATE IS RELEASED FROM THE TISSUE
AS DESCRIBED IN FIRST AID SECTION.

=====
Physical/Chemical Properties
=====

HCC: V4
B.P. Text: >300F,>
>149C
M.P/F.P Text: UNKNOWN
Decomp Text: UNKNOWN
Vapor Pres: < 0.2
Vapor Density: 3
Spec Gravity: 1.09
Viscosity: UNKNOWN
Evaporation Rate & Reference: UNKNOWN
Solubility in Water: POLYMERIZED BY WATER
Appearance and Odor: CLEAR LIQUID, PUNGENT ODOR
Corrosion Rate: UNKNOWN

=====
Reactivity Data
=====

Stability Indicator: YES
Stability Condition To Avoid: EXTREMELY HIGH TEMPERATURES
Materi
als To Avoid: POLYMERIZED BY CONTACT WITH WATER, ALCOHOLS, AMINES,
ALKALIES.
Hazardous Decomposition Products: IRRITATING ORGANIC VAPORS
Hazardous Polymerization Indicator: NO
Conditions To Avoid Polymerization: NONE. WILL NOT OCCUR.

=====
Toxicological Information
=====

=====
Ecological Information
=====

=====
MSDS Transport Information
=====

=====
Regulatory Information
=====

=====
Other Information
=====

=====
Transportation Information

=====
Responsible Party Cage: 05972
Trans ID NO: 109652
Product ID: QUICK SET 404 INDUSTRIAL ADHESIVE SPLICING
MSDS Prepared Date: 01/28/1991
Review Date: 03/18/1991
MFN: 3
Net Unit Weight: UNKNOWN
Multiple KIT Number: 0
Kit Part IND: Y
Review IND: Y
Unit Of Issue: KT
Container QTY: 1
Type Of Container: UNKNOWN

Additional Data: THIS IS PART OF A KIT. PART B IS THE MOST HAZARDOUS COMPONENT
AND THEREFORE GOVERNS SHIPPING. SHIPPI NG CODES WHEN S
HIPPED AS COMPLETE KIT:
LESS THAN 1 PINT OF PART B - DTJ; ZZZ; ZZZ; CZQ (ORM-D CONSUMER COMMODITY).
MORE THAN 1 PINT PART B-NAX; OSR; YEL; JKT.

=====
Detail DOT Information
=====

DOT PSN Code: ZZZ
DOT Proper Shipping Name: NOT REGULATED BY THIS MODE OF TRANSPORTATION
=====

Detail IMO Information
=====

=====
IMO PSN Code: ZZZ
IMO Proper Shipping Name: NOT REGULATED FOR THIS MODE OF TRANSPORTATION
=====

Detail IATA Information
=====

IATA PSN Code: ZZZ
IATA Proper Shipping Name: NOT REGULATED BY THIS MODE OF TRANSPORTATION
=====

Detail AFI Information
=====

AFI PSN Code: ZZZ
AFI Proper Shipping

Name: NOT REGULATED BY THIS MODE OF TRANSPORTATION

=====
HAZCOM Label
=====

Product ID: QUICK SET 404 INDUSTRIAL ADHESIVE SPLICING

Cage: 05972

Company Name: LOCTITE CORPORATION

Street: 1001 TROUT BROOK CROSSING

City: ROCKY HILL CT

Zipcode: 06067-3910

Health Emergency Phone: 203-278-1280

Label Required IND: Y

Date Of Label Review: 03/18/1991

Status Code: C

MFG Label NO: NONE

Label Date: 03/18/199

1

Origination Code: F

Chronic Hazard IND: Y

Eye Protection IND: YES

Skin Protection IND: YES

Signal Word: WARNING

Health Hazard: Slight

Contact Hazard: Moderate

Fire Hazard: Slight

Reactivity Hazard: Slight

Hazard And Precautions: STORE AT OR BELOW 75F TO PRESERVE SHELF LIFE. AVOID CONTACT WITH SKIN AND EYES. AVOID BREATHING VAPOR. FIRST AID: SKIN: IMMERSE THE BONDED SURFACES IN WARM SOAPY WATER. PEEL OR ROOL THE SURFACES APART WITH AID OF BLUNT EDGE. DO NOT TRY TO PULL SURFACES APART WIT

H A DIRECT

OPPOSING ACTION. EYES: WASH WITH WARM WATER AND APPLY A GAUZE PATCH. EYE WILL OPEN WITHOUT FURTHER ACTION, TYPICALLY IN 1-4 DAY S. MOUTH: APPLY LOTS OF WARM WATER TO LIPS. PEEL OR ROLL LIPS APART. DO NOT PULL WITH DIRECT FORCE.SEE MSDS FOR ADDITIONAL INFORMATION.

=====
Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense.

The U nited States of America in no manner whatsoever expressly or implied warrants, states, or intends said information to have any application, use or viability by or to any person or persons outside the Department of Defense nor any person or persons contracting with any instrumentality of the United States of America and disclaims all liability for such use. Any person utilizing this instruction who is not a military or civilian employee of the United States of America should seek comp

etent professional advice to verify
and assume responsibility for the suitability of this information to their
particular situation regardless of similarity to a corresponding Department
of Defense or other government situation.