View NSN Online: https://aerobasegroup.de/nsn/5330-00-197-8492

R M ENGINEERED PRODUCTS, INC. -- RM 303 PACKING -- 5330-00-197-8492

Product ID:RM 303 PACKING MSDS Date:04/24/1991 FSC:5330 NIIN:00-197-8492 **MSDS Number: BJYSR** === Responsible Party === Company Name: R M ENGINEERED PRODUCTS, INC. Address:4854 O'HEAR AVENUE City:NORTH CHARLESTON State:SC ZIP:29406 Country:US Info Phone Num:803-744-6261 Emergency Phone Num:803-744-6 261/803-744-0461 CAGE:10009 === Contractor Identification === Company Name: R M ENGINEERED PRODUCTS, INC. Address:4854 O'HEAR AVENUE Box:City:NORTH CHARLESTON State:SC ZIP:29405 Country:US Phone:843-744-6261 CAGE:10009

Ingred Name:ASBESTOS, CHRYSOTILE CAS:12001-29-5 RTECS #:CI6478500 Fraction by Wt: 35-40% Other REC Limits:NONE SPECIFIED OSHA PEL:0.2 FIBERS/CC ACGIH TLV:2 FIBERS/CC; A1;9192

Ingred Name:GRAPHITE, SYNTHETIC CAS

:7440-44-0 RTECS #:FF5250100 Fraction by Wt: 5-10% Other REC Limits:NONE SPECIFIED OSHA PEL:15 MG/M3 TDUST ACGIH TLV:2 MG/M3 TDUST; 9293

Ingred Name:ZINC (SARA III) CAS:7440-66-6 RTECS #:ZG8600000 Other REC Limits:NONE SPECIFIED OSHA PEL:10 MG ZNO/M3 ACGIH TLV:10 MG ZNO/M3; 9192 EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Ingred Name:HYDROTREATED HEAVY NAPHTHENIC DISTILLATE, PETROLEUM CAS:64742-52-5 RTECS #:PY8035000 Other REC Limits:NONE SPECIFIED

Ingred Name:MONEL WIRE (MAY INCLUDE TRACE AMO UNTS OF NI, CU, PB, C, MN, FE, S, TI, COBALT) Other REC Limits:NONE SPECIFIED

Ingred Name:ALUMINUM (SARA III) CAS:7429-90-5 RTECS #:BD0330000 Fraction by Wt: TRACE Other REC Limits:NONE SPECIFIED OSHA PEL:15MG/M3 DUST/5 FUME ACGIH TLV:10MG/M3 DUST; 9192

Routes of Entry: Inhalation:YES Skin:NO Ingestion:YES Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:YES Health Hazards Acute and Chronic:ACUTE:DUST MAY CAUSE S KIN/EYE

IRRITATION. CHRONIC:OVEREXPOSURE TO ASBESTOS MAY LEAD TO NUMEROUS RESPIRATORY PROBLEMS ASSOCIATED WITH ASBESTOSIS. OVEREXPOSURE TO THIS METALLIC FORMULATION CAN CAUSE ALL ERGIC DERMATITIS, FUME FEVER, FLU-LIKE SYMPTOMS, METALLIC TASTE AND IRRITATION SYMPTOMS, NAUSEA, MUSCLE PAIN.

Explanation of Carcinogenicity:ASBESTOS AND NICKEL/NICKEL COMPOUNDS ARE RECOGNIZED HUMAN CARCINOGEN AND ARE LISTED BY IARC, NTP OR OSHA AS CARCINOGENS

Effects of Overexposure:ASBESTO

SIS IS ASSOCIATED WITH SYMPTOMS OF LABORED BREATHING, CHEST PAIN AND CHEST TIGHTNESS. SYMPTOMS ARE NOT USUALLY MANIFEST UNTIL 15-20 YEARS AFTER EXPOSURE. METAL FUME FEVER WITH FLU LIKE SYMPTO MS (CHILLS AND FEVER - SHOULD DISAPPEARWITHIN 24-48 HOURS). HIGH TEMPERATURE AND GRINDING OPERATIONS MAY BE IRRITATIING Medical Cond Aggravated by Exposure:PERSONS WITH A HISTORY OF RESPIRATORY DISORDERS AND SMOKING MAY BE AT INCREASED RISK FROM EXPOSURE. CHRONIC EFFECTS OF ASBE STOS EXPOSURE (ASBESTOSIS, MESOTHELIOMA ETC.) MAY NOT SHOW UP FOR 10-20 YEARS
======================================
First Aid:EYE/SKIN: IMMEDIATELY FLUSH WITH PLENTY OF WATER FOR 15 MINUTES. GET MEDICAL ATTENTION. INHALATION: REMOVE TO FRESH AIR. INGESTION IS NOT LIKELY BUT LARGE AMOUNTS CAN CAUSE PROBLEMS-SEEK MEDICAL HELP . DO NOT INDUCE VOMITING WITHOUT MEDICAL ADVICE.
 Exti nguishing Media:USE WATER FOG, CARBON DIOXIDE, FOAM, OR DRY CHEMICAL AS APPROPRIATE FOR SURROUNDINGS. Fire Fighting Procedures:FIRE FIGHTERS SHOULD USE NIOSH APPROVED SCBA & FULL PROTECTIVE EQUIPMENT WHEN FIGHTING CHEMICAL FIRE. USE WATER SPRAY TO COOL NEARBY CONTAINERS EXPOSED TO FIRE. Unusual Fire/Explosion Hazard:FIRE OR EXCESSIVE HEAT MAY CAUSE PRODUCTION OF HAZARDOUS DECOMPOSITION PRODUCTS.
======================================
Spill Release P rocedures:VACUUM OR WASH DOWN. DO NOT DRY SWEEP AS THIS COULD RESULT IN HIGH CONCENTRATIONS OF AIRBORNE DUST. Neutralizing Agent:NONE
======================================
Handling and Storage Precautions: AVOID CREATING AIRBORNE DUST. WET SURFACES/FLOORS BEFORE SWEEPING AND USE APPROPRIATE DUST MASK. STORE AWAY FROM SOURCES OF DIRECT HEAT IN A DRY AREA. Other Precautions: USE DUST SUPPRESSION MEASURES-AVOID CREATION OF PARTICULATE ASBESTOS. WASH THO

ROUGHLY BEFORE EATING OR SMOKING. AVOID BREATHING OF DUST. MEDICAL SURVEILLANCE IS REQUIRED FOR PROLONGED EXPOSURE TO THIS MATERIAL.

======= Exposure Controls/Personal Protection ==========

Respiratory Protection: IF VENTILATION DOES NOT MAINTAIN INHALATION EXPOSURES BELOW PEL (TLV), USE NIOSH/MSHA APPROVED RESPIRATOR AS PER CURRENT 29 CFR 1910.134, INSTRUCTIONS/WARNINGS AND NIOSH-RESPIRATOR SELECTION. USE MESA /OSHA RESPIRATOR WHEN CUTTING & GRINDING

Ventilat

ion:CHECK GOVERNMENT STANDARDS OF EMISSION CONTROL.

Protective Gloves:COTTON OR IMPERVIOUS TYPE IF CUT/GRIND.

Eye Protection: SAFETY GOGGLES OR GLASSES

Other Protective Equipment:SAFETY SHOWER AND EYE BATH. INDUSTRIAL TYPE WORK CLOTHING AND APRON AS REQUIRED TO AVOID PROLONGED OR REPEATED CONTACT.

Work Hygienic Practices:WASH THOROUGHLY AFTER HANDLING AND BEFORE EATING OR DRINKING. LAUNDER CONTAMINATED CLOTHING BEFORE REUSE. DO NOT SMOKE.

Supplemental Safety and Health

DO NOT TAKE

PROTECTIVE GEAR OR CLOTHING HOME IS EXPOSED TO DUST.

HCC:T6

Appearance and Odor:DARK GRAY ODORLESS SOLID.

Stability Indicator/Materials to Avoid:YES STRONG OXIDIZING AGENTS, ACIDS, ALKALIES. Stability Condition to Avoid:HIGH TEMPERATURES Hazardous Decomposition Products:CARBON MONOXIDE, CARBON DIOXIDE AND METAL FUMES.

====== Disposal Co

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH ALL APPLICABLE FEDERAL, STATE AND LOCAL REGULATIONS FOR PROPER ASBESTOS DISPOSAL. ALL WASTE MATERIALS MUST BE SEALED AND BAGGED.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate

and

disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.