

PLASTI-KOTE -- CONDUCTIVE SILVER ADHESIVE PART II -- 8040-01-056-0875

=====
Product Identification
=====

Product ID:CONDUCTIVE SILVER ADHESIVE PART II

MSDS Date:04/01/1988

FSC:8040

NIIN:01-056-0875

Kit Part:Y

MSDS Number: BLJYT

=== Responsible Party ===

Company Name:PLASTI-KOTE

Address:100 LAKE ROAK

City:MEDINA

State:OH

ZIP:44256

Country:US

Info Phone Num:216-???-????

Emergency Phone Num:216-???-

????

CAGE:07700

=== Contractor Identification ===

Company Name:TECHNICAL WIRE PRODUCTS INC, DBA. TECKNIT

Address:129 DERMODY ST

Box:City:CRANFORD

State:NJ

ZIP:07016

Country:US

Phone:908-272-5500

CAGE:07700

=====
Composition/Information on Ingredients
=====

Ingred Name:NON-HAZARDOUS COMPONENTS (GAMMA-AMINOPROPYLTRIETHOXYSILANE)

Fraction by Wt: 100%

Other REC Limits:NONE SPECIFIED

=====
Hazards Identification
=====

Routes of Entry: Inhalation

:NO Skin:YES Ingestion:NO
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:AVOID CONTACT WITH SKIN OR EYES.
Effects of Overexposure:NONE

=====
===== First Aid Measures =====

First Aid:IMMEDIATELY FLUSH WITH PLENTY OF WATER FOR AT LEAST 15
MINUTES. FOR EYES, CALL A PHYSICIAN.

=====
===== Fire Fighting Measures =====

Flash Point Method:OC
Flash Point:220F,104C
Lower Limits:0.8
Upper Limits:4.5

Extinguishing Media:CO2 OR DRY CHEMICAL.
Fire Fighting Procedures:NONE
Unusual Fire/Explosion Hazard:NONE

=====
===== Accidental Release Measures =====

Spill Release Procedures:FLUSH AWAY SPILLED MATERIAL WITH LARGE VOLUMES
OF WATER.

=====
===== Handling and Storage =====

Handling and Storage Precautions:AVOID CONTACT WITH SKIN AND EYES. KEEP
CONTAINER TIGHTLY SEALED WHEN NOT IN USE.
Other Precautions:NONE

=====
===== Exposure C
ontrols/Personal Protection =====

Respiratory Protection:AIR-SUPPLIED MASK IN CONFINED AREAS.
Ventilation:LOCAL EXHAUST: PREFERABLE. MECHANICAL (GENERAL):
ACCEPTABLE.
Protective Gloves:RECOMMENDED.
Eye Protection:RECOMMENDED.
Other Protective Equipment:NOT REQUIRED.
Work Hygienic Practices:KEEP WORK AREA CLEAN.
Supplemental Safety and Health

=====
===== Physical/Chemical Properties =====

HCC:F2
Boiling Pt:B.P. Text:428F,220C
Vapor Pres:7.7 MM HG
Vapor Densit

y: