

BUCKEYE RUBBER PRODUCTS INC -- HOSE, NONMETALLIC, ZZ-H-428 TY-1, GRB, CL-2 --  
4720-00-288-9743

===== Product Identification =====

Product ID: HOSE, NONMETALLIC, ZZ-H-428 TY-1, GRB, CL-2

MSDS Date: 01/01/1987

FSC: 4720

NIIN: 00-288-9743

MSDS Number: BNWKL

=== Responsible Party ===

Company Name: BUCKEYE RUBBER PRODUCTS INC

Address: 637 N JACKSON ST

Box: 389

City: LIMA

State: OH

ZIP: 45802-0389

Country: US

Info Phone N

um: 419-228-4441 / FAX 419-222-5010

Emergency Phone Num: 419-228-4441

CAGE: 94519

=== Contractor Identification ===

Company Name: BUCKEYE RUBBER PRODUCTS INC

Address: 637 N JACKSON ST

Box: 389

City: LIMA

State: OH

ZIP: 45802-0389

Country: US

Phone: 419-228-4441

CAGE: 94519

===== Composition/Information on Ingredients =====

Ingred Name: "NOT HAZARDOUS"

Fraction by Wt: 100%

Other REC Limits: NONE RECOMMENDED

===== Hazards Identification =====

Routes of Entry

: Inhalation:YES Skin:NO Ingestion:NO  
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO  
Health Hazards Acute and Chronic:ACUTE- SMOKE DURING BURNING MAY CAUSE IRRITATION OF EYES, RESPIRATORY TRACT AND SKIN. CHRONIC- NONE KNOWN.  
Effects of Overexposure:SMOKE DURING BURNING MAY CAUSE IRRITATION OF EYES, RESPIRATORY TRACT AND SKIN.  
Medical Cond Aggravated by Exposure:NONE KNOWN.

=====  
===== First Aid Measures =====

First Aid:GET MEDICAL ATTENTION I  
F SYMPTOMS PERSIST. SKIN:WASH WITH  
SOAP & WATER. EYE:FLUSH WITH WATER FOR 15 MINUTES, HOLDING EYELIDS  
OPEN. INHALED:REMOVE TO FRESH AIR & PROVIDE OXYGEN/CPR IF NEEDED.  
ORAL:NOT LIKELY.

=====  
===== Fire Fighting Measures =====

Extinguishing Media:WATER, ABC DRY CHEMICAL, PROTEIN TYPE AIR FOAM. USE  
WATER SPRAY TO COOL FIRE EXPOSED CONTAINERS.  
Fire Fighting Procedures:WEAR NIOSH-APPROVED SELF-CONTAINED BREATHING  
APPARATUS.  
Unusual Fire/Explosion Ha  
zard:NONE KNOWN.

=====  
===== Handling and Storage =====

Handling and Storage Precautions:STORAGE- STORE IN A COOL, DRY  
VENTILATED AREA.  
Other Precautions:WASH THOROUGHLY AFTER HANDLING.

=====  
===== Exposure Controls/Personal Protection =====

Respiratory Protection:NIOSH-APPROVED DUST RESPIRATOR IF REQUIRED TO  
MAINTAIN EXPOSURES DURING CUTTING BELOW SAFE EXPOSURE LIMITS.  
Ventilation:REQUIRED DURING CUTTING.  
Protective Gloves:RECOMMENDED  
Eye Pro  
tection:DESIRABLE DURING CUTTING  
Other Protective Equipment:EYE BATH STATION  
Work Hygienic Practices:WASH EXPOSED SKIN SURFACES PRIOR TO EATING,  
DRINKING OR SMOKING TO MINIMIZE EXPOSURE.  
Supplemental Safety and Health

=====  
===== Physical/Chemical Properties =====

HCC:N1  
Solubility in Water:INSOLUBLE  
Appearance and Odor:HOSE

=====  
===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES  
NONE KNOWN.  
Stability Condition

to Avoid:FIRE, EXCESSIVE HEAT, FLAME

Hazardous Decomposition Products:CARBON MONOXIDE, CARBON DIOXIDE AND  
SMALL AMOUNT OF OXIDES OF NITROGEN, AROMATIC AND ALIPHATIC  
HYDROCARBONS

===== Disposal Considerations =====

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH ALL LOCAL, STATE  
AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department

o

f Defense. The United States of America in no manner whatsoever,  
expressly or implied, warrants this information to be accurate and  
disclaims all liability for its use. Any person utilizing this  
document should seek competent professional advice to verify and  
assume responsibility for the suitability of this information to their  
particular situation.