View NSN Online: https://aerobasegroup.de/nsn/3439-01-026-1084

GARDINER SOLDER CO DIV GARDINER METAL CO -- TIN LEAD ANTIMONY ALLOY: XM-200 CORE --3439-01-026-1084

Product ID:TIN LEAD ANTIMONY ALLOY: XM-200 CORE MSDS Date:05/01/1990 FSC:3439 NIIN:01-026-1084 MSDS Number: BPHPY === Responsible Party === Company Name: GARDINER SOLDER CO DIV GARDINER METAL CO Address:4820 SOUTH CAMPBELL AVENUE City:CHICAGO State:IL ZIP:60632-149 4 Country:US Info Phone Num:312-847-0100 Emergency Phone Num: 312-847-0100, CHEMTREC 800-424-9300 CAGE:84311 === Contractor Identification === Company Name: GARDINER SOLDER CO, DIV OF GARDINER METAL CO Address:4820 S CAMPBELL AVE Box:City:CHICAGO State:IL ZIP:60632-1416 Country:US Phone:312-847-0100/800-424-9300(CHEMTREC) CAGE:56244 Company Name: GARDINER SOLDER COMPANY DIV GARDINER METAL CO Address:4820 S CAMPBELL AVE Box:City:CHICAGO State:IL ZIP:60632-1494 Country:US Phone:312-847-0100 CHEMTRE C AFTER HOURS CAGE:84311 Ingred Name:LEAD (SARA III) CAS:7439-92-1 RTECS #: OF7525000 Fraction by Wt: 5-94.8% Other REC Limits: O.O3 MG/M3 OSHA PEL:0.05 MG/M3;1910.1025 ACGIH TLV:0.15 MG/M3;DUST 9192 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB Ingred Name: ANTIMONY (SARA III) CAS:7440-36-0 RTECS #:CC4025000 Fraction by Wt: 0.2-2%

Other REC Limits:NONE SPECIFIED OSHA PEL:0.5 MG/M3 Qty:5000 LBS

Ingred Name:TIN CAS:7440-31-5 RTECS #:XP7320000 Fraction by Wt: 5-94.8% Other REC Limits:NONE SPECIFIED OSHA PEL:2 MG/M3 ACGIH TLV:2 MG/M3; 9192

Ingred Name:ROSIN CAS:8050-09-7 Fraction by Wt: 0.5-3% Other REC Limits:NONE SPECIFIED OSHA PEL:0.1MG/M3 FORMALDEHYD ACGIH TLV:0.1MG/M3 FORMALDEHYD

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazar

ds Acute and Chronic:ACUTE-INHALATION OF FUMES(DURING SOLDERING): IRRITATION OF EYES AND RESPIRATORY TRACT SYSTEM. CHRONIC:LONG AND REPEATED EXPOSURE TO METAL FUMES MAY CAUSE HEADACHE, NAUSEA/VOMITING, ACHING BONES, FATIG UE, DECREASED APPETITE, ABDOMINAL CRAMPING, ANEMIA, BRAIN, HEART, LUNG, LIVER AND KIDNEY DEGENERATIVE CHANGES.

Explanation of Carcinogenicity:FORMALDEHYDE IS LISTED AS A PROBABLE CARCINOGEN BY NTP,IARC, EPA,& IT IS REGULATED BY OSHA.

Effects of Overexpos

ure: EXPOSURE TO FUMES MAY RESULT IN IRRITATION OF

NOSE, THROAT, EYES AND SKIN. BURNS FROM SKIN CONTACT OF MOLTEN SOLDER. WATERY EYES, HEADACHE, BREATHING DIFFICULTY, FREQUENT COUGHING.

Medical Cond Aggravated by Exposure:SOME WORKERS WITH PRE-EXISTING CONDITIONS OF LUNGS, EYES, SKIN, AND THOSE PREVIOUSLY EXPOSED TO LEAD & ANTMONY MAY BE AT INCREASED RISK.

First Aid:SKIN BURNS:FLUSH WITH COLD WATER OR APPLY

ICE. IN CASE OF SEVERE BURNS GET MEDICAL HELP. EYE IRRITATION:FLUSH WITH WATER FOR 15 MINUTES. INHALATION:REMOVE TO FRESH AIR. ADMINISTER OXYGEN IF BREATHING IS DIFFICULT. IF NOT BREATHING, BEGIN ARTIFICIAL RESPIRATION. GET MEDICAL HELP. INGESTION:GET MEDICAL HELP.

Extinguishing Media:DRY CHEMICAL. DO NOT USE WATER. Fire Fighting Procedures:FIRE FIGHTERS SHOULD USE NIOSH APPROVED SCBA & FULL PROTECTIVE E QUIPMENT WHEN FIGHTING CHEMICAL FIRE. USE WATER SPRAY TO COOL NEARBY CONTAINERS EXPOSED TO FIRE. Unusual Fire/Explosion Hazard:FIRE OR EXCESSIVE HEAT MAY CAUSE

PRODUCTION OF HAZARDOUS DECOMPOSITION PRODUCTS.

Spill Release Procedures:CLEAN UP ANY DUST OR WASTE RESIDUES AND PLACE IN SUITABLE DOT APPROVED CONTAINERS AND DISPOSE OF IN FULL COMPLIANCE WITH FEDERAL, STATE AND LOCAL REGULATIONS. AVOID INHALATION A ND SKIN EXPOSURE. Neutralizing Agent:NONE

Handling and Storage Precautions:NO SPECIAL REQUIREMENTS FOR STORAGE. WEAR GLOVES AND FLAME RETARDANT CLOTHING WHEN SOLDERING. Other Precautions:DO NOT BREATH FUMES WHILE SOLDERING.

======= Exposure Controls/Personal Protection ==========

Respiratory Protection:USE FUME/ORGANIC VAPOR RESPIRATOR OR AIR SUPPLIED RESPIRATOR WHEN SOLDERING IN A CONFINED SPACE OR WHERE LOCAL EXHAUST OR GENERAL VENTILATION DOES NOT KEEP EXPOSURE BELOW RECOMMENDED LIMITS. USE ONLY NIOSH APPROVED RESPIRATORS. Ventilation:USE ENOUGH VENTILATION WHEN SOLDERING TO KEEP THE DUST, FUMES & GASES BELOW TLV. Protective Gloves:LEATHER GLOVES Eye Protection:OSHA APPROVED GOGGLES/FACE SHIELD Other Protective Equipment:FLAME RETARDANT CLOTHING AND LEATHER GLOVES

WHEN SOLDERING. Work Hygienic Practices:WASH THOROUGHLY BEFORE EATING OR SMOKING.

LAUNDER CONTAMINATIED CLOTHI

## NG BEFORE REUSE. Supplemental Safety and Health

HCC:N1 Boiling Pt:B.P. Text:2516F,1380C Melt/Freeze Pt:M.P/F.P Text:361F,183C Vapor Pres:1 AT 1626F Solubility in Water:INSOLUBLE Appearance and Odor:SILVER GREY SOLID, ODORLESS

Stability Indicator/Materials to Avoid:YES STRONG OXIDIZING AGENTS. STRONG ACIDS. Stability Condition to Avoid:NONE Hazardous Decompo sition Products:TOXIC METAL FUMES ABOVE 886C(1627F). FROM THE ROSIN CORE; FORMALDEHYDE, CARBON MONOXIDE & DIOXIDE.

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH FEDERAL, STATE & LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expres

sly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.