View NSN Online: https://aerobasegroup.de/nsn/3439-01-009-2855

Product ID:FILLER METALS AND WELDING RODS, JB (10,14,38 MSDS Date:01/01/1987 FSC:3439 NIIN:01-009-2855 MSDS Number: BPVFW === Responsible Party === Company Name: RICKARD METALS INC Address:1707 S GROVE AVE City:ONTARIO State:CA ZIP:91761 Country:US Info Phone Num:714-947-4922/FAX -4909 Emergency Phone Num:714-947-4922 CAGE:67604 === Contractor Identification === Company Name: J B ALLOY CO INC Address:330 S 66TH ST Box:230070 **City:HOUSTON** State:TX ZIP:77011 Country:US Phone:713-926-3232 CAGE:4M698 Company Name: RICKARD METALS INC Address:1707 S GROVE AVE Box:City:ONTARIO State:CA ZIP:91761 Country:US Phone:714-947-4922 CAGE:67604

Ingred Name:NICKEL (SARA III) CAS:7440-02-0 RTECS #:QR5950000 Other REC Li mits:NONE RECOMMENDED OSHA PEL:1 MG/M3 ACGIH TLV:1 MG/M3; 9293

Ingred Name:BORON CAS:7440-42-8 RTECS #:ED7350000 Other REC Limits:NONE RECOMMENDED ACGIH TLV:10 MG/M3 (MFR)

Ingred Name:IRON CAS:7439-89-6 RTECS #:NO4565500 Other REC Limits:NONE RECOMMENDED OSHA PEL:5 MG/M3 (MFR) ACGIH TLV:10 MG/M3 (MFR)

Ingred Name:SILICON CAS:7440-21-3 RTECS #:VW0400000 Other REC Limits:NONE RECOMMENDED OSHA PEL:15 MG/M3 TDUST ACGIH TLV:10 MG/M3 TDUST; 9293

Ingred Name:CHROMIUM (SARA III) CAS:7440-47-3 RTECS #:GB4200000 Other REC Limits:NONE RECOMMENDED OSHA PEL:1 MG/M3 ACGIH TLV:0.5 MG/M3; 9293 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name:SILICON CAS:7440-21-3 RTECS #:VW0400000 Other REC Limits:NONE RECOMMENDED OSHA PEL:15 MG/M3 TDUST ACGIH TLV:10 MG/M3 TDUST; 9293

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:NO Health Hazards Acute and Chronic:ACUTE-FUMES & GASE S CAN BE DANGEROUS TO YOUR HEALTH.ARC RAYS CAN INJURE EYES & BURN SKIN.ELECTRIC SHOCK CAN KILL.INHALATION OF FUMES MAY CAUSE DIZZINESS, NAUSEA, DRYNESS/IRRITATION OF NOSE, THROAT/EYES, TIGHTNESS IN CHEST, FEVER & ALLERGIC REACTIONS. MAY LEAD TO SIDEROSIS & AFFECT PULMONARY FUNCTION.CHRONIC-CAN CAUSE CANCER. Explanation of Carcinogenicity: CONTAINS NICKEL AND CHROMIUM. Effects of Overexposure: FUMES & GASES CAN BE DANGEROUS TO YOUR HEALTH. ARC RAYS CAN INJURE EYES & BURN SKIN. EL ECTRIC SHOCK CAN KILL. INHALATION OF FUMES MAY CAUSE DIZZINESS, NAUSEA, DRYNESS/IRRITATION OF NOSE, THROAT/EYES, TIGHTNESS IN CHEST, FEVER & ALLERGIC REACTIONS. MAY LEAD TO SIDEROSIS & AFFECT PULMONARY FUNCTION. Medical Cond Aggravated by Exposure: PRE-EXISTING SKIN DISORDERS MAY BE MORE SUSCEPTIBLE TO THIS MATERIAL. First Aid:GET MEDICAL ATTENTION IF SYMPTOMS PERSIST. SKIN:WASH WITH SOAP & WATER, EYE:FLUS H WITH WATER FOR 15 MINUTES, HOLDING EYELIDS OPEN. INHALED: REMOVE TO FRESH AIR. PROVIDE OXYGEN/CPR IF NEEDED. **ORAL: GET P ROMPT MEDICAL ATTENTION.** Flash Point:NONE Extinguishing Media:WATER SPRAY, CARBON DIOXIDE, FOAM OR DRY CHEMICAL FOR SURROUNDING FIRE. USE WATER SPRAY TO COOL FIRE EXPOSED CONTAINERS. Fire Fighting Procedures: WEAR FULL PROTECTIVE CLOTHING AND NIOSH-APPROVED SELF-CONTAINED BREATHING APPARA TUS WITH FULL FACEPIECE OPERATED IN THE POSITIVE PRESSURE MODE. Unusual Fire/Explosion Hazard:WELDING ARC AND SPARKS CAN IGNITE COMBUSTIBLES AND FLAMMABLES. Handling and Storage Precautions: STORAGE- STORE IN DRY PLACE.

Other Precautions: AN ADEQUATE EXHAUST SYSTEM IS REQUIRED TO AVOID THE EFFECT OF FUMES. DO NOT INHALE FUMES OR DUST. WASH THOROUGHLY AFTER HANDLING.

======= Exposure Controls/Personal Prot

ection ==========

Respiratory Protection: USE NIOSH APPROVED SUPPLIED AIR RESPIRATORY PROTECTION OR RESPIRABLE FUME RESPIRATOR WHEN WELDING, BRAZING OR SOLDERING IN CONFINED SPACE OR WHERE LOCAL EXHAUST OR VENTILATION DOES NOT KEEP EXPOSURE B ELOW TLV. Ventilation:LOCAL EXHAUST Protective Gloves:WELDER'S GLOVES Eye Protection: CHEMICAL SAFETY GOGGLES Other Protective Equipment: EYE WASH STATION, QUICK DRENCH SHOWER AND **IMPERVIOUS CLOTHING** Work Hygienic Practices: OBSERVE GOOD PE **RSONAL HYGIENE PRACTICES AND** RECOMMENDED PROCEDURES. Supplemental Safety and Health THE MSDS WAS UNDATED. THE MANUFACTURER STATED THAT THE ORIGINAL MSDS WAS WITHOUT DATE AND THEY ARE NOT MAKING PRODUCT SINCE 1987. HCC:N1 Stability Indicator/Materials to Avoid:YES NONE Stability Condition to Avoid:NONE Hazardous Decomposition Products: CARBON MONOXIDE . CARBON DIOXIDE. OZONE, NITROGEN OXIDES MAY BE FORMED. 

Waste Disposal Methods:PREVENT WASTE FROM CONTAMINATING SURROUNDING ENVIRONMENT. DISCARD ANY PRODUCT RESIDUE, DISPOSABLE CONTAINER OR LINER IN AN ENVIRONMENTALLY ACCEPTABLE MANNER, IN FULL COMPLIANCE WITH FEDERAL, STATE & L OCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by

## elements of the Department

of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.