

MG INDUSTRIES -- HALOCARBON 22 -- 6830-00-782-3930

===== Product Identification =====

Product ID:HALOCARBON 22
MSDS Date:11/25/1985
FSC:6830
NIIN:00-782-3930
MSDS Number: BPXDX
=== Responsible Party ===
Company Name:MG INDUSTRIES
Address:2460 BOULEVARD OF THE GENERALS
Box:945
City:VALLEY FORGE
State:PA
ZIP:19482
Country:US
Info Phone Num:215-630-5422
Emergency Phone Num:215-630-5422
CAGE:08772

===

Contractor Identification ===
Company Name:MG INDUSTRIES
Address:3 GREAT VALLEY PKY
Box:City:MALVERN
State:PA
ZIP:19355-1424
Country:US
Phone:610-695-7400 / 610-695-7449
CAGE:08772
Company Name:PHOENIX INDUSTRIES INC
Address:11711 S ALAMEDA ST
Box:54083
City:LOS ANGELES
State:CA
ZIP:90054
Country:US
Phone:213-564-5711
CAGE:0MLP0

===== Composition/Information on Ingredients =====

Ingred Name:DICHLORODIFLUOROMETHANE
CAS:75-71-8
RTECS #:PA8200000
Fraction by Wt: 100%
Other REC

Limits:NONE SPECIFIED
OSHA PEL:1000 PPM
ACGIH TLV:1000 PPM
EPA Rpt Qty:5000 LBS
DOT Rpt Qty:5000 LBS
Ozone Depleting Chemical:1

===== Hazards Identification =====

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO
Health Hazards Acute and Chronic:EXPOSURE TO THE LIQUID OR CONCENTRATED VAPOR MAY CAUSE SKIN OR EYE IRRITATION.
Effects of Overexposure:INHALATION OF HIGH CONCENTRATIONS OF VAPOR MAY CAUSE LIGHT-HEADEDNESS, GIDDINESS, DISORIENTATION, NAUSEA,
VOMITING, NARCOSIS, CARDIAC DYSRHYTHMIA, HYPOTENSION & DEATH.
CONTACT WITH THE RAPIDLY EVAPORATING LIQUID MAY CAUSE FROSTBITE OR CRYOGENIC "BURNS".
Medical Cond Aggravated by Exposure:FROSTBITE EFFECTS ARE A CHANGE IN COLOR OF SKIN TO GRAY OR WHITE POSSIBLY FOLLOWED BY BLISTERING.

===== First Aid Measures =====

First Aid:INHALE: CONSCIOUS PERSON SHOULD BE ASSISTED TO AN UNCONTAMINATED AREA & INHALE FRESH AIR. UNCONSCIOUS PERSONS SHOULD
BE MOVED TO AN UNCONTAMINATED AREA, GIVEN MOUTH-TO-MOUTH RESUSCITATION AND SUPPLEMENTAL OXYGEN. FURTHER TREATMENT SHOULD BE SYMPTOMATIC AND SUPPORTIVE. DERMAL CONTACT OR FROSTBITE: REMOVE CONTAMINATED CLOTHING AND FLUSH AREAS WITH LUKEWARM WATER.

===== Fire Fighting Measures =====

Extinguishing Media:NON FLAMMABLE GAS.
Unusual Fire/Explosion Hazard:IF HALOCARBON 22 IS INVOLVED IN A FIRE, IT MAY DECOMPOSE YIELDING TOXIC PRODUCTS.

===== Accidental Release Measures =====

Spill Release Procedures:EVAC AREA. USE APPROPRIATE PROTECTIVE EQUIP. IF LEAK IS IN USER'S EQUIP, BE CERTAIN TO PURGE PIPING WITH AN INERT GAS PRIOR TO ATTEMPTING REPAIRS. IF LEAK IS IN CONTAINER/CONTAINER VALVE, CONTACT CLOSEST SUPPLIER LOCATION OR CALL EMERGENCY PHONE NUMBER LISTED HEREIN.

===== Handling and Storage =====

Handling and Storage Precautions:PROTECT CYLINDERS FROM PHYSICAL DAMAGE.

STORE IN COOL, DRY, WELL-VENTILATED AREAS AWAY FROM HEAVILY
TRAFFICKED AREAS AND EMERGENCY EXITS.

Other Precautions:USE PRESS REDUCING REGULTR WHEN CONNECT CYL TO LWR
PRESS (