View NSN Online: https://aerobasegroup.de/nsn/9150-01-099-2845

ZURN O F CO -- ZURN WAYLUBE #80 -- 9150-01-099-2845

Product ID:ZURN WAYLUBE #80

MSDS Date:01/04/1988

FSC:9150

NIIN:01-099-2845

MSDS Number: BSFRW
=== Responsible Party ===
Company Name:ZURN O F CO
Address:2738 N BROAD ST

Box:6779

City:PHILADELPHIA

State:PA

ZIP:19132-2721 Country:US

Info Phone Num:215-229-5268

Emergency Phone Num:215-229-5268

CAGE:55004 === Contra

ctor Identification ===

Company Name: ZURN O F CO Address: 2736 N BROAD ST

Box:6779

City:PHILADELPHIA

State:PA

ZIP:19132-2721 Country:US

Phone:215-229-5268

CAGE:55004

======= Composition/Information on Ingredients ========

Ingred Name:OIL MIST

Other REC Limits: NONE RECOMMENDED

OSHA PEL:5 MG/M3 ACGIH TLV:5 MG/M3

========= Hazards Identification ===============

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OS

Explanation of Carcinogenicity:NOT CARCINOGENIC. Effects of Overexposure:INGESTION MAY CAUSE GASTRIC UPSET. PROLONGED EYE AND SKIN CONTACT MAY CAUSE IRRITATION. Medical Cond Aggravated by Exposure:UNKNOWN.
======================================
First Aid:INGESTION-CALL PHYSICIAN AT ONCE. EYE-FLUSH WITH WATER FOR 15 MINUTES. SEEK MEDICAL ATTENTION FOR IRRITATION. SKIN-REMOVE CONTAMINATED CLOTHING. WASH WITH SOAP & WATER.
======================================
Flash Point Method:COC Flash Point:275F,135C Lower Limits:0.9 Upper Limits:7.0
Extinguishing Media:FOAM, DRY CHEMICAL, CARBON DIOXIDE, WATER SPRAY OR FOG.
Fire Fighting Procedures:USE AIR-SUPPLIED BREATHING APPARATUS FOR ENCLOSED AREAS. COOL EXPOSED CONTAINERS WITH WATER. AVOID BREATHING VAPORS OR FUMES.
Unusual Fire/Explosion Hazard:DO NOT MIX WITH STRONG OXIDANTS. KEEP AREA FREE FROM IGNIT
ION SOURCES. EMPTY CONTAINERS RETAIN PRODUCT RESIDUE; DO NOT PRESSURIZE, CUT WELD OR EXPOSE TO FLAME.
======== Accidental Release Measures =========
Spill Release Procedures:REMOVE ALL SOURCES. KEEP PEOPLE AWAY. RECOVER FREE LIQUID. ADD ABSORBENT TO SPILL AREA. KEEP MATERIAL OUT OF SEWERS AND WATER COURSES BY DIKING AND IMPOUNDING.
=========== Handling and Storage ============
Handling and Storage Precautions:KEEP CONTAINERS CLOSED WHEN NOT IN
USE. DO NOT HANDLE OR STORE NEAR HEAT, SPARKS, FLAME OR STRONG OXIDANTS. VENTILATE ADEQUATELY.
Other Precautions:NONE SPECIFIED BY MANUFACTURER.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:NORMALLY NOT REQUIRED. Ventilation:LOCAL EXHAUST-SUFFICIENT TO MAINTAIN SAFE EXPOSURE LEVELS. Protective Gloves:CHEMICAL RESISTANT GLOVES. Eye Protection:SPLASH GOGGLES OR FACE SHIELD. Other Protective Equipment:CHEMICAL RESISTANT APRON IS RECOMME

HA:NO

Health Hazards Acute and Chronic:NONE KNOWN.

NDED TO AVOID REPEATED SKIN CONTACT. Work Hygienic Practices: WASH HANDS AND EXPOSED AREAS WITH SOAP AND WATER AFTER PRODUCT USE AND LAUNDER CONTAMINATED CLOTHING BEFORE REUSE. Supplemental Safety and Health NONE. ======== Physical/Chemical Properties ============= HCC:V6 Boiling Pt:B.P. Text:500F,260C Vapor Pres:NIL Vapor Density: OVER 5 Spec Gravity: 0.8684 Evaporation Rate & Dr. Reference: NIL Solubility in Water:NIL Appearance and Odor: DARK AMBER COLORED LIQUID WIT H SULPHUR ODOR. ========= Stability and Reactivity Data ============= Stability Indicator/Materials to Avoid:YES

STRONG OXIDANTS.

Stability Condition to Avoid: NONE SPECIFIED BY MANUFACTURER. Hazardous Decomposition Products: FUMES, SMOKE, CARBON DIOXIDE AND/OR CARBON MONOXIDE.

======= Disposal Considerations ===============

Waste Disposal Methods: INCINERATE IN CONFORMITY WITH ALL REGULATIONS OR DISPOSE OF AT APPROVED LANDFILL SITE CONFORMING TO ALL FE DERAL.

STATE, AND LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of thi

