View NSN Online: https://aerobasegroup.de/nsn/6830-00-965-9647

Product ID:HALON 1301 CF3BR MSDS Date:01/01/1991 FSC:6830 NIIN:00-965-9647 MSDS Number: BSKTY === Responsible Party === **Company Name: METALCRAFT INC** Address:718 DEBELIUS AVE City:BALTIMORE State:MD ZIP:21205 Country:US Info Phone Num:301-485-0880 Emergency Phone Num:800-457-4280 CAGE:06535 === Contractor Ident ification === Company Name:METALCRAFT INC Address:9331 PHILADELPHIA ROAD Box:City:BALTIMORE State:MD ZIP:21237 Country:US Phone:410-687-5500 CAGE:06535 Ingred Name: BROMOTRIFLUOROMETHANE (HALON 1301) (SARA III) CAS:75-63-8 RTECS #:PA5425000 Fraction by Wt: 100% Other REC Limits:NONE RECOMMENDED OSHA PEL:1000 PPM ACGIH TLV:1000 PPM; 9394 **Ozone Depleting Chemical:1**

LD50 LC50 Mixture:ORAL LD50 (RAT) IS UNKNOWN. Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:EYES: CONTACT WITH LIQUID CAN CAUSE

"FREEZER" BURNS. SKIN: CONTACT WITH LIQUID CAN CAUSE FROSTBITE. INHALATION: AT CONCENTRATIONS >20,000 PPM, IRREGULARITIES IN CENTRAL NERVOUS SYSTEM AND CARDIAC MUSC LE ARE EXHIBITED. INGESTION: MILDLY TOXIC BY INGESTION, AFFECTING CENTRAL NERVOUS SY

STEM.

Effects of Overexposure:EYES: "FREEZER" BURNS. SKIN: FROSTBITE. INHALATION: IRREGULARITIES IN CENTRAL NERVOUS SYSTEM AND CARDIAC MUSCLE. INGESTION: CENTRAL NERVOUS SYSTEM EFFECTS.

Medical Cond Aggravated by Exposure:ANEMIA, ASTHMA, DERMAL SENSITIVITY AND LOW BLOOD PRESSURE.

First Aid:EYES: FLUSH WITH LARGE AMOUNTS OF WATER. IF IRRITATION PERSISTS, GET MEDICAL ATTENTION. SKIN: REMOVE CONTAMINATED CLOT

HING. WASH AREA WITH LARGE AMOUNTS OF WATER. IF IRRITATION PERSISTS, GET MEDICAL A TTENTION. INHALATION: IF ADVERSE SYMPTOMS DEVELOP, MOVE TO FRESH AIR AND GIVE OXYGEN IF NEEDED. GET MEDICAL ATTENTION. INGESTION: FOR LARGE AMOUNTS INGESTED, INDUCE VOMITING. GET MEDICAL ATTENTION.

Extinguishing Media:NON-FLAMMABLE. USE MEDIA SUITABLE FOR SURROUNDING FIRE.

Fire Fighting Procedures:WEAR FULL PROTECTIVE CLOTHING AND NIOSH-

APPROVED SELF-CONTAINED BREATHING APPARATUS WITH FULL FACEPIECE, OPERATED IN THE POSITIVE PRESSURE MODE.

Unusual Fire/Explosion Hazard:MOVE CONTAINER FROM FIRE AREA, IF POSSIBLE. COOL FIRE EXPOSED CONTAINERS WITH WATER WELL AFTER FIRE IS OUT, TO PREVENT POSSIBLE EXPLOSIONS.

Spill Release Procedures:WEAR PROTECTIVE EQUIPMENT. VENTILATE AREA AND REMOVE ALL IGNITION SOURCES. CONTAIN SPILL BY BUIL DING A DIKE USING ABSORBENT MATERIAL. COLLECT SPILL WITH ABSORBENT MATERIAL AND PLACE INTO A DRUM APPROV ED FOR WASTE DISPOSAL. Neutralizing Agent:NONE SPECIFIED BY MANUFACTURER.

Handling and Storage Precautions:STORE IN TIGHTLY CLOSED CONTAINER IN A COOL, WELL-VENTILATED AREA AWAY FROM HEAT, SPARKS, OPEN FLAMES, HOT SURFACES AND INCOMPATIBLE MATERIALS.

Other Precautions: AVOID EYE AND SKIN CONTACT. WHEN TRANSFE RRING FROM

CONTAINERS, GROUND AND BOND BOTH CONTAINERS. DO NOT INHALE VAPORS. KEEP OUT OF REACH OF CHILDREN.

======= Exposure Controls/Personal Protection ==========

Respiratory Protection:NONE REQUIRED UNDER NORMAL CONDITIONS. WHERE EXPOSED TO DUST/FUMES WEAR NIOSH RESPIRATOR FOR DUST/MISTS/FUMES APPROVED FOR THE AIRBORNE CONCENTRATION. WHERE VAPORS ARE GENERATED, USE NIOSH ORGANIC RES PIRATOR APPROVED FOR THE EXPOSURE. Ventilation:PROVIDE SUFFICIENT MECHANICAL (GENERAL) AND/OR LOCAL

EXHAUST VENTILATION TO MAINTAIN EXPOSURE BELOW APPROVED PEL OR TLV. Protective Gloves:NITRILE OR NATURAL RUBBER GLOVES.

Eye Protection: SPLASH PROOF GOGGLES WITH SIDE SHIELDS.

Other Protective Equipment: WEAR IMPERVIOUS BODY COVERING AND BOOTS WHERE SPILLS OR SPLASHING OCCUR.

Work Hygienic Practices: WASH AFTER HANDLING AND BEFORE EATING,

DRINKING, OR SMOKING. LAUNDER CONTAMINATED CLOTHING BEFORE REUSE. Supplemental Safety and Health

HCC:G3 Boiling Pt:B.P. Text:-72F,-58C Melt/Freeze Pt:M.P/F.P Text:-270F,-168C Vapor Pres:220 PSIG Vapor Density:5.14 Spec Gravity:1.54 Solubility in Water:NEGLIGIBLE Appearance and Odor:CLEAR, LIQUEFIED GAS. SLIGHT ETHEREAL ODOR. Percent Volatiles by Volume:100

Stability Indicator/Materials to Avoid:YES ALKALINE EARTH METALS, ALKALI, POWDERED ALUMINUM, ZINC, BERYLLIUM. Stability Conditi on to Avoid:EXPOSURE TO FLAMES OR HOT SURFACES ABOVE 850F (454C).

Hazardous Decomposition Products:HYDROBROMIC, HYDROCHLORIC AND HYDROFLUORIC ACIDS, POSSIBLY FREE HALIDES AND CARBONYL HALIDES. Conditions to Avoid Polymerization:WILL NOT OCCUR.

Waste Disposal Methods:DISPOSE OF WASTE IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS. RECOVERED MATERIAL CAN BE INCINERATED IN A FURNACE WHERE PERMITTED.

Dis

claimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.