View NSN Online: https://aerobasegroup.com/nsn/8010-00-181-8281

Product ID:CAT, MIL-C-83286, 17925 UNTINTED P/C 03W040CAT MSDS Date:05/26/1992 FSC:8010 NIIN:00-181-8281 Kit Part:Y **MSDS Number: BTCLD** === Responsible Party === Company Name: DEFT INC CHEMICAL COATING DIV Address:17451 VON KARMAN AVE City:IRVINE State:CA ZIP:92714-6205 Country:US Info Phone Num:714-474-0400 Emergency Phone Num:800-424-9300 CHEMTREC Preparer's Name:NORM GAUL CAGE:33461 === Contractor Identification === Company Name: DEFT, INC. Address:17451 VON KARMAN AVE City:IRVINE State:CA ZIP:92614 Country:US Phone:949-474-0400 CAGE:33461

Ingred Name:ALIPHATIC ISOCYANATE BIURET OF HMDI CAS:4035-89-6 Fraction by Wt: 30% Other REC Limits:NONE RECOMMENDED ACGIH TLV:0.005 PPM TWA

Ingr

ed Name: HEXAMETHYLENE DIISOCYANATE [HDI] FREE MONOMER > 0.5% AT TIME OF MFR, AFTER 3-6 MO, MAY RISE TO MAX 1.6%. CAS:822-06-0 RTECS #:MO1740000 Fraction by Wt: 0.5-1.6% Other REC Limits:NONE RECOMMENDED ACGIH TLV:0.005 PPM EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB Ingred Name:N-BUTYL ACETATE (SARA III) (VAPOR PRESSURE 13 MM HG @ 68F) CAS:123-86-4 RTECS #:AF7350000 Fraction by Wt: 5% Other REC Limits:NONE RECOMMENDED OSHA PEL:150 PPM;STEL 200 PPM ACGIH TLV:150 PPM;STEL 200 PPM EPA Rpt Qty:5000 LBS D OT Rpt Qty:5000 LBS Ingred Name:XYLENE (SARA III) (VAPOR PRESSURE 21 MM HG @ 100F) CAS:1330-20-7 RTECS #:ZE2100000 Fraction by Wt: 4.35% Other REC Limits:NONE RECOMMENDED OSHA PEL:100 PPM;STEL 150 PPM ACGIH TLV:100 PPM;STEL 150 PPM EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS Ingred Name: ETHYL BENZENE (SARA III) (VAPOR PRESSURE 7.1 MM HG @ 68F) CAS:100-41-4 RTECS #:DA0700000 Fraction by Wt: 0.89% Other REC Limits:NONE RECOMMENDED OSHA PEL:100 PPM;STEL 125 PPM ACGIH TLV:100 PPM;STEL 125 PPM EPA R pt Qty:1000 LBS DOT Rpt Qty:1000 LBS Ingred Name: ETHYL 3-ETHOXYPROPIONATE (VAPOR PRESSURE 0.7 MM HG @ 68F) CAS:763-69-9 RTECS #:UF3325000 Fraction by Wt: 10% Other REC Limits:50 PPM; STEL 100 PPM Ingred Name: METHYL ETHYL KETONE (SARA III) (VAPOR PRESSURE 70 MM HG @ 68F) CAS:78-93-3 RTECS #:EL6475000 Fraction by Wt: 46.56% Other REC Limits:NONE RECOMMENDED OSHA PEL:200 PPM;STEL 300 PPM ACGIH TLV:200 PPM;STEL 300 PPM EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

:9999999VO Other REC Limits:NONE RECOMMENDED

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:INHAL: RESP TRACT IRRIT,NERV SYS DEPRESS (HEADACHE,DIZZY,STAGGER,CONFUSION,UNCONSCIOUS,COMA). SKIN: ISOCYANATE REACT W/PROTEIN CAUSING IRRIT (SWELL,RED,RASH). ABSORPT: IRRIT,DRYING,DEFATTING (CRACKING). EYE: IRRIT (TEAR,RED,SWELL

W/STING).INGEST: IRRIT,CORROSIVE IN GI TRACT. VOMIT MAY CAUSE ASPIRATION-CHEM PNEUMONITIS

Effects of Overexposure:ACUTE: VAPOR IRRITATING TO EYES, NOSE, THROAT. INHALATION MAY CAUSE HEADACHES, DIFFICULT BREATHING & UNCONSCIOUSNESS. CHRONIC: AS RESULT OF PREVIOUS REPEATED OVEREXPOSURE OR SINGLE LARGE DOSE, SOME WILL DEVELOP ISOCYANATE SENSITIZATION WHICH WILL CAUSE THEM TO REACT TO LATER ISOCYANATE EXPOSURE WELL BELOW TLV.

Medical Cond Aggravated by Exposure:AS THMA AND ANY OTHER RESPIRATORY

DISORDERS. SKIN ALLERGIES, ECZEMA, AND DERMATITIS. ISOCYANATE SENSITIZATION.

First Aid:INHAL: MOVE TO FRESH AIR. RESTORE BREATHING. ASTHMATIC TYPE SYMPTOMS MAY DEVELOP. GET MEDICAL AID. SKIN: REMOVE CONTAMINATED CLOTHES. WASH AFFECTED AREAS W/SOAP & WATER. WASH CONTAMINATED CLOTHING BEF ORE REUSE. EYES: FLUSH W/LUKEWARM WATER(LOW PRESSURE) 15 MIN, OCCASIONALLY LIFTING EYE

LIDS. GET MED AID. INGESTION: DO NOT INDUCE VOMITING. DO NOT GIVE ANYTHING TO AN UNCONSCIOUS PERSON. GET MED AID.

Flash Point Method:TCC Flash Point:23.0F,-5.0C Lower Limits:1.00 Upper Limits:11.00 Extinguishing Media:FOAM, ALCOHOL FOAM, CO2, DRY CHEMICAL, WATER FOG, WATER SPRAY Fire Fighting Procedures:USE FULL PROTECT CLOTH/FIREFIGHT EQUIP W/SCBA. WATER MAY BE USED TO COOL CLSD CNTNRS (PREVENT PRESS BLDU P/AUTOIGNIT/EXPLOS). HDI/IRRIT VAPOR GENERATED BY FIRE. Unusual Fire/Explosion Hazard:KEEP CNTNR CLSD. KEEP FROM HEAT/IGNIT SOURCE. CLSD CNTNR MAY EXPLODE W/HEAT. APPLIC TO HOT SURFACE REQ SPECIAL PRECAUTION. OVEREXPOSURE TO DECOMP PROD-HLTH HZD.

Spill Release Procedures: EVACUATE ALL NON-ESSENTIAL PERSONNEL. REMOVE ALL SOURCES OF IGNITION (FLAME, SPARK SOURCES, HOT SURFACES). VENTILATE AREA. CONTAIN AND REMOVE WITH INERT ABSORBENT AND NON-SPARKING TOOLS.

Handling and Storage Precautions:STORE IN BLDGS IN COMPLY W/OSHA 1910.106. AVOID STORING NEAR HIGH TEMPERATURES/IGNITION SOURCES. STORE IN CLOSED CONTAINERS IN WELL VENTILATED AREA.
Other Precautions:KEEP CONTAINERS TIGHT & UPRIGHT (PREVENT LEAK). PREVENT PROLONGED VAPOR BREATHING. PROLONGED OVEREXPOSURE MAY CAUSE ALLERGIC REACTION. AVOID CONTACT WITH SKIN & EYES

. DO NOT INGEST.

DON'T HANDLE TILL MFR SFTY PRECAUTIONS READ/UNDERSTOOD.

======= Exposure Controls/Personal Protection ==========

Respiratory Protection: A RESPIRATOR RECOMMENDED FOR ORGANIC VAPOR ENVIRONMENT (AIR PURIFYING OR FRESH AIR SUPPLIED). OBEY OSHA REGS FOR RESPIRATOR USE. PROVIDE VENT TO KEEP EXPOSURE LEVELS BELOW PEL. USE VAPOR PARTICULATE R SPRTR (TC23C) WHEN BELOW 10X TLV/PEL. Ventilation: EXHAUST VENT TO KEEP AIRBORNE CONCENTRATIONS BELOW TLV'S. REMO VE ALL IGNITION SOURCES. Protective Gloves: COTTON, NEOPRENE, RUBBER, POLYETHYLENE Eye Protection: SPLASH GUARDS, SIDE/FACE SHIELDS, GOGGLES Other Protective Equipment: THE USE OF LONG SLEEVE AND LONG LEG CLOTHING IS RECOMMENDED. REMOVE AND WASH CONTAMINATED CLOTHING BEFORE REUSE. Work Hygienic Practices: WASH HANDS BEFORE EATING, SMOKING, OR USING WASHROOM. SMOKE IN SMOKING AREAS ONLY.

Supplemental Safety and Health

HCC:F2

Boiling Pt:B.P. Text:175 TO 338F Vapor Density:>AIR Spec Gravity:0.91477 Viscosity:* Evaporation Rate & amp; Reference:3.36 X N-BUTYL ACETATE Solubility in Water:INSOLUBLE Appearance and Odor:AMBER LIQUID WITH SOLVENT ODOR Percent Volatiles by Volume:74.9

Stability Indicator/Materials to Avoid:YES
WATER, AMINES, STRONG BASES, ALCOHOLS, METAL COMPOUNDS AND SURFACE ACTIVE MATERIALS.
Stability Condition to Avoid:CONTACT WITH
MOISTURE, MATERIAL WHICH REACT WITH ISOCYANATES AND HIGH TEMPERATURES.
Hazardous Decomposition Products:BY HIGH HEAT/TEMPERATURE: CARBON MONOXIDE, CARBON DIOXIDE, AND OXIDES OF NITROGEN, TRACES OF HCN &

HDI.

Waste Disposal Methods:DISPOSE OF WASTE IN ACCORDANCE WITH FEDERAL, STATE, & LOCAL ENVIRONMENTAL CONTROL REGULATIONS. EMPTY CONTAINERS MUST BE HANDLED WITH CARE, DUE TO PRODUCT RESIDUE & FLAMMABLE V

APOR. DON'T INCINERATE CL OSED CONTAINERS. EPA CODE: D001, F003, F005.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume respons ibility for the suitability of this information to their

particular situation.