

HARVEY WILLIAM H CO -- PLUMBER'S PUTTY -- 8030-00-221-3823

=====  
Product Identification  
=====

Product ID:PLUMBER'S PUTTY

MSDS Date:07/01/1986

FSC:8030

NIIN:00-221-3823

MSDS Number: BTSVX

=== Responsible Party ===

Company Name:HARVEY WILLIAM H CO

Address:4350 LAFAYETTE AVE

City:OMAHA

State:NE

ZIP:68131-1026

Country:US

Info Phone Num:402-553-0479 / FAX 402-553-4826

Emergency Phone Num:402-553-0479

C

AGE:51947

=== Contractor Identification ===

Company Name:WILLIAM H HARVEY CO

Address:4334 SOUTH 67TH ST

Box:City:OMAHA

State:NE

ZIP:68117-1019

Country:US

Phone:800-228-9681

CAGE:51947

=====  
Composition/Information on Ingredients  
=====

Ingred Name:NON HAZARDOUS INGREDIENT

Fraction by Wt: 100%

Other REC Limits:NONE RECOMMENDED

=====  
Hazards Identification  
=====

Routes of Entry: Inhalation:NO Skin:YES Ingestion:NO

Reports of Carcinogenicity:N

TP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:APPEARS TO BE NO SIGNIFICANT RISK.

Explanation of Carcinogenicity:NOT CONSIDERED TO BE CARCINOGENIC.

Effects of Overexposure:INHALATION-POSSIBLE LIGHT HEADEDNESS OR MAY CAUSE HEADACHE. EYES-MAY CAUSE IRRITATION. INGESTION-HAS LAXATIVE PROPERTIES AND MAY RESULT IN ABDOMINAL CRAMPS AND DIARRHEA.

Medical Cond Aggravated by Exposure:NONE.

===== First Aid Measures =====

First Aid:REMOVE VICTIM TO FRESH AIR, SEEK MEDICAL ATTENTION IF CONDITION PERSISTS.

===== Fire Fighting Measures =====

Flash Point Method:COC

Flash Point:650F,343C

Extinguishing Media:CARBON DIOXIDE, FOAM AND DRY CHEMICAL.

Fire Fighting Procedures:USE WATER SPRAY TO COOL FIRE EXPOSED MATERIAL AND TO PROTECT PERSONNEL.

Unusual Fire/Explosion Hazard:NONE.

===== Accidental Release Measures =====

Spill Release Procedures:NO SPECIAL PRECAUTION - SCOOP UP SPILLED

MATERIAL, IT CAN BE REUSED IF IT IS NOT DIRTY OR CONTAMINATED.

===== Handling and Storage =====

Handling and Storage Precautions:STORE AWAY FROM HEAT, KEEP CONTAINER CLOSED AFTER USE.

Other Precautions:KEEP OUT OF REACH OF CHILDREN AND PETS.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:NO SPECIAL REQUIREMENTS.

Ventilation:LOCAL EXHAUST-OPEN AREA IS SUFFICIENT.

Protective Gloves:NONE REQUIRED.

E

Eye Protection:NONE REQUIRED.  
Other Protective Equipment:NONE.  
Work Hygienic Practices:USE NORMAL GOOD HYGIENIC PRACTICES.  
Supplemental Safety and Health  
NONE.

===== Physical/Chemical Properties =====

HCC:N1  
Spec Gravity:2  
Solubility in Water:NEGLIGIBLE  
Appearance and Odor:GREY - PUTTY WITH PETROLEUM ODOR.

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES  
NONE - KEEP AWAY FROM HEAT 250 OR MORE AND FLAME AND STRONG OXIDIZING AGENTS.  
Stability Condition to Avoid:SOURCES OF HEAT.  
Hazardous Decomposition Products:PARTIAL BURNING WOULD PRODUCE SMOKE OR FUMES.

===== Disposal Considerations =====

Waste Disposal Methods:PLACE IN TRASH CONTAINER AND DISPOSE OF ACCORDING TO FEDERAL, STATE AND LOCAL REGULATIONS.

=====

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.