View NSN Online: https://aerobasegroup.com/nsn/6850-00-281-4033

## DOW CORNING CORP -- 340 HEAT SINK COMPOUND, DC 340 -- 6850-00-281-4033

Product ID:340 HEAT SINK COMPOUND, DC 340

MSDS Date:08/19/1992

FSC:6850

NIIN:00-281-4033

MSDS Number: BVFKW === Responsible Party ===

Company Name: DOW CORNING CORP Address:3901 SOUTH SAGINAW ROAD

Box:997

City:MIDLAND

State:MI ZIP:48640 Country:US

Info Phone Num:517-496-6000

Emergency Phone Num:

517-496-5900 CAGE:5D028

=== Contractor Identification ===

Company Name: DOW CORNING CORP

Address:3901 S SAGINAW RD

Box:997

City:MIDLAND

State:MI

ZIP:48686-0997 Country:US

Phone:517-496-6000/517-496-6315

CAGE:5D028

Company Name: DOW CORNING CORP

Address:2200 W SALZBURG RD

Box:City:AUBURN

State:MI ZIP:48611 Country:US

Phone:517-496-4388

CAGE:71984

====== Composition/Information on Ingredients ========

Ingred Name:ZINC OXIDE

CAS:1314-13-2

RTECS #:ZH4810000 Fraction by Wt: 69%

Other RE

ACGIH TLV:10 MG/M3 TDUST; 9394 ========== Hazards Identification =========================== LD50 LC50 Mixture:LD50 (ORAL, RAT) IS UNKNOWN. Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO **Explanation of Carcinogenicity:NONE** Effects of Overexposure: EYE AND GASTROINTESTINAL DISCOMFORT Medical Cond Aggravated by Exposure: OVEREXPOSURE TO ANY CHEMICAL MAY RESULT IN ENHANCEMENT OF P RE-EXISTING ADVERSE MEDICAL CONDITIONS AND ALLERGIC REACTIONS. First Aid:GET MEDICAL ATTENTION IF SYMPTOMS PERSIST. SKIN:REMOVE CONTAMINATED CLOTHING. WIPE OFF AND FLUSH SKIN WITH WATER. EYE:FLUSH WITH PLENTY OF WATER. INHALED/ORAL:NO FIRST AID SHOULD BE NEEDED. Flash Point Method:OC Flash Point:>250F,>121C Extinguishing Media: WATER FOG, CA RBON DIOXIDE, DRY CHEMICAL, FOAM Fire Fighting Procedures: AIR SUPPLIED RESPIRATOR OR SELF-CONTAINED BREATHING APPARATUS AND PROTECTIVE CLOTHING SHOULD BE WORN IN FIGHTING FIRES INVOLVING CHEMICALS. Unusual Fire/Explosion Hazard:NONE ======== Accidental Release Measures ============ Spill Release Procedures: SCOOP INTO CONTAINERS. USE ABSORBENT MATERIAL TO TAKE CARE OF ANY OIL-LIKE RESIDUES. Neutralizing Agent: NOT RELEVENT ========= Handling and Storag

C Limits:NONE RECOMMENDED OSHA PEL:15 MG/M3 TDUST

e ===========

Handling and Storage Precautions: STORE IN COOL PLACE. KEEP OUT OF REACH OF CHILDREN.

Other Precautions: WASH THOROUGHLY AFTER HANDLING AND BEFORE SMOKING OR EATING, AVOID INGESTION, DO NOT GET IN EYES.

====== Exposure Controls/Personal Protection ========

Respiratory Protection: NONE SHOULD BE NEEDED.

Ventilation: MECHANICAL (GENERAL)

Protective Gloves: WASHING AT MEALTIME AND END OF SHIFT

Eye Protection:SAFETY GLASSES Other Protective Equipment:SAF

ETY SHOWER AND EYE WASH FOUNTAIN SHOULD

BE LOCATED NEARBY.

Work Hygienic Practices: REMOVE CONTAMINATED CLOTHING AND SHOES AS SOON AS POSSIBLE AND CLEAN BEFORE REUSE.

Supplemental Safety and Health

FORMULA CHANGED. FOR PREVIOUS FORMULATIONS, SEE PNI A, SAME NSN. THESE PRECAUTIONS ARE FOR ROOM TEMPERATURE HANDLING; USE AT ELEVATED TEMPERATURES, OR AEROSOL/SPRAY APPLICATIONS, MAY REQUIRE ADDED PRE CAUTIONS.

========= Physical/Chemical Properties ===========

H CC:T6 NRC/State Lic Num:NOT RELEVENT Vapor Pres: