Product ID:US 9526-D 1,304-176

MSDS Date:11/17/1986

FSC:5835

NIIN:01-182-4855 MSDS Number: BXJXV

=== Responsible Party ===

Company Name: RAYMARK CORP

Address:123 E STIEGEL ST

City:MANHEIM

State:PA ZIP:17545 Country:US

Info Phone Num:717-665-2211

Emergency Phone Num:717-665-2211 Preparer's Name:RONALD L. RAMSE

Υ

**CAGE:8X148** 

=== Contractor Identification ===

Company Name: BF GOODRICH CO AEROSPACE DIV AIRCRAFT WHEEL &BRAKE

Address:WACO ST

Box:340 City:TROY State:OH

ZIP:45373-3835 Country:US

Phone:513-339-3811

CAGE:97153

Company Name: RAYMARK CORP

Address:123 E STIEGEL ST

Box:City:MANHEIM

State:PA

ZIP:17545-1626 Country:US

Phone:717-665-2211

**CAGE:8X148** 

====== Composition/Information on Ingredients ========

Ingred Name: ASBESTOS, CHRYSOTILE

CAS:12001-29-5 RTECS #:CI6478500 Fraction by Wt: 70 - 76%

Other REC Limits: NONE RECOMMENDED

OSHA PEL:0.2 FIBERS/CC

ACGIH TLV:2 FIBERS/CC,A1; 9495

Ingred Name: PHENOLIC RESIN

Fraction by Wt: 24 - 30%

Other REC Limits: NONE RECOMMENDED

========== Hazards Identification ================

LD50 LC50 Mixture:LD50 (ORAL, RAT) IS NOT RELEVANT.

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO

Health Hazards Acute and Chronic:TARGET ORGANS:EYES, SKIN, LUNGS.

**ACUTE- MAY CAU** 

SE EYE & SKIN IRRITATION. INGESTION UNLIKELY.

INHALATION MAY CAUSE RESPIRATORY TRACT IRRITATION. CHRONIC-INHALATION MAY CAUSE ASBESTOSIS & LUNG DISORDER S/CANCER. SMOKING GREATLY INCREASES CANCER RISKS. SYMPTOMS SUCH AS LABORED BREATHING MAY SHOW 15-20 YEARS LATER.

Explanation of Carcinogenicity: CONTAINS A [1332-21-4] WHICH IS LISTED BY NTP AND IARC AND REGULATED BY OSHA AS A CARCINOGEN.

Effects of Overexposure:BREATHING DIFFICULTY, IRRITATION

Medical Cond Aggravated by Exp

osure:PERSONS WITH PRE-EXISTING

RESPIRATORY OR LUNG PROBLEMS SHOULD AVOID BREATHING AIRBORNE DUST FROM THIS PRODUCT.

First Aid:SEEK MEDICAL ATTENTION IF SYMPTOMS DEVELOP. IN CASE OF EYE IRRITATION GENTLY RINSE WITH WATER FOR 15 MINUTES WHILE KEEPING EYELIDS OPEN. DO NOT RUB EYES. SKIN: WASH FREQUENTLY WITH SOAP AND WATER. INH ALATION: REMOVE TO FRESH AIR. INGESTION: UNLIKELY.

	======= Fire F
ighting Measures	

Flash Point: NON-FLAMMABLE

Extinguishing Media:WATER SPRAY, CARBON DIOXIDE, FOAM OR DRY CHEMICAL FOR SURROUNDING FIRE. USE WATER SPRAY TO COOL FIRE EXPOSED CONTAINERS.

Fire Fighting Procedures:AVOID BREATHING FUMES. WEAR PROTECTIVE CLOTHING AND NIOSH-APPROVED SELF-CONTAINED BREATHING APPARATUS OPERATED IN THE POSITIVE PRESSURE MODE.

Unusual Fire/Explosion Hazard:TOXIC GASES AND ASBESTOS FIBERS MAY BE RELEASED.

====== Accid

antal Ralassa N	Maggurag	 

Spill Release Procedures:WEAR PROTECTIVE EQUIPMENTS. TREAT DUST AS FREE ASBESTOS. DO NOT DRY SWEEP OR USE COMPRESSED AIR. WET METHOD SHOULD BE USED FOR EXTRACTION OF DUST AND DEBRIS. HIGH EFFICIENCY PARTICULATE APPARATUS (HEP A) VACUUMS SHOULD BE USED. AVOID WATER-POLLUTION.

Neutralizing Agent: NOT RELEVANT

=========== Handling and Storage ================

Handling and Storage Precautions:STORE IN CLOSED BOXES THAT AR E CLEARLY

LABELED WITH ASBESTOS WARNINGS. STORE IN ACCORDANCE WITH 29 CFR 1910.1001.

Other Precautions:AFTER HANDLING, DO NOT SMOKE, EAT OR APPLY COSMETIC UNTIL THOROUGHLY WASHED WITH WARM WATER AND SOAP. DO NOT RAISE DUST. KEEP OUT OF REACH OF CHILDREN.

===== Exposure Controls/Personal Protection ========

Respiratory Protection: USE NIOSH APPROVED HIGH EFFICIENCY FIBERS/FUMES RESPIRATOR WHEN AIRBORNE FIBER CONCENTRATIONS EXCEED THE PEL. Ventilation: LOCAL/GENE

RAL TO MAINTAIN PEL/TLV.

Protective Gloves:LEATHER, COTTON OR RUBBER IF FRIABLE

Eye Protection: DUST-RESISTANT SAFETY GOGGLES IF FRIABLE

Other Protective Equipment: EYE WASH STATION AND SAFETY SHOWER, WORK CLOTHING AND APRON AS REQUIRED. DO NOT WEAR CONTACT LENSES

Work Hygienic Practices:DON'T TAKE PROTECTIVE GEAR/CLOTHING HOME IF EXPOSED TO DUST. DON'T SHAKE. DON'T EAT IN AREA WHERE ASBESTOS/DUST PRESENT.

Supplemental Safety and Health

HCC:T7

NRC/State Lic Num:NOT RELEVANT Melt/Freeze Pt:M.P/F.P Text:NOT KNOWN

Spec Gravity:0.6

Viscosity: NOT RELEVANT

Evaporation Rate & Evaporation Relevant

Appearance and Odor: TAN FELT WITH PHENOLIC ODOR

======== Stability and Reactivity Data ==========

Stability Indicator/Materials to Avoid:YES

NONE

Stability Condition to Avoid: RAISING DUST

Hazardous Decomposition Products:TOXIC GASES AND ASBESTOS FIBERS MAY BE RELEASED.

\_\_\_\_\_

Disposal Considerations ==========

Waste Disposal Methods:APPROVED LANDFILL. WASTE SHOULD BE CONTAINED IN IMPERMEABLE BAGS, LABELED AND DISPOSED IN ACCORDANCE WITH ALL LOCAL, STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and

disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.