View NSN Online: https://aerobasegroup.de/nsn/6665-00-401-8500

MINE SAFETY APPLIANCES CO -- CALIBRATING GAS,2% METHANE IN AIR,P/N'S

96329,454380,456236 -- 6665-00-401-8500

Product ID:CALIBRATING GAS,2% METHANE IN AIR,P/N'S 96329,454380,456236

MSDS Date:03/04/1993

FSC:6665

NIIN:00-401-8500

Kit Part:Y

MSDS Number: BYGYH === Responsible Party ===

Company Name: MINE SAFETY APPLIANCES CO

Box:426

City:PITTSBURGH

State:PA ZIP:15230 Country:US

Info Phone Num:412-967-3000

Emergency Phone Num:412-967-3000

Preparer's Name: NONE

CAGE:40912

=== Contractor Identification ===

Company Name: APPLIANCE PARTS DISTRIBUTOR

Box:City:CROYDON

State:PA

ZIP:79020-5406 Country:US

Phone:215-785-6282

CAGE:2P336

Company Name: MINE SAFETY APPLIANCE (REPLACED BY CAGE 55799)

Address: 201 N BRADDOCK AVENUE

Box:426

City:PITTSBURGH

State:PA ZIP:15230 Country:US

Phone:412-967-3000

CAGE:40912

====== Composition/Information on Ingredients ======

Ingred Name:METHANE CAS:74-82-8 RTECS #:PA1490000 Fraction by Wt: 2.0% Other REC Limits:NONE RECOMMENDED ACGIH TLV:ASPHYXIANT; 9495
Ingred Name:AIR, COMPRESSED CAS:25635-88-5 Fraction by Wt: 98.0% Other REC Limits:NONE RECOMMENDED
========== Hazards Identification ===========
LD50 LC50 Mixture:NONE SPECIFIED BY MANUFACTURER. Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic :METHANE IS A SIMPLE ASPHYXIANT, ACGIH 1992-93.
Explanation of Carcinogenicity:NONE Effects of Overexposure:NONE KNOWN FOR 2% METHANE IN AIR. Medical Cond Aggravated by Exposure:NO INFORMATION.
======================================
First Aid:NONE.
======================================
Flash Point:NON-FLAMMABLE Extinguishing Media:THIS CALIBRATION GAS MIXTURE IS NOT FLAMMABLE. USE MEDIA APPROPRIATE FOR SURROUNDING FIRE.
Fir e Fighting Procedures:COOL FIRE EXPOSED CYLINDERS. Unusual Fire/Explosion Hazard:GAS UNDER PRESSURE, 115 PSIG AT 70F. DO NOT EXCEED 120F.
======== Accidental Release Measures ==========
Spill Release Procedures:VENTILATE AREA. Neutralizing Agent:NONE
======================================
Handling and Storage Precautions:STORE IN A COOL, DRY, WELL-VENTILATED AREA. DO NOT EXCEED TEMPERATURE OF 120F. Other Precautions:DO NOT BREATH GAS.

====== Exposure Controls/Personal Protection ========
Respiratory Protection:DUE TO THE LIMITED AMOUNT OF GAS IN THE CYLINDER, AND THE LOW RELEASE RATE EMPLOYED IN INSTRUMENT CALIBRATION, RESPIRATORY PROTECTION IS NOT INDICATED UNDER CONDITIONS OF INTENDED USE. Ventilation:MECHANICAL VENTILATION IS SUITABLE. Protective Gloves:NOT REQUIRED. Eye Protection:NOT REQUIRED. Other Protective Equipment:NONE SPECIFIED BY MANUFACTURER. Work Hygienic Practices:AVOID BREATHING GA S. USE IN WILL-VENTILATED AREAS. FOLLOW PROCEDURE IN MSA MANUAL FOR THE INSTRUMENT UNDER CALIBRATION. Supplemental Safety and Health KEY1:G3.
======== Physical/Chemical Properties =========
HCC:G3 Vapor Density: